

# **Aviation Investigation Final Report**

Location: GORMAN, California Accident Number: LAX93LA089

Date & Time: January 2, 1993, 15:30 Local Registration: N6790V

Aircraft: MOONEY M20C Aircraft Damage: Substantial

**Defining Event:** 2 Minor

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

THE AIRPLANE WAS IN CRUISE FLIGHT AT ABOUT 9,500 FEET MEAN SEA LEVEL WHEN THE ENGINE HAD A TOTAL LOSS OF POWER. THE PILOT ENTERED A POWER OFF FORCED LANDING AND PERFORMED EMERGENCY PROCEDURES ATTEMPTING TO RE START THE ENGINE. HE COULD NOT GET THE ENGINE STARTED. THE PILOT LANDED THE AIRPLANE ON A TWO LANE ROAD ADJACENT TO AN INTERSTATE HIGHWAY. THE PILOT ENCOUNTERED AN UNFAVORABLE LEFT CROSSWIND WHICH CAUSED THE AIRPLANE TO DRIFT TO THE RIGHT SIDE OF THE ROAD. DURING LANDING ROLL THE AIRPLANE'S RIGHT WING CONTACTED METAL FENCE POSTS AND SPUN THE AIRPLANE INTO AN EMBANKMENT. DURING AN FAA SUPERVISED ENGINE RUN FUEL WAS NOTED AS LEAKING FROM THE CARBURETOR. AN EXAMINATION OF THE CARBURETOR REVEALED THAT THE INLET FUEL FITTING HAD GALLED OR CROSSFED THREADS. METAL SHAVINGS FROM THE THREADS BYPASSED THE FUEL SCREEN AND TRAVELED DIRECTLY INTO THE FUEL FLOAT VALVE WITHOUT GOING THROUGH THE FILTER SCREEN. THIS CAUSED THE FLOAT VALVE TO BECOME INOPERATIVE, WHICH RESULTED IN FLOODING THE ENGINE WITH FUEL CAUSING A TOTAL LOSS OF ENGINE POWER. THE AIRPLANE'S ENGINE HAD A TOTAL TIME OF 7 HOURS SINCE OVERHAUL.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

1) THE CARBURETOR INLET FUEL LINE BEING IMPROPERLY INSTALLED BY MAINTENANCE
PERSONNEL WHICH ALLOWED THE CARBURETOR TO BECOME CONTAMINATED WITH
METAL PARTICLES, AND 2) THE CARBURETOR FLOAT VALVE BEING JAMMED BY METAL
PARTICLES WHICH ALLOWED EXCESSIVE FUEL TO BE INTRODUCED INTO THE CARBURETOR
RESULTING IN FLOODING AND THE TOTAL LOSS OF ENGINE POWER. A FACTOR IN THIS

ACCIDENT WAS THE PILOT ENCOUNTERING AN UNFAVORABLE CROSSWIND DURING FINAL APPROACH WHICH LED TO THE AIRPLANE'S WING COLLIDING WITH FENCE POSTS DURING LANDING ROLL.

### **Findings**

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: CRUISE - NORMAL

#### **Findings**

1. (C) FUEL SYSTEM, LINE FITTING - CROSS/STRIPPED THREADED

2. (C) MAINTENANCE, INSTALLATION - IMPROPER - OTHER MAINTENANCE PERSONNEL

3. (C) FUEL SYSTEM, CARBURETOR - CONTAMINATION

4. (C) FUEL SYSTEM, CARBURETOR FLOAT - JAMMED

5. (C) FLUID, FUEL - PRESSURE EXCESSIVE

-----

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

-----

Occurrence #3: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING - ROLL

#### **Findings**

6. (F) WEATHER CONDITION - UNFAVORABLE WIND

7. OBJECT - FENCE POST

Page 2 of 5 LAX93LA089

## **Factual Information**

### **Pilot Information**

Certificate:	Private	Age:	42,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	September 16, 1992
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	564 hours (Total, all aircraft), 385 hours (Total, this make and model), 484 hours (Pilot In Command, all aircraft), 13 hours (Last 90 days, all aircraft), 7 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

## **Aircraft and Owner/Operator Information**

Aircraft Make:	MOONEY	Registration:	N6790V
Model/Series:	M20C M20C	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	700084
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	December 21, 1992 Annual	Certified Max Gross Wt.:	2975 lbs
Time Since Last Inspection:	12 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3091 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	O-360-A1D
Registered Owner:	DANIEL G. OLIVIER	Rated Power:	180 Horsepower
Operator:	DANIEL G. OLIVIER	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 LAX93LA089

### **Meteorological Information and Flight Plan**

Conditions at Accident Site: Visual (VMC)  Observation Facility, Elevation:  Observation Time:  Direction from Accident Site:  Lowest Cloud Condition:  Clear  Visibility  20 miles  Lowest Ceiling:  None  Visibility (RVR):  Wind Speed/Gusts:  20 knots / 25 knots  Turbulence Type  /	
Observation Time:  Lowest Cloud Condition:  Clear  Visibility  20 miles  Lowest Ceiling:  None  Visibility (RVR):	
Lowest Cloud Condition:       Clear       Visibility       20 miles         Lowest Ceiling:       None       Visibility (RVR):	
Lowest Ceiling: None Visibility (RVR):	
Wind Speed/Guets: 20 knots / 25 knots Turbulence Type /	
Forecast/Actual:	
Wind Direction: 300° Turbulence Severity / Forecast/Actual:	
Altimeter Setting: Temperature/Dew Point:	
Precipitation and Obscuration: No Obscuration; No Precipitation	
Departure Point: PETALUMA , CA (069 ) Type of Flight Plan Filed: None	
Destination: EL MONTE , CA (EMT ) Type of Clearance: None	
<b>Departure Time:</b> 13:30 Local <b>Type of Airspace:</b> Class G	

## **Airport Information**

Airport:		Runway Surface Type:	
Airport Elevation:		<b>Runway Surface Condition:</b>	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

## **Wreckage and Impact Information**

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	1 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Minor	Latitude, Longitude:	34.859066,-118.870445(est)

Page 4 of 5 LAX93LA089

#### **Administrative Information**

Investigator In Charge (IIC): Childress, Richard

Additional Participating Persons:

Original Publish Date: November 15, 1993

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=27903

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 LAX93LA089