

Aviation Investigation Final Report

Location: PRESCOTT, Arizona Accident Number: LAX93LA135

Date & Time: February 23, 1993, 12:30 Local Registration: N9HD

Aircraft: Downer Aircraft Industries KR-1 Aircraft Damage: Destroyed

Defining Event: 1 Serious

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE EXPERIMENTAL HOMEBUILT HAD ONLY BEEN OPERATED ABOUT 56 HOURS IN THE LAST 12 YEARS. WITH THE LAST FLIGHT PRIOR TO THE ACCIDENT LISTED IN THE AIRCRAFT LOG BOOK AS JUNE 16, 1992. THE PILOT MADE NO STATEMENT REGARDING THE ACCIDENT CIRCUMSTANCES. GROUND WITNESSES REPORTED HEARING AND OBSERVING THE AIRCRAFT DESCEND INTO A RESIDENTIAL AREA WITHOUT ANY APPARENT ENGINE POWER. FAA AIRWORTHINESS INSPECTORS EXAMINED THE AIRCRAFT AND REPORTED FINDING MANY DISCREPANCIES IN THE AIRCRAFT SYSTEM DESIGNS AND INSTALLATIONS. THE FUEL SYSTEM CONSISTED OF A RUBBERMAID FIVE GALLON CONTAINER CONNECTED TO THE ENGINE WITH PLASTIC TUBING AND OPERATED BY A HAND WOBBLE PUMP. THE CARBURETOR HEAT SYSTEM CONSISTED OF PVC PLUMBING PIPE HELD TOGETHER AND SECURED TO BOTH THE ENGINE EXHAUST SYSTEM AND THE CARBURETOR WITH RTV SEALANT. THE FAA INSPECTORS REPORTED THAT THE EXAMINATION OF THE REVMASTER VW ENGINE ITSELF REVEALED NO EVIDENCE OF A MECHANICAL MALFUNCTION. REVIEW OF FAA RECORDS REVEALED THAT THE PILOT'S MEDICAL HAD EXPIRED. THE PILOT HAD HELD HIS PRIVATE CERTIFICATE FOR 40 YEARS AND HAD FLOWN 290 HOURS IN THAT TIME. THE AVAILABLE PILOT AND AIRCRAFT RECORDS DISCLOSED THAT THE PILOT HAD NOT FLOWN IN THE LAST SEVEN MONTHS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE TOTAL LOSS OF ENGINE POWER FOR UNDETERMINED REASONS. A FACTOR IN THE ACCIDENT WAS THE LACK OF A SUITABLE LANDING AREA AT THE TIME OF THE POWER INTERRUPTION.

Findings

Occurrence #1: LOSS OF ENGINE POWER

Phase of Operation: CRUISE

Findings

1. (C) REASON FOR OCCURRENCE UNDETERMINED

- 2. FUEL SYSTEM IMPROPER
- 3. EXHAUST SYSTEM IMPROPER
- 4. MAINTENANCE, INSTALLATION INADEQUATE MANUFACTURER
- 5. INSUFFICIENT STANDARDS/REQUIREMENTS MANUFACTURER

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - EMERGENCY

Findings

6. (F) TERRAIN CONDITION - RESIDENTIAL AREA

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - EMERGENCY

Page 2 of 5 LAX93LA135

Factual Information

Pilot Information

Certificate:	Private	Age:	70,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Expired	Last FAA Medical Exam:	January 7, 1991
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	290 hours (Total, all aircraft), 15 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	Downer Aircraft Industries	Registration:	N9HD
Model/Series:	KR-1 KR-1	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	001
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	March 24, 1992 Annual	Certified Max Gross Wt.:	750 lbs
Time Since Last Inspection:	6 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	56 Hrs	Engine Manufacturer:	Revmaster
ELT:		Engine Model/Series:	2100 CC
Registered Owner:	ROBERT O. WOODWARD	Rated Power:	80 Horsepower
Operator:	ROBERT O. WOODWARD	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 LAX93LA135

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PRC,5042 ft msl	Distance from Accident Site:	10 Nautical Miles
Observation Time:	13:52 Local	Direction from Accident Site:	1°
Lowest Cloud Condition:	25000 ft AGL	Visibility	65 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	220°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	11°C / -3°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	(PRC)	Type of Flight Plan Filed:	None
Destination:	(PRC)	Type of Clearance:	None
Departure Time:	10:30 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Destroyed
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	34.619884,-112.41957(est)

Page 4 of 5 LAX93LA135

Administrative Information

Investigator In Charge (IIC): Rich, Jeff

Additional Participating Persons:

Original Publish Date: February 10, 1994

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=27936

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 LAX93LA135