



# **Aviation Investigation Final Report**

Location: WAKEFIELD, Virginia Accident Number: IAD97LA013

Date & Time: October 26, 1996, 16:00 Local Registration: N83N

Aircraft: Cessna 140 Aircraft Damage: Substantial

**Defining Event:** 2 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot made an approach to the airport with a passenger aboard. The wind was calm, and the pilot proceeded with a standard traffic pattern. When the airplane touched down, main tire(s) locked, and the airplane nosed over. The pilot stated that he was in a perfect configuration for a three point landing, and there was no warning or indication of a problem until the accident occurred. Examination of the airplane revealed that the left master cylinder tension spring, which was designed to prevent the parking brake lock from engaging, was missing.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: uncommanded operation of the parking brake, due to a missing tension spring, which resulted in locked brakes and subsequent nose over of the airplane during landing.

#### **Findings**

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION

Phase of Operation: LANDING - FLARE/TOUCHDOWN

#### **Findings**

1. (C) LANDING GEAR, PARKING BRAKE - MALFUNCTION

2. (C) MISCELLANEOUS, BOLT/NUT/FASTENER/CLAMP/SPRING - MISSING

3. (C) LANDING GEAR, NORMAL BRAKE SYSTEM - LOCKED

-----

Occurrence #2: NOSE OVER Phase of Operation: LANDING

Page 2 of 6 IAD97LA013

#### **Factual Information**

On October 26, 1996, about 1600 eastern daylight time, a Cessna 140, N83N, sustained substantial damage when it nosed over during landing at the Wakefield Municipal Airport (AKQ), Wakefield, Virginia. The certificated private pilot and passenger were not injured. Visual meteorological conditions prevailed for the flight, and no flight plan had been filed for the personal flight conducted under 14 CFR Part 91.

In a written statement, the pilot said he was on approach to runway 2 at AKQ. He further stated:

"...The winds were basically calm, as could be observed from the flags next to the airport office. I then proceeded with a standard traffic pattern...I was in a perfect configuration for a 3 point landing, but as I touched down, the airplane front tires violently and abruptly locked up. There was no warning or indication of a problem, but the airplane within seconds flipped forward on its back."

The airplane was examined by a Federal Aviation Administration Inspector. The examination revealed that left master cylinder tension spring which is designed to prevent the parking brake lock from engaging, was missing.

The Cessna 140 Airplane Operations Manuel stated:

"The parking brake control is operated in conjunction with the toe brake...In setting the parking brake, first press the toe brake to the desired brake pressure then pull the control out to engage the locking lever and release the toe brake pressure...."

The pilot did recall depressing the toe brakes during the cross country flight to AKQ.

Page 3 of 6 IAD97LA013

### **Pilot Information**

Certificate:	Private	Age:	50,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	April 26, 1996
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	298 hours (Total, all aircraft), 85 hours (Total, this make and model), 205 hours (Pilot In Command, all aircraft), 40 hours (Last 90 days, all aircraft), 10 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N83N
Model/Series:	140 140	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	11607
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	August 19, 1996 Annual	Certified Max Gross Wt.:	1450 lbs
Time Since Last Inspection:	14 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3500 Hrs	Engine Manufacturer:	Continental
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	C-85-12F
Registered Owner:	RAYMOND L. BOSSOLLA	Rated Power:	85 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 4 of 6 IAD97LA013

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Unknown	Visibility	10 miles
Lowest Ceiling:	Broken / 5500 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	19°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	BURGAW, NC (AKQ)	Type of Flight Plan Filed:	None
Destination:	(AKQ)	Type of Clearance:	None
Departure Time:	17:30 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	WAKFIELD MUNICIPAL AKQ	Runway Surface Type:	Asphalt
Airport Elevation:	113 ft msl	Runway Surface Condition:	Dry
Runway Used:	2	IFR Approach:	None
Runway Length/Width:	4000 ft / 75 ft	VFR Approach/Landing:	Full stop;Traffic pattern

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	36.959011,-76.979255(est)

Page 5 of 6 IAD97LA013

#### **Administrative Information**

Investigator In Charge (IIC): Moffett, Jodi

Additional Participating Persons:

Original Publish Date: March 31, 1998

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=28157

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 IAD97LA013