



# **Aviation Investigation Final Report**

Location: LEBANON, New Hampshire Accident Number: IAD97LA075

Date & Time: May 14, 1997, 12:40 Local Registration: N4992V

Aircraft: Cessna 180J Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

According to the pilot, during takeoff climb, at about 400 feet above ground level, the engine lost power. He headed for a highway to make an emergency landing. The pilot stated as he got closer, he realized there was a lot of traffic, so he decided to land on the embankment off the right side of the highway. The airplane touched down, continued for about 100 feet, nosed over onto the highway. Examination of the airplane, which included a test run of the engine, did not disclose evidence of mechanical malfunction.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The loss of engine power for undetermined reasons.

#### **Findings**

Occurrence #1: LOSS OF ENGINE POWER
Phase of Operation: TAKEOFF - INITIAL CLIMB

**Findings** 

1. REASON FOR OCCURRENCE UNDETERMINED

-----

Occurrence #2: FORCED LANDING

Phase of Operation: EMERGENCY DESCENT/LANDING

-----

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: EMERGENCY LANDING

Page 2 of 6 IAD97LA075

#### **Factual Information**

On May 14, 1997, at about 1240 eastern daylight time, N4992V, a Cessna 180J, owned and operated by the private pilot, sustained substantial damage shortly after takeoff when the pilot reported a loss of engine power and crashed on Interstate 89, about one-half mile east of the Lebanon Airport, Lebanon, New Hampshire. The pilot and sole occupant was not injured. Visual Meteorological conditions existed and no flight plan was filed. The flight was conducted under the provisions of 14 CFR Part 91.

According to the pilot, he was going to Lake Sunapee to practice water landings. At 400 feet after takeoff, the engine went silent. The pilot stated he headed for Interstate 89 to make an emergency landing. As he got closer, he noticed a lot of traffic. The pilot landed the airplane on an embankment off the right side of the highway. The airplane touched down and continued for about 100 feet on the embankment before the airplane flipped over onto the highway. The aircraft had not been flown for 9 days prior to the accident.

An inspection/examination of the engine was conducted at Teledyne Continental Motors on December 11, 1997. Present during the examination was the National Transportation Safety Board (NTSB), the Federal Aviation Administration (FAA), and the Continental Motors. All valve covers, throttle and intake pipes were returned loose. All engine mounts were broken and the number three intake pipe was damaged from impact. The oil sump was dented upward however there were no punctures observed. One rear induction elbow was damaged from the impact. The crankshaft propeller flange was visually examined and no cracks were observed.

In order to do a test run, the engine mounts and loose parts were mounted back on the engine and the induction elbow was replaced with a slave pipe. Exhaust stacks, temperature probes, and an adapter for the propeller governor pad were installed for testing. Engine startup was immediate and the engine ran smoothly. After the warm up, the engine was run to 2100 RPM for a magneto check. Both magnetos had a 50 RPM drop. The engine was then run to full throttle for 10 minutes. The engine produced the rated RPM and horsepower. The engine was then run at cruise power for an additional 15 minutes and no discrepancies were found.

Page 3 of 6 IAD97LA075

### **Pilot Information**

Certificate:	Private	Age:	60,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	April 15, 1997
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1641 hours (Total, all aircraft), 192 hours (Total, this make and model), 1475 hours (Pilot In Command, all aircraft), 4 hours (Last 30 days, all aircraft)		

## **Aircraft and Owner/Operator Information**

Aircraft Make:	Cessna	Registration:	N4992V
Model/Series:	180J 180J	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18052334
Landing Gear Type:	Amphibian	Seats:	2
Date/Type of Last Inspection:	February 21, 1997 Annual	Certified Max Gross Wt.:	3100 lbs
Time Since Last Inspection:	4 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1241 Hrs	Engine Manufacturer:	Continental
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	IO550-D
Registered Owner:	WILLIAM N. PEABODY	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 4 of 6 IAD97LA075

### Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	LEB ,600 ft msl	Distance from Accident Site:	1 Nautical Miles
Observation Time:	12:45 Local	Direction from Accident Site:	360°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	20 miles
Lowest Ceiling:	Broken / 5000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	300°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	17°C / 1°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:	NEW LONDON , NH	Type of Clearance:	None
Departure Time:	12:40 Local	Type of Airspace:	Class D

## **Airport Information**

Airport:	LEBANON MUNICIPAL LEB	Runway Surface Type:	Asphalt
Airport Elevation:	600 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	36	IFR Approach:	None
Runway Length/Width:	5200 ft / 150 ft	VFR Approach/Landing:	Forced landing

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Page 5 of 6 IAD97LA075

#### **Administrative Information**

Investigator In Charge (IIC): Wilson, Butch

Additional Participating Persons: CHARLES REILING; DANIELLE PINNERI;

Original Publish Date: June 21, 2000

Last Revision Date: Investigation Class: Class

Note: Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=28195

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 IAD97LA075