



Aviation Investigation Final Report

Location: IMPERIAL, California Accident Number: LAX93LA163

Date & Time: April 3, 1993, 15:00 Local Registration: N34205

Aircraft: CESSNA 177RG Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

DURING THE LANDING ROLL-OUT THE AIRPLANE ENCOUNTERED A DUST DEVIL WHICH LIFTED AND TURNED THE AIRPLANE TO THE LEFT. THE PILOT APPLIED FULL POWER AND BEGAN A TAKEOFF. SHORTLY AFTER LIFT-OFF THE AIRPLANE'S LEFT LANDING GEAR STRUCK THE LEADING EDGE OF A PARKED AIRPLANE. THE PILOT RETURNED TO THE AIRPORT AND INTENTIONALLY LANDED ADJACENT TO THE RUNWAY WITH ITS LANDING GEARS RETRACTED. A GROUND WITNESS CONFIRMED THE DUST DEVIL PHENOMENA.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE FLIGHT'S ENCOUNTER WITH A DUST DEVIL.

Findings

Occurrence #1: IN FLIGHT ENCOUNTER WITH WEATHER

Phase of Operation: LANDING - ROLL

Findings

1. (C) WEATHER CONDITION - UNFAVORABLE WIND

Occurrence #2: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: LANDING - ABORTED

Findings

2. OBJECT - AIRCRAFT PARKED/STANDING

Occurrence #3: GEAR NOT EXTENDED

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

3. WHEELS UP LANDING - INTENTIONAL - PILOT IN COMMAND

Page 2 of 6 LAX93LA163

Factual Information

On April 3, 1993, at about 1500 hours Pacific standard time, a Cessna 177RG, N34205, executed an emergency landing adjacent to Imperial County Airport, Imperial, California, after colliding with a parked airplane. The pilot was completing a local visual flight rules personal flight. The airplane, registered to and operated by the pilot, sustained substantial damage. Neither the certificated private pilot nor his passenger was injured. Visual meteorological conditions prevailed.

The pilot told Mr. Nick Weber, Aviation Safety Inspector, Federal Aviation Administration (FAA), San Diego [California] Flight Standards District Office, that prior to landing the surface winds were calm. The touch down was normal, but during the landing roll out the airplane made an abrupt swerve to the left and exited the 100 foot wide runway.

After exiting the runway the airplane was heading toward a parked Cessna 175, N7378M. The pilot applied power and began a go-around. The airplane lifted off, but its left wheel struck the parked Cessna's leading edge wing and separated from the airplane.

The pilot executed a fly by over the runway and elected to land, gear up, on the dirt area adjacent to the runway.

A ground witness confirmed that the winds were calm as the airplane touched down. A "dust devil," however, developed as the airplane was rolling out. After encountering the dust devil, the airplane lifted off the runway and turned to the left.

Pilot Information

Certificate:	Private	Age:	50,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	January 29, 1992
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	936 hours (Total, all aircraft), 600 hours (Total, this make and model), 900 hours (Pilot In Command, all aircraft), 18 hours (Last 90 days, all aircraft), 18 hours (Last 30 days, all aircraft)		

Page 3 of 6 LAX93LA163

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N34205
Model/Series:	177RG 177RG	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	177RG0982
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	2800 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:		Engine Model/Series:	10-360
Registered Owner:	MCDONALD, ARNOLD C.	Rated Power:	180 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site: Visual (VMC) Condition of Light: Day Observation Facility, Elevation: Distance from Accident Site: Observation Time: Direction from Accident Site: Lowest Cloud Condition: Scattered / 3000 ft AGL Visibility 30 miles Lowest Ceiling: None Visibility (RVR): Wind Speed/Gusts: 4 knots / Turbulence Type Forecast/Actual: / Wind Direction: 30° Turbulence Severity Forecast/Actual: / Altimeter Setting: Temperature/Dew Point: 30°C	
Observation Time: Lowest Cloud Condition: Scattered / 3000 ft AGL Visibility 30 miles Lowest Ceiling: None Visibility (RVR): Turbulence Type Forecast/Actual: Wind Direction: 30° Turbulence Severity Forecast/Actual: Temperature/Dew Point: 30°C	
Lowest Cloud Condition: Scattered / 3000 ft AGL Visibility 30 miles Lowest Ceiling: None Visibility (RVR): Wind Speed/Gusts: 4 knots / Turbulence Type Forecast/Actual: / Wind Direction: 30° Turbulence Severity Forecast/Actual: / Altimeter Setting: Temperature/Dew Point: 30°C	
Lowest Ceiling: None Visibility (RVR): Wind Speed/Gusts: 4 knots / Turbulence Type Forecast/Actual: Wind Direction: 30° Turbulence Severity Forecast/Actual: Altimeter Setting: Temperature/Dew Point: 30°C	
Wind Speed/Gusts: 4 knots / Turbulence Type Forecast/Actual: Wind Direction: 30° Turbulence Severity Forecast/Actual: Altimeter Setting: Temperature/Dew Point: 30°C	
Wind Direction: 30° Turbulence Severity Forecast/Actual: Altimeter Setting: Temperature/Dew Point: 30°C	
Forecast/Actual: Altimeter Setting: Temperature/Dew Point: 30°C	
Precipitation and Obscuration: No Obscuration; No Precipitation	
Departure Point: (IPL) Type of Flight Plan Filed: None	
Destination: (IPL) Type of Clearance: None	
Departure Time: 10:05 Local Type of Airspace: Class D;Class E	

Page 4 of 6 LAX93LA163

Airport Information

Airport:	IMPERIAL COUNTY AIRPORT IPL	Runway Surface Type:	Asphalt
Airport Elevation:	-56 ft msl	Runway Surface Condition:	Dry
Runway Used:	14	IFR Approach:	None
Runway Length/Width:	5304 ft / 100 ft	VFR Approach/Landing:	Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	32.859931,-115.650115(est)

Page 5 of 6 LAX93LA163

Administrative Information

Investigator In Charge (IIC):	Llorente, A.	
Additional Participating Persons:	NICK F WEBER; SAN DIEGO , CA	
Original Publish Date:	June 30, 1994	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=28361	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 LAX93LA163