



Aviation Investigation Final Report

Location:	HEMET, California	Accident Number:	LAX96LA022
Date & Time:	October 26, 1995, 12:30 Local	Registration:	N8649V
Aircraft:	BELLANCA 7GCBC	Aircraft Damage:	Destroyed
Defining Event:		Injuries:	1 Serious, 1 Minor
Flight Conducted Under:	Part 91: General aviation - Other work use		

Analysis

THE PILOT ATTEMPTED TO DEMONSTRATE HIS SKILL AT PERFORMING A SHORT FIELD LANDING DURING A PREEMPLOYMENT EVALUATION FLIGHT TO BECOME A GLIDER TOW PILOT. ON SHORT FINAL APPROACH, THE PILOT DESCENDED TO BETWEEN 10 AND 15 FEET ABOVE GROUND LEVEL, 200 FEET SHORT OF THE THRESHOLD, AND THE AIRCRAFT STALLED. THE WIND WAS CALM.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the pilot's failure to maintain adequate airspeed and the inadvertent stall while performing a short field landing.

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT
Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

Findings

1. (C) AIRSPEED - NOT MAINTAINED - PILOT IN COMMAND
 2. (C) STALL/MUSH - INADVERTENT - PILOT IN COMMAND
-

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER
Phase of Operation: DESCENT - UNCONTROLLED

Findings

3. TERRAIN CONDITION - ROUGH/UNEVEN

Factual Information

On October 26, 1995, around 1230 hours Pacific daylight time, a Bellanca 7GCBC, N8649V, collided with terrain on short final approach to the Hemet-Ryan Airport, Hemet, California. The airplane was destroyed, and the certificated commercial pilot received minor injuries. The passenger received serious injuries. At the time of the accident the pilot was demonstrating his airman skills to the rear seated glider flight instructor (CFI) for the purpose of acquiring employment towing gliders. Visual meteorological conditions prevailed, and no flight plan was filed. The flight originated from Hemet around 1215.

The CFI reported that during the preemployment evaluation flight he asked the pilot-in-command to demonstrate his skill at performing a short field landing. The airplane's engine was operating normally, and the wind was light and variable. The pilot's initial approach appeared satisfactory; however, on short final approach the pilot allowed the airplane to become low and slow. The CFI stated that there was ample time for the pilot to take corrective action.

Between 10 and 15 feet above ground level, the pilot suddenly stalled the airplane, lost control, and crashed into a rough field about 200 feet short of the threshold. The CFI further stated that there was insufficient time for him to have acquired control of the airplane in order to avert the accident.

On November 1, 1995, the pilot reported to the National Transportation Safety Board that during the accident flight his approach speed was initially 65 knots. He was trying to make a "low energy" landing. Although the wind was calm he may have encountered a shear, and then the airplane stalled. There were no reported mechanical malfunctions with the airplane.

Pilot Information

Certificate:	Commercial	Age:	45, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	April 14, 1995
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	399 hours (Total, all aircraft), 105 hours (Total, this make and model), 344 hours (Pilot In Command, all aircraft), 268 hours (Last 90 days, all aircraft), 98 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BELLANCA	Registration:	N8649V
Model/Series:	7GCBC 7GCBC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Aerobatic	Serial Number:	819-75
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	March 21, 1995 Annual	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:	71 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3120 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	O-320-A2B
Registered Owner:	LARRY HANSEN	Rated Power:	150 Horsepower
Operator:	AMERICAN VALET AIR	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	25 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	27°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	, CA (HMT)	Type of Flight Plan Filed:	None
Destination:	(HMT)	Type of Clearance:	None
Departure Time:	12:15 Local	Type of Airspace:	Class G

Airport Information

Airport:	HEMET-RYAN HMT	Runway Surface Type:	Asphalt
Airport Elevation:	1512 ft msl	Runway Surface Condition:	Dry
Runway Used:	22	IFR Approach:	None
Runway Length/Width:	2045 ft / 20 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Destroyed
Passenger Injuries:	1 Serious	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious, 1 Minor	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	Pollack, Wayne
Additional Participating Persons:	ERIC JACKSON; RIVERSIDE , CA
Original Publish Date:	January 29, 1996
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=29318

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).