



# Aviation Investigation Final Report

---

<b>Location:</b>	GROVELAND, California	<b>Accident Number:</b>	LAX96LA152
<b>Date &amp; Time:</b>	April 2, 1996, 10:58 Local	<b>Registration:</b>	N59LP
<b>Aircraft:</b>	POWELL                      GLASAIR	<b>Aircraft Damage:</b>	Destroyed
<b>Defining Event:</b>		<b>Injuries:</b>	1 Fatal
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

---

## Analysis

The pilot (part owner of the aircraft) held an A&P certificate & had completed a condition/annual inspection of the aircraft before the flight. The aircraft co-owner stated there was a problem with the throttle cable, & the pilot was going to order a new one, but had not yet done so. Witnesses said the aircraft departed straight out after takeoff. About 4 minutes later, it entered a downwind to the pattern, low & very close to the runway. The witnesses estimated the aircraft's altitude was between 200 and 300 feet agl. At first, some witnesses thought the pilot was going to make a downwind landing on the runway. The witnesses said the aircraft made a tight turn from downwind to base. During the base-to-final turn, the right wing dropped, and the aircraft entered a nose-down descent and crashed. The witnesses heard the engine running before impact, but they described the sound as 'not full power.' An examination of the engine & controls revealed that a clip, which secured the accelerator pump plunger to its actuation shaft in the carburetor, was missing & the pump was inoperative. The throttle cable housing/actuating shaft at the carburetor end was found separated from the cable sheath, exposing the unsupported inside cable. A piece of welding rod was found bent around the housing end & taped to the sheath. The cable was removed from the aircraft & operationally tested. During push-pull tests, the carburetor end would sometimes move an amount corresponding to the cockpit end input; at other times, the carburetor end would move only slightly.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the pilot's decision to fly the aircraft with a known mechanical discrepancy in the throttle linkage, which resulted in a partial loss of engine power; and his failure to maintain an adequate airspeed while maneuvering for an emergency landing, which resulted in an

inadvertent stall/spin. Inadequate maintenance/annual inspection was a related factor.

## Findings

Occurrence #1: LOSS OF ENGINE POWER(PARTIAL) - MECH FAILURE/MALF

Phase of Operation: CLIMB

### Findings

1. (F) MAINTENANCE,ANNUAL INSPECTION - INADEQUATE - OWNER/PILOT MECHANIC
2. (C) THROTTLE/POWER LEVER,CABLE - LOOSE
3. (C) OPERATION WITH KNOWN DEFICIENCIES IN EQUIPMENT - ATTEMPTED - OWNER/PILOT MECHANIC

-----

Occurrence #2: FORCED LANDING

Phase of Operation: EMERGENCY DESCENT/LANDING

-----

Occurrence #3: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: EMERGENCY DESCENT/LANDING

### Findings

4. (C) AIRSPEED - NOT MAINTAINED - PILOT IN COMMAND
5. (C) STALL/SPIN - INADVERTENT - PILOT IN COMMAND

-----

Occurrence #4: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

## Factual Information

On April 2, 1996, at 1058 hours Pacific standard time, a Powell Glasair homebuilt experimental airplane, N59LP, collided with trees and the ground following a loss of control during the base-to-final turn at the Pine Mountain Lake Airport, Groveland, California. The aircraft was owned and operated by the pilot. Visual meteorological conditions prevailed and no flight plan was filed for the local area personal flight. The aircraft was destroyed in the collision sequence. The private pilot, the sole occupant, sustained fatal injuries. The flight originated from the airport about 4 minutes prior to the accident.

Ground witnesses said the aircraft departed straight out following takeoff. About 4 minutes later, it made a downwind entry to the pattern "low and very close to the runway." The witnesses consistently estimated the aircraft's altitude as between 200 and 300 feet agl. One witness said the aircraft was so close that at first he thought the pilot was going to make a downwind landing on the runway. The witnesses said the aircraft made a tight turn from downwind to base. During the base-to-final turn, the right wing dropped and the aircraft entered a nose-down vertical descent to ground impact in a tree. The witnesses said they heard engine sounds throughout, however, they were described as "not full power."

The pilot holds an FAA Airframe and Powerplant mechanics certificate. Immediately prior to the accident flight, the pilot completed a condition/annual inspection on the aircraft and the airframe and engine logbooks were annotated to reflect the inspection. During a telephone interview, the aircraft co-owner stated that they had been having problems with the throttle cable and the pilot was going to order a new one.

An FAA airworthiness inspector responded to the accident site and interviewed witnesses and examined the wreckage. The engine portion of the wreckage examination was conducted with the assistance of a technical representative from Textron Lycoming Engines. Their respective reports are attached to this report.

The FAA inspector reported that he found no discrepancies with the aircraft's control system. Fuel was found in the aircraft tanks and all lines to the carburetor.

The engine crankshaft rotated easily by hand, with compression developed in each cylinder. Accessory gear and valve train continuity was established throughout the engine, with normal valve lift developed. Both magnetos were timed to 25 degrees before top dead center and produced strong sparks at each ignition lead. The examination report notes that the spark plugs exhibited normal operating signatures and the induction system was free of obstructions. No discrepancies were found with the fuel pump. Disassembly of the carburetor revealed that the clip which secures the accelerator pump plunger to its actuation shaft was missing and the pump was inoperative.

The throttle cable was examined in detail. The cable housing/actuating shaft at the carburetor end was found separated from the cable sheath, exposing the unsupported inside cable. A piece of welding rod was found bent around the housing end and taped to the sheath. The cable was removed from the aircraft and subjected to a series of operational tests. For the tests, the cable was supported by hand at each housing end and then the cockpit end was actuated, with no resistance on the carburetor end. In both push and pull directions, the carburetor end was observed to move intermittently. On some occasions, the carburetor end would move an amount corresponding to the cockpit end input; however, at other times, the carburetor end would only move slightly if at all.

The pilot sustained fatal injuries in the accident and an autopsy was conducted by the Tuolumne County Sheriff/Coroner with specimens retained for toxicological analysis. The results of the toxicological tests were negative for alcohol and all screened drug substances.

### Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	64, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	Yes
<b>Medical Certification:</b>	Class 3 Valid Medical-w/ waivers/lim	<b>Last FAA Medical Exam:</b>	August 26, 1994
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	1286 hours (Total, all aircraft), 15 hours (Total, this make and model), 6 hours (Last 90 days, all aircraft), 1 hours (Last 30 days, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	POWELL	<b>Registration:</b>	N59LP
<b>Model/Series:</b>	GLASAIR GLASAIR	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	Yes
<b>Airworthiness Certificate:</b>	Experimental (Special)	<b>Serial Number:</b>	156
<b>Landing Gear Type:</b>	Tricycle	<b>Seats:</b>	
<b>Date/Type of Last Inspection:</b>	April 2, 1996 Annual	<b>Certified Max Gross Wt.:</b>	
<b>Time Since Last Inspection:</b>	1 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	1656 Hrs	<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	Installed, activated, did not aid in locating accident	<b>Engine Model/Series:</b>	O-360-A1G
<b>Registered Owner:</b>	BOBBY HOCKETT & WALTER MAAS	<b>Rated Power:</b>	180 Horsepower
<b>Operator:</b>	BOBBY A. HOCKETT	<b>Operating Certificate(s) Held:</b>	None
<b>Operator Does Business As:</b>		<b>Operator Designator Code:</b>	

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>		<b>Distance from Accident Site:</b>	
<b>Observation Time:</b>		<b>Direction from Accident Site:</b>	
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	15 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	/	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	0°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>		<b>Temperature/Dew Point:</b>	17°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	(Q68 )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>		<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	10:54 Local	<b>Type of Airspace:</b>	Class E

## Airport Information

<b>Airport:</b>	PINE MOUNTAIN LAKE Q68	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	2930 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	27	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	3625 ft / 50 ft	<b>VFR Approach/Landing:</b>	Precautionary landing;Traffic pattern

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 Fatal	<b>Aircraft Damage:</b>	Destroyed
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 Fatal	<b>Latitude, Longitude:</b>	37.849895,-120.01091(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Rich, Jeff
<b>Additional Participating Persons:</b>	JIM MURRY; FRESNO , CA MARK W PLATT; WILLIAMSPORT , PA
<b>Original Publish Date:</b>	February 1, 1997
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=29405">https://data.ntsb.gov/Docket?ProjectID=29405</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).