

Aviation Investigation Final Report

Location: MARANA, Arizona Accident Number: LAX97LA041

Date & Time: November 14, 1996, 11:25 Local Registration: N1567P

Aircraft: Beech F33A Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The flight instructor reported that following some air work, the flight proceeded to the Avra Valley Airport where two touch-and-go landings were accomplished, followed by a full stop landing. The student taxied the aircraft back for takeoff, and the instructor took control to demonstrate procedures for an engine failure during the takeoff initial climb. The instructor stated that following a high performance takeoff, 'the airplane climbed to 50 to 100' AGL, at which time I smoothly reduced throttle to idle and lowered nose below level pitch. Airplane began to descend rapidly and I realized that the sink rate was quite large. I applied full throttle and raised nose to attempt to reduce sink. The airplane impacted the ground in approx. level attitude, the nose gear collapsed and the plane slid to a stop in approximately a few hundred feet.' The temperature was reported to be 81 degrees Fahrenheit. Based upon this temperature and the estimated pressure altitude, the density altitude was calculated to be 3.892 feet.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: improper planning/decision by the flight instructor (CFI), which resulted in his failure to recover from a descent during demonstration of a simulated (engine-out) emergency procedure.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: TAKEOFF

- Findings
 1. WEATHER CONDITION HIGH DENSITY ALTITUDE
- 2. EMERGENCY PROCEDURE SIMULATED PILOT IN COMMAND(CFI)
- 3. (C) PLANNING/DECISION IMPROPER PILOT IN COMMAND(CFI)
- 4. (C) DESCENT NOT CORRECTED PILOT IN COMMAND(CFI)

Page 2 of 6 LAX97LA041

Factual Information

On November 14, 1996, at 1125 hours mountain standard time, a Beech F33A, N1567P, collapsed the landing gear and damaged the wings during a hard landing at the Avra Valley, Arizona airport. The aircraft was owned and operated by Air Transport Training International, Inc., of Tucson, Arizona, and was engaged in a dual primary instructional flight. Visual meteorological conditions prevailed at the time and no flight plan was filed for the operation. The aircraft incurred substantial damage in the crash. The certificated airline transport pilot flight instructor and the dual primary student were not injured. The flight originated at the Ryan airport, Tucson, on the day of the accident at 1025.

In his written statement, the flight instructor reported that following some air work, the flight proceeded to the Avra Valley airport where two touch-and-go landings were accomplished, followed by a full-stop landing. The student taxied the aircraft back for takeoff and the instructor took control to demonstrate procedures for an engine failure during the takeoff initial climb. The instructor stated that following a high performance takeoff, "the airplane climbed to 50 to 100' AGL, at which time I smoothly reduced throttle to idle and lowered nose below level pitch. Airplane began to descend rapidly and I realized that the sink rate was quite large. I applied full throttle and raised nose to attempt to reduce sink. The airplane impacted the ground in approx. level attitude, the nose gear collapsed and the plane slid to a stop in approximately a few hundred feet."

The temperature at the time the accident occurred was 81 degrees Fahrenheit. Based upon this temperature and the estimated pressure altitude, the density altitude was calculated to be 3,892 feet msl.

Page 3 of 6 LAX97LA041

Pilot Information

| Certificate: | Airline transport; Flight instructor | Age: | 35,Male |
|---------------------------|---|-----------------------------------|-----------------|
| Airplane Rating(s): | Single-engine land; Multi-engine land | Seat Occupied: | Right |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | Airplane | Second Pilot Present: | Yes |
| Instructor Rating(s): | Airplane multi-engine; Airplane single-engine; Instrument airplane | Toxicology Performed: | No |
| Medical Certification: | Class 1 Valid Medicalno waivers/lim. | Last FAA Medical Exam: | October 8, 1996 |
| Occupational Pilot: | Yes | Last Flight Review or Equivalent: | |
| Flight Time: | 3367 hours (Total, all aircraft), 30 hours (Total, this make and model) | | |

Aircraft and Owner/Operator Information

| Aircraft Make: | Beech | Registration: | N1567P |
|-------------------------------|--|-----------------------------------|-----------------|
| Model/Series: | F33A F33A | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal; Utility | Serial Number: | CE-1296 |
| Landing Gear Type: | Retractable - Tricycle | Seats: | 4 |
| Date/Type of Last Inspection: | Continuous airworthiness | Certified Max Gross Wt.: | 3400 lbs |
| Time Since Last Inspection: | | Engines: | 1 Reciprocating |
| Airframe Total Time: | | Engine Manufacturer: | Continental |
| ELT: | Installed, activated, did not aid in locating accident | Engine Model/Series: | IO-520-BB18B |
| Registered Owner: | AIR TRANSPORT TRAINING INT | Rated Power: | 285 Horsepower |
| Operator: | | Operating Certificate(s) Held: | None |
| Operator Does Business As: | | Operator Designator Code: | |

Page 4 of 6 LAX97LA041

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|------------------------------|--------------------------------------|------------|
| Observation Facility, Elevation: | | Distance from Accident Site: | |
| Observation Time: | | Direction from Accident Site: | |
| Lowest Cloud Condition: | Scattered / 18000 ft AGL | Visibility | 40 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 0° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 29 inches Hg | Temperature/Dew Point: | 27°C / 1°C |
| Precipitation and Obscuration: | No Obscuration; No Precipita | ation | |
| Departure Point: | MIRANA , AZ (E14) | Type of Flight Plan Filed: | None |
| Destination: | | Type of Clearance: | None |
| Departure Time: | 11:24 Local | Type of Airspace: | Class E |

Airport Information

| Airport: | AVRA VALLEY E14 | Runway Surface Type: | Asphalt |
|----------------------|------------------|---------------------------|-----------------|
| Airport Elevation: | 2031 ft msl | Runway Surface Condition: | Dry |
| Runway Used: | 12 | IFR Approach: | None |
| Runway Length/Width: | 6901 ft / 100 ft | VFR Approach/Landing: | Traffic pattern |

Wreckage and Impact Information

| Crew Injuries: | 2 None | Aircraft Damage: | Substantial |
|------------------------|--------|-------------------------|----------------------------|
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 2 None | Latitude, Longitude: | 32.450042,-111.289695(est) |

Page 5 of 6 LAX97LA041

Administrative Information

Investigator In Charge (IIC): Rich, Jeff

Additional Participating Persons:

Original Publish Date: August 21, 1997

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=29684

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 LAX97LA041