



Aviation Investigation Final Report

Location: SAN JOSE, California Accident Number: LAX97LA267

Date & Time: July 26, 1997, 13:30 Local Registration: N8333V

Aircraft: Champion 7GCBC Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

The pilot's touchdown and initial rollout were uneventful. The pilot reported that he had the airplane trimmed 'all the way back,' and he applied brakes. The airplane veered off the runway, collided with an airport sign, nosed over, and came to rest in a dirt clearing adjacent to the runway. The pilot indicated that during the landing he had 'over corrected' which resulted in his loss of control as the airplane drifted left. The surface wind was calm.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain directional control, and excessive remedial action, which resulted in an inadvertent swerve off the runway.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

- 2. (C) REMEDIAL ACTION EXCESSIVE PILOT IN COMMAND
- 3. GROUND LOOP/SWERVE INADVERTENT PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: LANDING - ROLL

Findings 4. OBJECT - SIGN

Occurrence #3: NOSE OVER

Phase of Operation: LANDING - ROLL

Page 2 of 6 LAX97LA267

Factual Information

On July 26, 1997, at 1330 hours Pacific daylight time, a Champion 7GCBC, N8333V, owned and operated by the pilot, collided with an airport sign while landing on runway 31R at the Reid Hillview of Santa Clara County Airport, San Jose, California. The pilot reported that he had the airplane trimmed "all the way back," and he applied brakes. The airplane veered off the runway, collided with the sign, and came to rest in a dirt clearing adjacent to the runway. Visual meteorological conditions prevailed at the time of the personal flight, and no flight plan was filed. The airplane was substantially damaged, and the private pilot was not injured. The flight originated from San Jose at 1300.

In the pilot's completed report he indicated that no mechanical problems were experienced during the accident flight. The pilot further reported that during the landing he "over corrected" and the airplane drifted left. After colliding with the sign the airplane nosed over. At the time, the surface wind was calm.

Pilot Information

Certificate:	Private	Age:	62,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	July 11, 1995
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1000 hours (Total, all aircraft), 300 hours (Total, this make and model)		

Page 3 of 6 LAX97LA267

Aircraft and Owner/Operator Information

Aircraft Make:	Champion	Registration:	N8333V
Model/Series:	7GCBC 7GCBC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	63
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	January 24, 1997 Annual	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:	30 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1320 Hrs	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	0-320
Registered Owner:	FRED F. SCHURPF	Rated Power:	150 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	RHV ,133 ft msl	Distance from Accident Site:	
Observation Time:	13:30 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	(SJC)	Type of Flight Plan Filed:	None
Destination:	(RHV)	Type of Clearance:	VFR
Departure Time:	13:00 Local	Type of Airspace:	Class D

Page 4 of 6 LAX97LA267

Airport Information

Airport:	REID HILLVIEW RHV	Runway Surface Type:	Asphalt
Airport Elevation:	133 ft msl	Runway Surface Condition:	Dry
Runway Used:	31R	IFR Approach:	None
Runway Length/Width:	3101 ft / 75 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	37.330375,-121.829147(est)

Page 5 of 6 LAX97LA267

Administrative Information

Investigator In Charge (IIC):	Pollack, Wayne	
Additional Participating Persons:	J. P HOWARD; SAN JOSE , CA	
Original Publish Date:	November 10, 1998	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=29858	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 LAX97LA267