

Aviation Investigation Final Report

Location:	GOODYEAR, Arizon	а	Accident Number:	LAX98LA071
Date & Time:	January 13, 1998, 1	5:20 Local	Registration:	N2496V
Aircraft:	Cessna	140	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Instructional			

Analysis

On the third touch-and-go landing the student pilot inadvertently applied brake pressure. He lost control, ground looped the aircraft, and the landing gear collapsed. No mechanical malfunctions of the brake was noted by the student pilot.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The inadvertent brake activation by the student pilot while practicing touch-and-go landings.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - ROLL

Findings

1. (C) BRAKES(NORMAL) - INADVERTENT ACTIVATION - PILOT IN COMMAND 2. GROUND LOOP/SWERVE - ENCOUNTERED

Occurrence #2: GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Factual Information

On January 13, 1998, at 1520 hours mountain standard time, a Cessna 140, N2496V, ground looped on landing and collapsed the landing gear at the Goodyear, Arizona, airport. The aircraft sustained substantial damage, and the student pilot was not injured. Visual meteorological conditions existed for the local solo instructional flight and no flight plan was filed.

The student pilot reported that on his third touch-and-go landing he inadvertently applied brake pressure on landing, lost control, and ground looped the aircraft. He stated that weather was not a factor. He also reported that there were no mechanical difficulties with the aircraft.

Phot information			
Certificate:	Student	Age:	49,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	December 15, 1997
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	32 hours (Total, all aircraft), 28 hours (Total, this make and model), 1 hours (Pilot In Command, all aircraft), 28 hours (Last 90 days, all aircraft), 24 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Pilot Information

Aircraft and Owner/Operator Information

Cessna	Registration:	N2496V
140 140	Aircraft Category:	Airplane
	Amateur Built:	
Normal	Serial Number:	14765
Tailwheel	Seats:	2
January 23, 1997 Annual	Certified Max Gross Wt.:	1450 lbs
78 Hrs	Engines:	1 Reciprocating
5507 Hrs	Engine Manufacturer:	Continental
Installed, activated, did not aid in locating accident	Engine Model/Series:	C-90-12F
EVERET W. QUAMME	Rated Power:	90 Horsepower
	Operating Certificate(s) Held:	None
	Operator Designator Code:	
	140 140 Normal Tailwheel January 23, 1997 Annual 78 Hrs 5507 Hrs Installed, activated, did not aid in locating accident	140 140Aircraft Category:140 140Amateur Built:NormalSerial Number:TailwheelSeats:January 23, 1997 AnnualCertified Max Gross Wt.:78 HrsEngines:5507 HrsEngine Manufacturer:5507 HrsEngine Manufacturer:Installed, activated, did not aid in locating accidentRated Power:EVERET W. QUAMMERated Power:Operating Certificate(s) Held:Net and the second se

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Dav
Conditions at Accident Site.		Condition of Light.	Day
Observation Facility, Elevation:	GYR ,968 ft msl	Distance from Accident Site:	
Observation Time:	15:21 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	7 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	17°C / 6°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	(GYR)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	VFR
Departure Time:	14:55 Local	Type of Airspace:	Class D

Airport Information

Airport:	PHOENIX-GOODYEAR MUNI GYR	Runway Surface Type:	Asphalt
Airport Elevation:	968 ft msl	Runway Surface Condition:	Dry
Runway Used:	21	IFR Approach:	None
Runway Length/Width:	8500 ft / 150 ft	VFR Approach/Landing:	Touch and go;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	Cornejo, Tealeye		
Additional Participating Persons:	MICHAEL GONZALES; SCOTTSDALE , AZ		
Original Publish Date:	June 21, 2000		
Last Revision Date:			
Investigation Class:	<u>Class</u>		
Note:			
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=30020		

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.