

Aviation Investigation Final Report

Location:	VAN NUYS, Californ	ia	Accident Number:	LAX98LA078
Date & Time:	January 27, 1998, 1	2:30 Local	Registration:	N7921S
Aircraft:	Bellanca	8KCAB	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 91: General avi	ation - Personal		

Analysis

While on the takeoff roll the aircraft pulled hard to the left and the pilot counteracted with full right rudder. The aircraft departed the runway, crossed a grass area and a taxiway, and continued to a ramp area. The pilot was unable to stop the accident aircraft from impacting two parked aircraft. Winds at the time were from 090 degrees at 7 knots. The aircraft was examined on-scene and no mechanical difficulties were noted with the brakes. Flight control continuity was established on scene.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The student pilot's inadequate compensation for the existing crosswind condition and failure to maintain directional control. A related factor was the crosswind.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: TAKEOFF - ROLL/RUN

Findings

1. WEATHER CONDITION - CROSSWIND

2. (C) COMPENSATION FOR WIND CONDITIONS - INADEQUATE - PILOT IN COMMAND

3. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: COLLISION BETWEEN AIRCRAFT (OTHER THAN MIDAIR) Phase of Operation: TAKEOFF - ABORTED

Findings 4. OBJECT - AIRCRAFT PARKED/STANDING

Factual Information

On January 27, 1998, at 1230 hours Pacific standard time, a Bellanca 8KCAB, N7921S, veered off runway 16R on a midfield takeoff and struck several parked aircraft at the Van Nuys, California, airport. The aircraft, on lease back to AV-8, a fixed based operator at the airport, sustained substantial damage. The student pilot/owner was not injured. Visual meteorological conditions existed for the local instructional flight and no flight plan was filed. Winds reported at the time of the accident were 090 degrees at 7 knots.

The pilot reported that he had been given permission to taxi to runway 16R via taxiway 10G and cleared for takeoff. The pilot stated that on the takeoff roll everything was normal. The tail wheel came off the ground and the main landing gear started to depart the ground. He reported that the aircraft pulled hard to the left; he countered with full right rudder, but the aircraft continued to pull to the left. The aircraft departed the runway, crossed a grass area and a taxiway, and continued to the north ramp. The pilot stated that he was unable to stop the aircraft from impacting a Beech and a Cessna aircraft.

The aircraft was examined by a Federal Aviation Administration airworthiness inspector from the Van Nuys Flight Standards District Office. No mechanical difficulties were noted with the brakes, and flight control continuity was established on scene.

Certificate:	Student	Age:	46,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	August 22, 1996
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	47 hours (Total, all aircraft), 26 hour all aircraft)	rs (Total, this make and model), 4 hour	rs (Pilot In Command,

Pilot Information

Aircraft and Owner/Operator Information

Aircraft Make:	Bellanca	Registration:	N7921S
Model/Series:	8KCAB 8KCAB	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Aerobatic; Normal	Serial Number:	272-76
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	May 10, 1997 100 hour	Certified Max Gross Wt.:	1800 lbs
Time Since Last Inspection:	83 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1436 Hrs	Engine Manufacturer:	Lycoming
ELT:		Engine Model/Series:	AEIO-320-E1B
Registered Owner:	INVERTIBLE INC.	Rated Power:	150 Horsepower
Operator:	WARREN E. LEAVITT JR.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	VNY ,799 ft msl	Distance from Accident Site:	
Observation Time:	12:20 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 10000 ft AGL	Visibility	6 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	90°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	21°C / 7°C
Precipitation and Obscuration:	N/A - None - Haze		
Departure Point:	(VNY)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	VFR
Departure Time:	12:30 Local	Type of Airspace:	Class D

Airport Information

Airport:	VAN NUYS AIRPORT VNY	Runway Surface Type:	Asphalt
Airport Elevation:	799 ft msl	Runway Surface Condition:	Dry
Runway Used:	16R	IFR Approach:	None
Runway Length/Width:	8001 ft / 150 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	34.189838,-118.489929(est)

Administrative Information

Investigator In Charge (IIC):	Cornejo, Tealeye		
Additional Participating Persons:	JAMES COUGHRAN; VAN NUYS , CA		
Original Publish Date:	June 21, 2000		
Last Revision Date:			
Investigation Class:	<u>Class</u>		
Note:			
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=30025		

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.