



# Aviation Investigation Final Report

<b>Location:</b>	TULARE, California	<b>Accident Number:</b>	LAX98LA142
<b>Date &amp; Time:</b>	April 26, 1998, 09:11 Local	<b>Registration:</b>	N9144S
<b>Aircraft:</b>	Beech C23	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	2 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Personal		

## Analysis

During the landing rollout, the airplane departed the runway laterally and impacted a ditch 75 to 100 feet off the side of the runway. The pilot stated that, after a minor directional correction to the right, the aircraft would not respond to left steering inputs until full rudder was applied. At that time the aircraft entered an abrupt swerve to the left and departed the runway. The aircraft was damaged to the extent that it was not possible to conduct a high speed taxi test to evaluate aircraft response to nosewheel steering commands.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The malfunction of the nose wheel steering for undetermined reasons.

## Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER  
Phase of Operation: LANDING - ROLL

### Findings

1. LANDING GEAR,STEERING SYSTEM - MALFUNCTION
2. (C) REASON FOR OCCURRENCE UNDETERMINED

-----

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER  
Phase of Operation: LANDING - ROLL

Findings

3. (F) TERRAIN CONDITION - DITCH

## Factual Information

On April 26, 1998, at 0911 hours Pacific daylight time, a Beech C23, N9144S, was substantially damaged when it departed the runway laterally and impacted a ditch 75 to 100 feet off the side of the runway at Tulare, California. The private pilot and one passenger were not injured and no property damage was incurred. The flight had departed from Bakersfield, California, on a visual flight to Tulare. No flight plan was filed and visual meteorological conditions prevailed for the personal flight.

The pilot stated in his report that, on the landing roll, he applied right rudder to correct his ground path to runway centerline. When he applied left rudder to stop the turn, he got no aircraft response until he had applied full left rudder. At that time the aircraft entered an abrupt left turn from which he could not recover before departing the runway surface.

The aircraft was damaged to the extent that it was not possible to conduct a high speed taxi test to evaluate aircraft response to nosewheel steering commands.

### Pilot Information

<b>Certificate:</b>	Private	<b>Age:</b>	41, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Left
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	None	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	None	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 3 Valid Medical--no waivers/lim.	<b>Last FAA Medical Exam:</b>	July 25, 1997
<b>Occupational Pilot:</b>	No	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	92 hours (Total, all aircraft), 9 hours (Total, this make and model), 44 hours (Pilot In Command, all aircraft), 3 hours (Last 90 days, all aircraft), 2 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

## Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	Beech	<b>Registration:</b>	N9144S
<b>Model/Series:</b>	C23 C23	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Normal; Utility	<b>Serial Number:</b>	M-1767
<b>Landing Gear Type:</b>	Retractable - Tricycle	<b>Seats:</b>	4
<b>Date/Type of Last Inspection:</b>	March 20, 1998 Annual	<b>Certified Max Gross Wt.:</b>	2800 lbs
<b>Time Since Last Inspection:</b>	42 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	2008 Hrs	<b>Engine Manufacturer:</b>	Lycoming
<b>ELT:</b>	Installed, not activated	<b>Engine Model/Series:</b>	O-360 SER
<b>Registered Owner:</b>	TED C. WITT	<b>Rated Power:</b>	180 Horsepower
<b>Operator:</b>	KERN CHARTER SERVICE	<b>Operating Certificate(s) Held:</b>	None
<b>Operator Does Business As:</b>		<b>Operator Designator Code:</b>	

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	KVI ,292 ft msl	<b>Distance from Accident Site:</b>	10 Nautical Miles
<b>Observation Time:</b>	09:15 Local	<b>Direction from Accident Site:</b>	350°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	10 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	4 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	160°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30 inches Hg	<b>Temperature/Dew Point:</b>	16°C / 9°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>	BAKERSFIELD , CA (L45 )	<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	(TLR )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	08:25 Local	<b>Type of Airspace:</b>	Class E

## Airport Information

<b>Airport:</b>	MEFFORD FIELD TUR	<b>Runway Surface Type:</b>	Asphalt
<b>Airport Elevation:</b>	271 ft msl	<b>Runway Surface Condition:</b>	Dry
<b>Runway Used:</b>	13	<b>IFR Approach:</b>	None
<b>Runway Length/Width:</b>	3914 ft / 75 ft	<b>VFR Approach/Landing:</b>	Full stop;Traffic pattern

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>	1 None	<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	2 None	<b>Latitude, Longitude:</b>	36.180725,-119.359848(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Armstrong, Weldon
<b>Additional Participating Persons:</b>	JAMES SHAMP; FRESNO , CA
<b>Original Publish Date:</b>	April 6, 2001
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.ntsb.gov/Docket?ProjectID=30073">https://data.ntsb.gov/Docket?ProjectID=30073</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).