



Aviation Investigation Final Report

Location: ROCHESTER, New York Accident Number: NYC86LA080

Date & Time: February 27, 1986, 11:30 Local Registration: N36638

Aircraft: BEECH 95-B55 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 135: Air taxi & commuter - Non-scheduled

Analysis

ON LANDING ROLL LEFT GEAR COLLAPSED, AIRPLANE SWERVED LEFT, CAME TO A STOP. AIRPLANE SUBSTANTIALLY DAMAGED. NO FIRE. NO INJURIES.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: MAIN GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Findings

1. (C) LANDING GEAR, GEAR LOCKING MECHANISM - UNLOCKED

2. (C) REASON FOR OCCURRENCE UNDETERMINED

Factual Information

Pilot Information

Certificate:	Airline transport	Age:	26,Male
Airplane Rating(s):	Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	October 3, 1985
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	3033 hours (Total, all aircraft), 15 hours (Total, this make and model), 1094 hours (Pilot In Command, all aircraft), 65 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

BEECH	Registration:	N36638
95-B55 95-B55	Aircraft Category:	Airplane
	Amateur Built:	
Normal	Serial Number:	TC-2325
Retractable - Tricycle	Seats:	6
June 1, 1985 Unknown	Certified Max Gross Wt.:	5100 lbs
81 Hrs	Engines:	2 Reciprocating
2802 Hrs	Engine Manufacturer:	CONTINENTAL
Installed, not activated	Engine Model/Series:	10-470-L
VAN-AIR	Rated Power:	260 Horsepower
	Operating Certificate(s) Held:	On-demand air taxi (135)
	Operator Designator Code:	B1QA
	95-B55 95-B55 Normal Retractable - Tricycle June 1, 1985 Unknown 81 Hrs 2802 Hrs Installed, not activated	95-B55 95-B55 Aircraft Category: Amateur Built: Normal Serial Number: Seats: June 1, 1985 Unknown Certified Max Gross Wt.: 81 Hrs Engines: Engine Manufacturer: Installed, not activated VAN-AIR Rated Power: Operating Certificate(s) Held:

Page 2 of 4 NYC86LA080

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)		Condition of Light:	Day
Observation Facility, Elevation:			Distance from Accident Site:	
Observation Time:			Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 40	000 ft AGL	Visibility	20 miles
Lowest Ceiling:	Unknown / 40	000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /		Turbulence Type Forecast/Actual:	/
Wind Direction:	270°		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg		Temperature/Dew Point:	-4°C / -7°C
Precipitation and Obscuration:	No Obscuration	on; No Precipita	ition	
Departure Point:	TORONTO	(4TZ)	Type of Flight Plan Filed:	IFR
Destination:			Type of Clearance:	IFR
Departure Time:			Type of Airspace:	Class E

Airport Information

Airport:	ROCHESTER ROC	Runway Surface Type:	Asphalt
Airport Elevation:	560 ft msl	Runway Surface Condition:	Dry
Runway Used:	25	IFR Approach:	None
Runway Length/Width:	4430 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	43.170856,-77.700469(est)

Page 3 of 4 NYC86LA080

Administrative Information

Investigator In Charge (IIC):	Twine, Chauncey
Additional Participating Persons:	
Original Publish Date:	April 25, 1988
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=30304

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 NYC86LA080