

Aviation Investigation Final Report

Location:	KOTZEBUE, Alaska		Accident Number:	ANC97LA136
Date & Time:	August 30, 1997, 19	9:50 Local	Registration:	N93276
Aircraft:	Cessna	185F	Aircraft Damage:	Substantial
Defining Event:			Injuries:	2 None
Flight Conducted Under:	Part 91: General av	iation		

Analysis

The pilot landing the tundra tire equipped airplane on a 600 feet long x 75 feet wide gravel landing area. The pilot stated that the off-airport site was too short to stop, so he attempted to ground loop to the left to avoid running off the end into a drop off. The right wing and right stabilizer contacted the ground.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's selection of an unsuitable landing area. A factor was the short length of the offairport site.

Findings

Occurrence #1: OVERRUN Phase of Operation: LANDING - ROLL

Findings

1. (F) TERRAIN CONDITION - SHORT RUNWAY/LANDING AREA 2. (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA - SELECTED - PILOT IN COMMAND

Occurrence #2: ABRUPT MANEUVER Phase of Operation: LANDING - ROLL Findings 3. GROUND LOOP/SWERVE - INTENTIONAL - PILOT IN COMMAND

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER Phase of Operation: LANDING - ROLL

Findings

4. TERRAIN CONDITION - GROUND

Factual Information

On August 30, 1997, at 1950 Alaska daylight time, a tundra tire equipped Cessna 185F airplane, N93276, was substantially damaged when its right wing and right horizontal stabilizer contacted terrain at the end of an off-airport landing site, 28 miles northeast of Kotzebue, Alaska, at position 67-35 degrees north latitude, 161-47 west longitude. The commercial certificated pilot and one passenger were uninjured. The airplane was operated by Mavrik Aire of Soldotna, Alaska. The flight was conducted under 14 CFR Part 91 as a business flight preparing camps for the upcoming hunting season. Visual meteorological conditions prevailed at the time of the accident, and a flight plan was filed with a local lodge owner.

During an interview with the NTSB investigator, the pilot stated that he and an employee were landing at the 600 feet long x 75 feet wide site, in calm winds, and were not able to stop before reaching the end. The terrain steeply dropped off at the end of the landing area. The pilot attempted to ground loop the airplane to the left, the airplane tipped up on the right wing, and the right wing and right horizontal stabilizer struck the ground.

Certificate:	Commercial	Age:	30,Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	August 1, 1997
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	5000 hours (Total, all aircraft), 2500 hours (Total, this make and model), 4000 hours (Pilot In Command, all aircraft), 150 hours (Last 90 days, all aircraft), 50 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Pilot Information

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N93276
Model/Series:	185F 185F	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	185-03208
Landing Gear Type:	Tailwheel	Seats:	6
Date/Type of Last Inspection:	August 1, 1997 100 hour	Certified Max Gross Wt.:	3350 lbs
Time Since Last Inspection:	50 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	6000 Hrs	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	IO-520D
Registered Owner:	PAT LOCKHART	Rated Power:	300 Horsepower
Operator:	CRAIG M. SCHWEITZER	Operating Certificate(s) Held:	On-demand air taxi (135)
Operator Does Business As:	MAVRIK AIRE	Operator Designator Code:	M9UC

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 4000 ft AGL	Visibility	50 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	10°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	, AK (OTZ)	Type of Flight Plan Filed:	Company VFR
Destination:	SQUIRREL RIVER , AK	Type of Clearance:	None
Departure Time:	19:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop;Valley/terrain following

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	67.240028,-161.189788(est)

Administrative Information

Investigator In Charge (IIC):	Thomas, Matthew	
Additional Participating Persons:	DAVID A SMITH; FAIRBANKS , AK	
Original Publish Date:	November 6, 1998	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=3057	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.