



Aviation Investigation Final Report

Location: GUAYAMA, Puerto Rico Accident Number: MIA84LA098

Date & Time: March 7, 1984, 23:30 Local Registration: N2610X

Aircraft: CESSNA 206 Aircraft Damage: Destroyed

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PLT HAD PURCHASED THE ACFT ABOUT 2 WKS PRIOR TO THE ACCIDENT. AFTER CLIMBING ON TOP FOR A X-COUNTRY FLT, HE LOST RADIO COMMUNICATION. HE ELECTED TO CONTINUE ON THE FLT & MAKE POSITION REPORTS IN THE BLIND. THE PLT REPORTED THAT HE ENCOUNTERED HEADWINDS. LATER, HE REPORTEDLY SMELLED FUEL, THEN THE ENG BEGAN TO SPUTTER. HE DIVERTED TOWARD PUERTO RICO, BUT THE ENG LOST POWER. HE DITCHED THE ACFT ABOUT 2 MI FROM PUNTA POZUELO PENINSULA, PUERTO RICO, ABOUT 5 HRS AFTER TAKING OFF. ACCORDING TO THE OWNER'S MANUAL, MAX ENDURANCE AT 65% POWER WAS 5.1 HRS.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: CRUISE

Findings

- 1. (C) PREFLIGHT PLANNING/PREPARATION INADEQUATE PILOT IN COMMAND
- 2. (F) LACK OF TOTAL EXPERIENCE IN TYPE OF AIRCRAFT PILOT IN COMMAND
- 3. FUEL CONSUMPTION CALCULATIONS INACCURATE PILOT IN COMMAND
- 4. (C) FLUID, FUEL EXHAUSTION

5. (C) FUEL SUPPLY - INADEQUATE - PILOT IN COMMAND

Occurrence #2: FORCED LANDING Phase of Operation: LANDING

Occurrence #3: DITCHING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Page 2 of 5 MIA84LA098

Factual Information

Pilot Information

| Certificate: | Airline transport; Commercial | Age: | 35,Male |
|---------------------------|--|-----------------------------------|------------------|
| Airplane Rating(s): | Single-engine land; Multi-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | Airplane | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | None Valid Medicalno waivers/lim. | Last FAA Medical Exam: | October 23, 1984 |
| Occupational Pilot: | Yes | Last Flight Review or Equivalent: | |
| Flight Time: | 3300 hours (Total, all aircraft), 68 hours (Total, this make and model), 3060 hours (Pilot In Command, all aircraft), 60 hours (Last 90 days, all aircraft), 4 hours (Last 24 hours, all aircraft) | | |

Aircraft and Owner/Operator Information

| Aircraft Make: | CESSNA | Registration: | N2610X |
|-------------------------------|--------------------------|-----------------------------------|-----------------|
| Model/Series: | 206 206 | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | P206-0110 |
| Landing Gear Type: | Tricycle | Seats: | 6 |
| Date/Type of Last Inspection: | 100 hour | Certified Max Gross Wt.: | 2475 lbs |
| Time Since Last Inspection: | 60 Hrs | Engines: | 1 Reciprocating |
| Airframe Total Time: | 2590 Hrs | Engine Manufacturer: | CONTINENTAL |
| ELT: | Installed, not activated | Engine Model/Series: | I0-520-A |
| Registered Owner: | GERRY K. KING | Rated Power: | 285 Horsepower |
| Operator: | FRANK CHUKES | Operating Certificate(s) Held: | |
| Operator Does Business As: | | Operator Designator Code: | |

Page 3 of 5 MIA84LA098

Meteorological Information and Flight Plan

| | 1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 (1 | | NU Local L |
|----------------------------------|--|--------------------------------------|-------------------|
| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Night/dark |
| Observation Facility, Elevation: | SJU ,10 ft msl | Distance from Accident Site: | 60 Nautical Miles |
| Observation Time: | 17:53 Local | Direction from Accident Site: | 175° |
| Lowest Cloud Condition: | Scattered / 3000 ft AGL | Visibility | 20 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 10 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 120° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 30 inches Hg | Temperature/Dew Point: | 27°C / 19°C |
| Precipitation and Obscuration: | No Obscuration; No Precipita | ition | |
| Departure Point: | MONT.BAY , OF (MKJS) | Type of Flight Plan Filed: | IFR |
| Destination: | (STX) | Type of Clearance: | IFR |
| Departure Time: | 00:00 Local | Type of Airspace: | Class G |

Airport Information

| Airport: | | Runway Surface Type: | |
|----------------------|---|----------------------------------|----------------|
| Airport Elevation: | | Runway Surface Condition: | |
| Runway Used: | 0 | IFR Approach: | |
| Runway Length/Width: | | VFR Approach/Landing: | Forced landing |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Destroyed |
|------------------------|--------|-------------------------|-----------|
| Passenger Injuries: | 1 None | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 2 None | Latitude, Longitude: | |

Page 4 of 5 MIA84LA098

Administrative Information

| Investigator In Charge (IIC): | Baro, Edward |
|-----------------------------------|--|
| Additional Participating Persons: | |
| Original Publish Date: | |
| Last Revision Date: | |
| Investigation Class: | <u>Class</u> |
| Note: | |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=31090 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 MIA84LA098