



Aviation Investigation Final Report

Location: MINCHUMINA, Alaska Accident Number: ANC98LA053

Date & Time: May 25, 1998, 08:40 Local Registration: N1199E

Aircraft: Bellanca 8GCBC Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The solo student was landing at a remote, gravel airstrip. He stated that he visually inspected the airport wind sock and determined the winds were 'light and variable', favoring runway 20. He stated that the approach was normal until he went below the adjacent tree line, and the rate of descent increased. He was unable to arrest the descent prior to touchdown, and the airplane hit hard and bounced twice. He was unable to maintain directional control, and the airplane turned 45 degrees from its original runway heading. He said that in an attempt to abort the landing, he added full power, and the airplane went off the right side of the runway. The left wing struck a stand of trees.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain directional control while landing. A factor associated with this accident was the pilot's inadequate recovery from a bounced landing.

Findings

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) RECOVERY FROM BOUNCED LANDING - INADEQUATE - PILOT IN COMMAND

Occurrence #2: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ABORTED

Findings

2. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #3: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: LANDING - ABORTED

Findings

3. OBJECT - TREE(S)

Page 2 of 6 ANC98LA053

Factual Information

On May 25, 1998, about 0840 Alaska daylight time, a wheel equipped Bellanca 8GCBC airplane, N1199E, sustained substantial damage while landing at the Minchumina Airport, Minchumina, Alaska. The airplane was being operated as a visual flight rules (VFR) student cross country flight under Title 14 CFR Part 91 when the accident occurred. The solo student pilot was not injured. Visual meteorological conditions prevailed, and a VFR flight plan was filed. The flight originated at the Chena Marina Airport, Fairbanks, Alaska, about 0721.

During a telephone conversation with the National Transportation Safety Board investigator-incharge, on May 27, the student pilot reported that, prior to landing, he looked at the airport wind sock and determined the winds were "light and variable", favoring runway 20. He stated that the approach was normal until he went below the adjacent tree line, and the rate of descent increased. He was unable to arrest the descent prior to touchdown, and the airplane hit hard and bounced twice. The pilot noted in his written statement that he was unable to maintain directional control, and the airplane turned 45 degrees from its original runway heading. The pilot stated that in an attempt to abort the landing, he added full power, and the airplane went off the right side of the runway. The left wing struck a stand of trees and received substantial damage.

The pilot stated that there were no preaccident mechanical anomalies with the airplane.

Pilot Information

Certificate:	Student	Age:	42,Male
Airplane Rating(s):	None	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	March 11, 1997
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	61 hours (Total, all aircraft), 61 hour	rs (Total, this make and model)	

Page 3 of 6 ANC98LA053

Aircraft and Owner/Operator Information

Aircraft Make:	Bellanca	Registration:	N1199E
Model/Series:	8GCBC 8GCBC	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	254-77
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	December 5, 1997 Annual	Certified Max Gross Wt.:	2150 lbs
Time Since Last Inspection:	13 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1436 Hrs	Engine Manufacturer:	Lycoming
ELT:	Installed, not activated	Engine Model/Series:	O-360-C1E
Registered Owner:	MICHAEL HELMBRECHT	Rated Power:	180 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipi	ation	
Departure Point:	CHENA MARINA , AK (AK28)	Type of Flight Plan Filed:	VFR
Destination:	MINCHUMINA , AK (MHM)	Type of Clearance:	None
Departure Time:	07:21 Local	Type of Airspace:	Class G

Page 4 of 6 ANC98LA053

Airport Information

Airport:	MINCHUMINA MHM	Runway Surface Type:	Gravel
Airport Elevation:	684 ft msl	Runway Surface Condition:	Wet
Runway Used:	20	IFR Approach:	None
Runway Length/Width:	4200 ft / 90 ft	VFR Approach/Landing:	Straight-in

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	

Page 5 of 6 ANC98LA053

Administrative Information

Investigator In Charge (IIC):	Johnson, Clinton	
Additional Participating Persons:	MIKE KALKANA (FAA); FAIRBANKS , AK	
Original Publish Date:	November 17, 1999	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=3142	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC98LA053