



# **Aviation Investigation Final Report**

Location: TITUSVILLE, Florida Accident Number: MIA89LA244

Date & Time: September 10, 1989, 13:05 Local Registration: N7946P

Aircraft: PIPER PA-24-180 Aircraft Damage: Substantial

**Defining Event:** 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

### **Analysis**

AS THE ACFT WAS ON FINAL APCH TO LAND AFTER A BFR FLT, THE ENG LOST POWER DUE TO FUEL STARVATION. DURING A SUBSEQUENT EMERGENCY LANDING, IT COLLIDED WITH TREES SHORT OF THE RWY & WAS DAMAGED. AN INVESTIGATION REVEALED THE ENG LOST POWER WHEN THE RIGHT FUEL TANK EMPTIED & THE LEFT TANK WAS STILL FULL.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: FAILURE OF THE PRIVATE PILOT (DUAL STUDENT) TO ASSURE THE FUEL SELECTOR WAS POSITIONED TO THE PROPER TANK, WHICH RESULTED IN FUEL STARVATION; AND INADEQUATE SUPERVISION BY THE INSTRUCTOR PILOT (CFI). THE TREES WERE A RELATED FACTOR.

#### **Findings**

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

#### **Findings**

- 1. (C) FLUID, FUEL STARVATION
- 2. (C) FUEL TANK SELECTOR POSITION IMPROPER DUAL STUDENT
- 3. (C) SUPERVISION INADEQUATE PILOT IN COMMAND(CFI)

-----

Occurrence #2: FORCED LANDING Phase of Operation: LANDING

Occurrence #3: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: LANDING

Findings

4. (F) OBJECT - TREE(S)

Page 2 of 6 MIA89LA244

## **Factual Information**

#### **Pilot Information**

Certificate:	Commercial; Flight instructor	Age:	57,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 3 Invalid Medical for flight	Last FAA Medical Exam:	January 4, 1989
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	6000 hours (Total, all aircraft), 75 hours (Total, this make and model), 6000 hours (Pilot In Command, all aircraft), 120 hours (Last 90 days, all aircraft), 40 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Page 3 of 6 MIA89LA244

### **Aircraft and Owner/Operator Information**

Aircraft Make:	PIPER	Registration:	N7946P
Model/Series:	PA-24-180 PA-24-180	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	24-3182
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	2550 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Installed	Engine Model/Series:	O-360-A1A
Registered Owner:	H. L. PUGH	Rated Power:	180 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	TIX ,35 ft msl	Distance from Accident Site:	
Observation Time:	13:05 Local	Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Scattered / 2500 ft AGL	Visibility	7 miles
Lowest Ceiling:	Broken / 15000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	30°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-18°C / -18°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	12:00 Local	Type of Airspace:	Class G

Page 4 of 6 MIA89LA244

## **Airport Information**

Airport:	SPACE CENTER EXECUTIVE TIX	Runway Surface Type:	Asphalt
Airport Elevation:	35 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	36	IFR Approach:	None
Runway Length/Width:	6001 ft / 150 ft	VFR Approach/Landing:	Forced landing;Straight-in

## Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	28.57916,-80.819854(est)

Page 5 of 6 MIA89LA244

#### **Administrative Information**

Investigator In Charge (IIC): Monville, Timothy

Additional Participating
Persons:

Original Publish Date: September 5, 1991

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=32499

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 MIA89LA244