



Aviation Investigation Final Report

Location: LAWRENCE, Kansas Accident Number: MKC83LA217

Date & Time: September 12, 1983, 14:00 Local Registration: N2327G

Aircraft: PIPER PA-38-112 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

THE PILOT STATED THAT HE WAS TAKING OFF FOR HIS FOURTH TOUCH AND GO LANDING WHEN THE ACFT WEATHERVANED AND HE LOST CONTROL OF THE ACFT. THE NOSE WHEEL STRUCK A CONCRETE DRAINAGE DITCH.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: TAKEOFF - ROLL/RUN

Findings

1. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: TAKEOFF - ROLL/RUN

Findings

2. TERRAIN CONDITION - DITCH

Page 2 of 5 MKC83LA217

Factual Information

Pilot Information

Certificate:	Student	Age:	26,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	July 29, 1983
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	34 hours (Total, all aircraft), 34 hours (Total, this make and model), 17 hours (Pilot In Command, all aircraft), 17 hours (Last 90 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N2327G
Model/Series:	PA-38-112 PA-38-112	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	112
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	August 8, 1983 100 hour	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:	92 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	966 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	0-235-L2C
Registered Owner:	DAVID HOOVER	Rated Power:	112 Horsepower
Operator:	CAPITOL AIR SERVICE	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 MKC83LA217

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	20 knots / 25 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	10°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	24°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Airport Information

Airport:	LAWRENCE MUNI 3LA	Runway Surface Type:	Asphalt
Airport Elevation:	834 ft msl	Runway Surface Condition:	Dry
Runway Used:	1	IFR Approach:	None
Runway Length/Width:	3900 ft / 75 ft	VFR Approach/Landing:	Touch and go

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	39.020053,-95.21035(est)

Page 4 of 5 MKC83LA217

Administrative Information

Investigator In Charge (IIC):	Thorpe, C.
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=33486

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 MKC83LA217