



Aviation Investigation Final Report

Location: CELINA, Tennessee Accident Number: ATL94LA067

Date & Time: March 23, 1994, 07:30 Local Registration: N76342

Aircraft: CESSNA 140 Aircraft Damage: Destroyed

Defining Event: 1 Fatal, 1 Minor

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE STUDENT PILOT REPORTED THAT HE WAS FLYING LOW, OVER THE CUMBERLAND RIVER, WHEN THE AIRCRAFT COLLIDED WITH A POWER LINE. HE LOST CONTROL OF THE AIRPLANE, AND IT CRASHED INTO THE RIVER. HIS PASSENGER, WHO WAS NOT A PILOT, WAS FATALLY INJURED. THE PILOT WAS ISSUED HIS STUDENT CERTIFICATE 12 DAYS PRIOR TO THE ACCIDENT, AND AT THAT TIME REPORTED A TOTAL FLIGHT TIME OF 385 HOURS. AN INSPECTION OF THE WRECKAGE REVEALED NO EVIDENCE OF MECHANICAL FAILURE OR MALFUNCTION. THE WIRE WHICH WAS SEVERED BY THE AIRPLANE WAS ERECTED ABOUT 90 FEET ABOVE THE SURFACE OF THE RIVER.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S FAILURE TO MAINTAIN A PROPER ALTITUDE, AND HIS FAILURE TO MAINTAIN CLEARANCE FROM THE TRANSMISSION WIRE.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH OBJECT

Phase of Operation: CRUISE

Findings

1. OBJECT - WIRE, TRANSMISSION

2. (C) PROPER ALTITUDE - NOT MAINTAINED - PILOT IN COMMAND

3. (C) CLEARANCE - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: CRUISE

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - UNCONTROLLED

Page 2 of 6 ATL94LA067

Factual Information

On March 23, 1993, at about 0730 central standard time, a Cessna 140, N76342, collided with a power line during cruise flight near Celina, Tennessee. The non-rated pilot had minor injuries, and his passenger was fatally injured. The aircraft was destroyed. The aircraft was operated under 14 CFR Part 91 by the pilot. Visual meteorological conditions existed at the time, and no flight plan was filed for the personal flight. The flight originated in Gainesboro, Tennessee, at an unknown time.

The pilot reported to law enforcement personnel that he was flying low, over the Cumberland River, when the aircraft collided with a power line. He lost aircraft control, and the aircraft crashed into the river.

An inspector from the Federal Aviation Administration (FAA) visited the accident site and inspected the aircraft after it was recovered from the river. He reported that the power line was severed at a point that was approximately 90 feet above the surface of the water. Details of his wreckage examination are included in the inspector's written statement as an attachment to this report.

The pilot was issued a student pilot and third class medical certificate on March 11, 1994. According to FAA records, he was not rated in any airplane. On his certificate application, he reported a total flying time of 385 hours. The passenger did not possess any pilot certificates or ratings.

Pilot Information

Certificate:	Student	Age:	46,Male
Airplane Rating(s):	None	Seat Occupied:	Unknown
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	March 11, 1994
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	385 hours (Total, all aircraft)		

Page 3 of 6 ATL94LA067

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N76342
Model/Series:	140 140	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	10759
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1500 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:		Engine Model/Series:	C-85-12
Registered Owner:	VASSILEV, JAMES H.	Rated Power:	85 Horsepower
Operator:	VASSILEV, JAMES H.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	8A3 ,1370 ft msl	Distance from Accident Site:	12 Nautical Miles
Observation Time:	07:40 Local	Direction from Accident Site:	130°
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	6 knots / None	Turbulence Type Forecast/Actual:	/
Wind Direction:	200°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	17°C / -1°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	GAINESBORO (1A7)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class G

Page 4 of 6 ATL94LA067

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Destroyed
Passenger Injuries:	1 Fatal	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Fatal, 1 Minor	Latitude, Longitude:	36.540962,-85.499221(est)

Page 5 of 6 ATL94LA067

Administrative Information

Investigator In Charge (IIC):	Hicks, Ralph	
Additional Participating Persons:	ROBERT D DAVIDSON; NASHVILLE , TN	
Original Publish Date:	November 14, 1994	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=3360	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ATL94LA067