



Aviation Investigation Final Report

Location: CHAPEL HILL, North Carolina Accident Number: ATL94LA106

Date & Time: May 25, 1994, 14:30 Local Registration: N8527Q

Aircraft: CESSNA A185F Aircraft Damage: Substantial

Defining Event: 4 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE AIRPLANE WAS LANDING ON RUNWAY 27. THE PILOT REPORTED THE SURFACE WINDS TO BE FROM THE SOUTH AT 7 TO 10 KNOTS, WITH GUSTS TO 15 KNOTS. DURING THE LANDING ROLLOUT, A GUST OF WIND WAS ENCOUNTERED. THE PILOT LOST DIRECTIONAL CONTROL, AND THE AIRCRAFT DEPARTED THE RUNWAY SURFACE TO THE RIGHT. THE AIRCRAFT THEN GROUND LOOPED. THE PILOT REPORTED NO MECHANICAL MALFUNCTION OR FAILURE WITH THE AIRCRAFT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S INADEQUATE COMPENSATION FOR WIND CONDITIONS, AND HIS FAILURE TO MAINTAIN DIRECTIONAL CONTROL DURING THE LANDING ROLL. FACTORS WERE THE CROSSWINDS AND GUSTS PREVAILING AT THE AIRPORT AT THE TIME OF THE ACCIDENT.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (F) WEATHER CONDITION - GUSTS

2. (F) WEATHER CONDITION - CROSSWIND

3. (C) COMPENSATION FOR WIND CONDITIONS - INADEQUATE - PILOT IN COMMAND

4. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER Phase of Operation: LANDING - ROLL

Page 2 of 6 ATL94LA106

Factual Information

On May 25, 1994, at 1430 eastern daylight time, a Cessna A185F, N8527Q, was substantially damaged during a loss of directional control while landing at the Horace Williams Airport in Chapel Hill, North Carolina. The airline transport pilot and three passengers were not injured. The aircraft was operated under 14 CFR Part 91 by the pilot. Visual meteorological conditions existed at the time, and an instrument flight rules flight plan was filed for the personal flight. The flight originated in Columbia, South Carolina at 1330.

The pilot reported the following: He landed the airplane on runway 27 following a normal approach. During the landing rollout, a gust of wind was encountered, which turned the aircraft sideways (toward the south). The aircraft departed the runway surface and ground looped. Structural damage to the right wing, right horizontal stabilizer, and right, main landing gear resulted. He reported no mechanical malfunction or failure with the aircraft.

The Horace Williams Airport does not have weather reporting capability. The pilot estimated the winds at the time of the accident to be out of the south at 7 to 10 knots, with gusts to 15 knots. The Raleigh-Durham International Airport, located about 13 miles east-southeast of Horace Williams, was reporting surface winds from 230 degrees at 10 knots, with no gusts, about 20 minutes after the accident.

Pilot Information

Certificate:	Airline transport; Commercial	Age:	43,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine; None	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	March 28, 1994
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	4000 hours (Total, all aircraft), 2000 hours (Total, this make and model), 3850 hours (Pilot In Command, all aircraft)		

Page 3 of 6 ATL94LA106

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N8527Q
Model/Series:	A185F A185F	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal; Provisional (Special)	Serial Number:	18503726
Landing Gear Type:	Tailwheel	Seats:	6
Date/Type of Last Inspection:	April 1, 1994 Annual	Certified Max Gross Wt.:	3350 lbs
Time Since Last Inspection:	38 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2020 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	IO-520-D
Registered Owner:	NORTH STATE AIR SERVICE, INC.	Rated Power:	300 Horsepower
Operator:	COFFMAN, EDWARD K.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	RDU ,437 ft msl	Distance from Accident Site:	14 Nautical Miles
Observation Time:	14:50 Local	Direction from Accident Site:	115°
Lowest Cloud Condition:	Scattered / 3000 ft AGL	Visibility	7 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	230°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	29°C / 19°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	COLUMBIA , SC (CUB)	Type of Flight Plan Filed:	IFR
Destination:		Type of Clearance:	VFR;IFR
Departure Time:	13:30 Local	Type of Airspace:	Class G

Page 4 of 6 ATL94LA106

Airport Information

Airport:	HORACE WILLIAMS W52	Runway Surface Type:	Asphalt
Airport Elevation:	509 ft msl	Runway Surface Condition:	Dry
Runway Used:	27	IFR Approach:	None
Runway Length/Width:	4005 ft / 75 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	3 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	4 None	Latitude, Longitude:	35.920364,-79.040725(est)

Page 5 of 6 ATL94LA106

Administrative Information

Investigator In Charge (IIC):	Hicks, Ralph	
Additional Participating Persons:	JANE T LAMBERT; WINSTON-SALEM , NC	
Original Publish Date:	February 24, 1995	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=3390	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ATL94LA106