



Aviation Investigation Final Report

Location: SHAWNEE, Kansas Accident Number: MKC85LA185

Date & Time: August 10, 1985, 20:00 Local Registration: N40468

Aircraft: BALLOON WORKS FIREFLY 7 Aircraft Damage: None

Defining Event: 1 Serious, 3 None

Flight Conducted Under: Part 91: General aviation

Analysis

THE COMMERCIAL BALLOON PLT WAS GIVING A RIDE TO THREE PAYING PASSENGERS. PLT STATED THAT DURING THE LANDING APCH HIGHER THAN NORMAL WINDS WERE PRESENT SO HE BRIEFED THE PASSENGERS TO LEAN AGAINST THE SIDE OF THE BASKET. HE STATED THAT HE PULLED THE DEFLATION LINE WHEN THE BASKET WAS 3 FT AGL. ONE PASSENGER GOT HER ARM UNDER THE SIDE OF THE BASKET AS IT WAS SKIDDING AND RECEIVED LACERATIONS. AFTER SHE WAS TAKEN TO THE HOSPITAL, SHE WAS FOUND TO HAVE TWO COMPRESSED VERTEBRAE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: HARD LANDING Phase of Operation: LANDING

Findings

1. (F) WEATHER CONDITION - HIGH WIND

2. (C) PROPER DESCENT RATE - EXCEEDED - PILOT IN COMMAND

Page 2 of 5 MKC85LA185

Factual Information

Pilot Information

Certificate:	Commercial; Private	Age:	Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Unknown
Other Aircraft Rating(s):	Balloon	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	None Unknown	Last FAA Medical Exam:	
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	534 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	BALLOON WORKS	Registration:	N40468
Model/Series:	FIREFLY 7 FIREFLY 7	Aircraft Category:	Balloon
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	7902
Landing Gear Type:	Retractable - Tricycle	Seats:	
Date/Type of Last Inspection:	July 18, 1985 Annual	Certified Max Gross Wt.:	900 lbs
Time Since Last Inspection:	7 Hrs	Engines:	0 Unknown
Airframe Total Time:	320 Hrs	Engine Manufacturer:	
ELT:	Not installed	Engine Model/Series:	
Registered Owner:	RAY M. DITIRRO	Rated Power:	
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 MKC85LA185

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Dusk
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:	20:15 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	8 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	135°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	19:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	Asphalt
Airport Elevation:	0 ft msl	Runway Surface Condition:	Dry
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	None
Passenger Injuries:	1 Serious, 2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious, 3 None	Latitude, Longitude:	39.019744,-94.709922(est)

Page 4 of 5 MKC85LA185

Administrative Information

Investigator In Charge (IIC): Roth, Eugene

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=34007

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 MKC85LA185