



# **Aviation Investigation Final Report**

Location: LAWRENCE, Kansas Accident Number: MKC86LA047

Date & Time: January 9, 1986, 03:00 Local Registration: N38127

Aircraft: PIPER PA-32R-300 Aircraft Damage: Substantial

**Defining Event:** 1 None

Flight Conducted Under: Part 91: General aviation - Positioning

### **Analysis**

THE PLT STATED HE MISTOOK AN ICE AND SNOW COVERED AREA FOR A TAXIWAY AND TURNED OFF PAST THE ACTUAL TAXIWAY. THE ACFT STRUCK A SNOWBANK WHICH COLLAPSED THE NOSEGEAR. THE BLUE TAXIWAY LIGHT WAS OUT. THIS LIGHT MARKS THE EDGE OF TAXIWAY. THE TAXIWAY WAS FREE OF ICE AND SNOW MAKING IT EASILY DESTINGUISHABLE FROM THE SNOW AND ICE AT IT'S EDGES. THE PLT WAS VERY FAMILIAR WITH THE AIRPORT, HAVING FLOWN IN AND OUT OF THE AIRPORT ON NUMEROUS OCCASIONS. A SIGNIFICANT REDUCTION IN FORWARD SPEED AFTER LANDING IS REQUIRED BEFORE EXECUTING A TURN TO THE TAXIWAY.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

#### **Findings**

1. (C) TERRAIN CONDITION - SNOWBANK

2. (C) VISUAL LOOKOUT - NOT MAINTAINED - PILOT IN COMMAND

- 3. (C) COMPLACENCY PILOT IN COMMAND 4. (F) LIGHT CONDITION DARK NIGHT

Page 2 of 5 MKC86LA047

## **Factual Information**

#### **Pilot Information**

Certificate:	Airline transport; Commercial	Age:	28,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	May 15, 1985
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	4615 hours (Total, all aircraft), 350 hours (Total, this make and model), 4510 hours (Pilot In Command, all aircraft), 63 hours (Last 90 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

## **Aircraft and Owner/Operator Information**

Aircraft Make:	PIPER	Registration:	N38127
Model/Series:	PA-32R-300 PA-32R-300	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	7780387
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	May 1, 1985 100 hour	Certified Max Gross Wt.:	3400 lbs
Time Since Last Inspection:	70 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	5217 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	IO-540K1G5D
Registered Owner:	PRIORITY AIR	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	On-demand air taxi (135)
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 MKC86LA047

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Night/dark
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	KANSAS CITY , MO (MKC )	Type of Flight Plan Filed:	VFR
Destination:	LAWRENCE , KS (3LA)	Type of Clearance:	None
Departure Time:	02:45 Local	Type of Airspace:	Class E

#### **Airport Information**

Airport:	LAWRENCE 3LA	Runway Surface Type:	Asphalt
Airport Elevation:	834 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	1	IFR Approach:	None
Runway Length/Width:	3900 ft / 75 ft	VFR Approach/Landing:	Traffic pattern

### **Wreckage and Impact Information**

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	39.020263,-95.210433(est)

Page 4 of 5 MKC86LA047

#### **Administrative Information**

Investigator In Charge (IIC):	Thorpe, Clint	
Additional Participating Persons:	LOREN NEWTON; WICHITA , KS	
Original Publish Date:		
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=34127	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 MKC86LA047