

Aviation Investigation Final Report

Location:	HEPHZIBAH, Georg	ia	Accident Number:	ATL94LA144
Date & Time:	July 24, 1994, 13:00) Local	Registration:	N4030S
Aircraft:	HILLER	UH-12E	Aircraft Damage:	Substantial
Defining Event:			Injuries:	1 None
Flight Conducted Under:	Part 137: Agricultur	al		

Analysis

THE COMMERCIAL AG PILOT WAS ABOUT 5 MINUTES INTO HIS FLIGHT WHEN THE ENGINE LOST POWER AND QUIT. DURING THE AUTOROTATION, THE HELICOPTER LANDED HARD, AND THE TAIL BOOM CONTACTED THE GROUND. THE PILOT REPORTED THAT HE BEGAN THE FLIGHT WITH ABOUT 10 GALLONS OF FUEL, WHICH HE MEASURED WITH A DIP STICK THAT HE CARRIED IN THE COCKPIT. HE STATED THAT THE EXPECTED FUEL CONSUMPTION WAS ABOUT 15 GALLONS PER HOUR. THE FUEL SYSTEM SURVIVED THE ACCIDENT INTACT. FAA INSPECTORS FOUND NO EVIDENCE OF FUEL IN THE TANK OR IN THE LINES. THE FUEL GAUGE INDICATED EMPTY.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S INADEQUATE PREFLIGHT OF THE AIRCRAFT, RESULTING IN FUEL EXHAUSTION, AND HIS IMPROPER FLARE OF THE HELICOPTER DURING THE AUTOROTATION, RESULTING IN A HARD LANDING.

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL Phase of Operation: CRUISE

Findings 1. (C) FLUID, FUEL - EXHAUSTION 2. (C) AIRCRAFT PREFLIGHT - INADEQUATE - PILOT IN COMMAND

Occurrence #2: FORCED LANDING Phase of Operation: DESCENT - UNCONTROLLED

Occurrence #3: HARD LANDING Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings 3. (C) FLARE - IMPROPER - PILOT IN COMMAND

Factual Information

On July 24, 1994, at 1300 eastern daylight time, a Hiller UH-12E, N4030S, was substantially damaged following an engine power loss and autorotation in Hephzibah, Georgia. The commercial pilot was not injured. The helicopter was operated under 14 CFR Part 137 by Custom Air Brewton, Inc. of Brewton, Alabama. Visual meteorological conditions existed at the time, and no flight plan was filed for the aerial application flight. The flight originated in Wrens, Georgia at 1255.

The pilot reported that he had completed spraying operations at one site, and was in transit to another field (an estimated 6 to 8 minute flight). He estimated his fuel on board to be about 10 gallons. He used a dip stick that he carried in the cockpit to gauge the fuel quantity. He also reported that the normal fuel consumption was about 15 gallons per hour. During low altitude cruise, about 5 minutes into the flight, the engine lost power and quit. An autorotation was attempted. The helicopter landed hard, and the tail rotor contacted the ground.

Inspectors from the Federal Aviation Administration visited the accident site and inspected the helicopter. They reported that the aircraft fuel system was not damaged, and that there was no evidence of fuel in the tank or in any fuel line. The fuel quantity gauge indicated empty.

Thethethethethethethethethethethethetheth			
Certificate:	Commercial	Age:	31,Male
Airplane Rating(s):	None	Seat Occupied:	Center
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	December 30, 1993
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	2450 hours (Total, all aircraft), 725 hours (Total, this make and model), 100 hours (Last 90 days, all aircraft), 40 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Pilot Information

Aircraft and Owner/Operator Information

Aircraft Make:	HILLER	Registration:	N4030S
Model/Series:	UH-12E UH-12E	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	HA-3082
Landing Gear Type:	Skid	Seats:	
Date/Type of Last Inspection:	January 11, 1994 Annual	Certified Max Gross Wt.:	3100 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	VO-540-C2A
Registered Owner:	CUSTOM AIR BREWTON, INC.	Rated Power:	305 Horsepower
Operator:	CUSTOM AIR BREWTON, INC.	Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	AGS ,145 ft msl	Distance from Accident Site:	8 Nautical Miles
Observation Time:	13:17 Local	Direction from Accident Site:	60°
Lowest Cloud Condition:	Scattered / 2900 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	250°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	31°C / 24°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	WRENS , GA (NONE)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	12:55 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	33.280075,-82.100746(est)

Administrative Information

Investigator In Charge (IIC):	Hicks, Ralph
Additional Participating Persons:	CHARLES H GALLOWAY; COLLEGE PARK , GA JAMES D STRICKLAND; COLLEGE PARK , GA DUDLEY BOONE; COLLEGE PARK , GA
Original Publish Date:	November 14, 1994
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=3422

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.