



Aviation Investigation Final Report

Location: DUANESBURG, New York Accident Number: NYC83LA167

Date & Time: July 4, 1983, 14:45 Local Registration: N2842A

Aircraft: CESSNA 180 Aircraft Damage: Substantial

Defining Event: 3 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PLT LANDED THE TAILWHEEL EQUIPPED ACFT IN A 15 KT, LEFT X-WIND. DURING THE LANDING, THE ACFT VEERED TO THE LEFT INTO A ROUGH AREA, GROUND LOOPED & CAME TO REST IN A DITCH. THE PLT STATED THAT THE RIGHT BRAKE FAILED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

Findings

1. (F) WEATHER CONDITION - CROSSWIND

- 2. (C) LANDING GEAR, NORMAL BRAKE SYSTEM FAILURE, PARTIAL
- 3. (C) DIRECTIONAL CONTROL NOT POSSIBLE PILOT IN COMMAND
- 4. (F) GROUND LOOP/SWERVE UNCONTROLLED PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Findings

- 5. (F) TERRAIN CONDITION ROUGH/UNEVEN 6. (F) TERRAIN CONDITION DITCH

NYC83LA167 Page 2 of 5

Factual Information

Pilot Information

| Certificate: | Commercial | Age: | 33,Male |
|---------------------------|---|-----------------------------------|------------------|
| Airplane Rating(s): | Single-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | | Restraint Used: | |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | | Toxicology Performed: | No |
| Medical Certification: | Class 2 Valid Medicalno waivers/lim. | Last FAA Medical Exam: | October 18, 1982 |
| Occupational Pilot: | UNK | Last Flight Review or Equivalent: | |
| Flight Time: | 968 hours (Total, all aircraft), 550 hours (Total, this make and model), 550 hours (Pilot In Command, all aircraft), 22 hours (Last 90 days, all aircraft), 5 hours (Last 24 hours, all aircraft) | | |

Aircraft and Owner/Operator Information

| Aircraft Make: | CESSNA | Registration: | N2842A |
|-------------------------------|-----------------------|-----------------------------------|-----------------|
| Model/Series: | 180 180 | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 30042 |
| Landing Gear Type: | Tailwheel | Seats: | 4 |
| Date/Type of Last Inspection: | June 1, 1983 100 hour | Certified Max Gross Wt.: | 2550 lbs |
| Time Since Last Inspection: | 25 Hrs | Engines: | 1 Reciprocating |
| Airframe Total Time: | 4200 Hrs | Engine Manufacturer: | CONTINENTAL |
| ELT: | Not installed | Engine Model/Series: | 0-470-J |
| Registered Owner: | LARRY A. DYER | Rated Power: | 225 Horsepower |
| Operator: | | Operating Certificate(s) Held: | None |
| Operator Does Business As: | | Operator Designator Code: | |

Page 3 of 5 NYC83LA167

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|------------------------------|--------------------------------------|----------|
| Observation Facility, Elevation: | | Distance from Accident Site: | |
| Observation Time: | | Direction from Accident Site: | |
| Lowest Cloud Condition: | Clear | Visibility | 20 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 15 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 180° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 30 inches Hg | Temperature/Dew Point: | 29°C |
| Precipitation and Obscuration: | No Obscuration; No Precipita | ation | |
| Departure Point: | | Type of Flight Plan Filed: | None |
| Destination: | | Type of Clearance: | None |
| Departure Time: | 00:00 Local | Type of Airspace: | Class G |

Airport Information

| Airport: | DUANESBURG 4B1 | Runway Surface Type: | Gravel |
|----------------------|-----------------|----------------------------------|-----------|
| Airport Elevation: | 710 ft msl | Runway Surface Condition: | |
| Runway Used: | 28 | IFR Approach: | None |
| Runway Length/Width: | 2800 ft / 50 ft | VFR Approach/Landing: | Full stop |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|------------------------|--------|-------------------------|--------------------------|
| Passenger Injuries: | 2 None | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 3 None | Latitude, Longitude: | 42.76049,-74.130287(est) |

Page 4 of 5 NYC83LA167

Administrative Information

| Investigator In Charge (IIC): | Taylor, Vernon |
|-----------------------------------|--|
| Additional Participating Persons: | |
| Original Publish Date: | |
| Last Revision Date: | |
| Investigation Class: | <u>Class</u> |
| Note: | |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=35223 |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 NYC83LA167