



# **Aviation Investigation Final Report**

Location: MANAHAWKIN, New Jersey Accident Number: NYC85LA196

Date & Time: July 27, 1985, 11:30 Local Registration: N6887B

Aircraft: CESSNA 425 Aircraft Damage: Substantial

**Defining Event:** 4 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

AFTER OVERFLYING THE AIRFLD AND DECIDING TO LAND ON RWY 22, THE PLT CONCENTRATED ON THE AIRSPEED AND ALT OF THE ACFT. A TWR EAST OF THE FLT WAS NOTICED AND WAS NOT CONSIDERED A PROBLEM. DURING THE FINAL APCH, THE PLT WAS DISTRACTED BY A PASSENGER WHO SAID TO WATCH OUT FOR THE TWR. THE PLT LOOKED FOR THE TWR AND CONTINUED THE APCH. AT ABOUT 800 FT FRON THE THRESHOLD, THE PLT REDUCED PWR TO LOSE ALT AND INADVERTENTLY PULLED THE PWR LEVERS INTO REVERSE. THE ACFT LOST AIRSPEED QUICKLY AND LANDED APRX 40 FT SHORT OF THE RWY IN SOFT SAND. THE ACFT COLLIDED WITH THE ASPHALT RWY AND BECAME AIRBORNE. THE ACFT LANDED HARD ON THE RWY APRX 100 FT PAST THE THRESHOLD AND VEERED LEFT. THE LEFT MAIN LANDING GEAR ROLLED OFF THE LEFT SIDE OF THE RWY AND COLLAPSED.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: UNDERSHOOT

Phase of Operation: LANDING - FLARE/TOUCHDOWN

**Findings** 

1. (C) PROPELLER SYSTEM/ACCESSORIES, REVERSING SYSTEM - ENGAGED

2. (C) THROTTLE/POWER CONTROL - IMPROPER USE OF - PILOT IN COMMAND

3. (C) AIRSPEED - NOT MAINTAINED - PILOT IN COMMAND

4. (F) DESCENT - EXCESSIVE - PILOT IN COMMAND

------

Occurrence #2: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

#### **Findings**

5. (C) RECOVERY FROM BOUNCED LANDING - IMPROPER - PILOT IN COMMAND

-----

Occurrence #3: LOSS OF CONTROL - ON GROUND/WATER

Phase of Operation: LANDING - ROLL

#### **Findings**

6. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

-----

Occurrence #4: MAIN GEAR COLLAPSED Phase of Operation: LANDING - ROLL

#### **Findings**

7. (F) TERRAIN CONDITION - LOOSE GRAVEL/SANDY

8. LANDING GEAR, MAIN GEAR - OVERLOAD

Page 2 of 6 NYC85LA196

## **Factual Information**

### **Pilot Information**

Certificate:	Private	Age:	51,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	May 2, 1985
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	2570 hours (Total, all aircraft), 180 hours (Total, this make and model), 2170 hours (Pilot In Command, all aircraft), 7 hours (Last 90 days, all aircraft)		

Page 3 of 6 NYC85LA196

## **Aircraft and Owner/Operator Information**

Aircraft Make:	CESSNA	Registration:	N6887B
Model/Series:	425 425	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:		Serial Number:	425-0163
Landing Gear Type:	Retractable - Tricycle	Seats:	8
Date/Type of Last Inspection:	Annual	Certified Max Gross Wt.:	8200 lbs
Time Since Last Inspection:		Engines:	2 Turbo prop
Airframe Total Time:	635 Hrs	Engine Manufacturer:	P&W
ELT:	Installed, not activated	Engine Model/Series:	PT6A-112
Registered Owner:	TELECOMMUNICATIONS SYSTEM,INC.	Rated Power:	450 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

## Meteorological Information and Flight Plan

3			
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	ACY	Distance from Accident Site:	
Observation Time:	10:50 Local	Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Scattered / 1000 ft AGL	Visibility	7 miles
Lowest Ceiling:	Broken / 3000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	22°C / 18°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	WHITE PLAINS , NY (HPN )	Type of Flight Plan Filed:	IFR
Destination:	MANAHAWKIN , NJ (72N )	Type of Clearance:	IFR
Departure Time:	10:40 Local	Type of Airspace:	Class G

Page 4 of 6 NYC85LA196

## **Airport Information**

Airport:	MANAHAWKIN 82N	Runway Surface Type:	Asphalt
Airport Elevation:	46 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	22	IFR Approach:	None
Runway Length/Width:	2696 ft / 50 ft	VFR Approach/Landing:	Full stop;Traffic pattern

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	3 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	4 None	Latitude, Longitude:	

Page 5 of 6 NYC85LA196

#### **Administrative Information**

Investigator In Charge (IIC):	Taylor, Vernon
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=35933

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 NYC85LA196