

Aviation Investigation Final Report

Location:	WESTERLY, Rhode	Island	Accident Number:	NYC91LA201
Date & Time:	August 6, 1991, 07	:50 Local	Registration:	N30837
Aircraft:	PIPER	J3-C65	Aircraft Damage:	Substantial
Defining Event:			Injuries:	2 None
Flight Conducted Under:	Part 91: General av	viation - Personal		

Analysis

THE PILOT STATED THAT SHE EXPERIENCED A PARTIAL POWER LOSS AFTER TAKEOFF WHILE CLIMBING THROUGH 300 FEET AGL. SHE SUBSEQUENTLY ATTEMPTED TO TURN BACK TO THE AIRPORT, HOWEVER, DURING THE TURN THE AIRPLANE DEVELOPED A DESCENT RATE AND THE PILOT CHANGED HER INTENDED FORCED LANDING AREA TO A STREET RATHER THAN IN FRONT OF THE AIRPORT TERMINAL. ON SHORT FINAL, THE AIRPLANE STRUCK A CHAIN LINK FENCE AND CONTROL WAS LOST. THE AIRPLANE CAME TO REST IN FRONT OF THE TERMINAL. THE REASON FOR THE POWER LOSS WAS NOT DETERMINED DURING THE INVESTIGATION.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: ENGINE FAILURE FOR AN UNDETERMINED REASON. A FACTOR WAS THE PILOT MISJUDGING THE CLEARANCE OVER A FENCE DURING AN ATTEMPTED FORCED LANDING.

Findings

Occurrence #1: LOSS OF ENGINE POWER Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings 1. (F) POWERPLANT - FAILURE, PARTIAL 2. (F) REASON FOR OCCURRENCE UNDETERMINED -----

Occurrence #2: FORCED LANDING Phase of Operation: DESCENT - EMERGENCY

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER Phase of Operation: LANDING

Findings 3. OBJECT - FENCE 4. (C) CLEARANCE - MISJUDGED - PILOT IN COMMAND

Factual Information

Pilot Information

T not information			
Certificate:	Private	Age:	52,Female
Airplane Rating(s):	Single-engine land	Seat Occupied:	Rear
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	May 24, 1991
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1000 hours (Total, all aircraft), 40 hours (Total, this make and model), 1000 hours (Pilot In Command, all aircraft), 10 hours (Last 90 days, all aircraft), 1 hours (Last 30 days, all aircraft), 1 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:PIPERRegistration:N30837Model/Series:J3-C65 J3-C65Aircraft Category:AirplaneYear of Manufacture:Amateur Built:Airworthiness Certificate:NormalSerial Number:5137Ainding Gear Type:TricycleSeats:2Date/Type of Last Inspection:August 19, 1990 AnnualCertified Max Gross Wt::1500 lbsTime Since Last Inspection:96 HrsEngines:1 ReciprocatingAirframe Total Time:6188 HrsEngine Manufacturer:CONTINENTALELT:Installed, activated, did not adi in locating accidentRated Power:65 HorsepowerOperator:CUB CLUB, INCOperating Certificate(s) Rediscured SeriesNoneOperator Does Business As:UB CLUB, INCOperator Does Gusines Certificate(s)None				
Year of Manufacture:Amateur Built:Airworthiness Certificate:NormalSerial Number:5137Landing Gear Type:TricycleSeats:2Date/Type of Last Inspection:August 19, 1990 AnnualCertified Max Gross Wt.:1500 lbsTime Since Last Inspection:96 HrsEngines:1 ReciprocatingAirframe Total Time:6188 HrsEngine Manufacturer:CONTINENTALELT:Installed, activated, did not al In locating accidentFace Power:65 HorsepowerQuest Owner:CUB CLUB, INCRated Power:65 HorsepowerOperator:CUB CLUB, INCOperating Certificate(s) RedieNone	Aircraft Make:	PIPER	Registration:	N30837
Airworthiness Certificate:NormalSerial Number:5137Landing Gear Type:TricycleSeats:2Date/Type of Last Inspection:August 19,1990 AnnualCertified Max Gross Wt.:1500 lbsTime Since Last Inspection:96 HrsEngines:1 ReciprocatingAirframe Total Time:6188 HrsEngine Manufacturer:0 CONTINENTALELT:Installed, activated, did not adi In locating accidentRated Power:65 HorsepowerOperator:CUB CLUB, INCRated Power:05 Horsepower	Model/Series:	J3-C65 J3-C65	Aircraft Category:	Airplane
Landing Gear Type:TricycleSeats:2Date/Type of Last Inspection:August 19, 1990 AnnualCertified Max Gross Wt.:1500 lbsTime Since Last Inspection:96 HrsEngines:1 ReciprocatingAirframe Total Time:6188 HrsEngine Manufacturer:CONTINENTALELT:Installed, activated, did not aid in locating accidentEngine Model/Series:A65-8Registered Owner:CUB CLUB, INCRated Power:65 HorsepowerOperator:CUB CLUB, INCOperating Certificate(s) Held:None	Year of Manufacture:		Amateur Built:	
Date/Type of Last Inspection:August 19, 1990 AnnualCertified Max Gross Wt.:1500 lbsTime Since Last Inspection:96 HrsEngines:1 ReciprocatingAirframe Total Time:6188 HrsEngine Manufacturer:CONTINENTALELT:Installed, activated, did not aid in locating accidentEngine Model/Series:A65-8Registered Owner:CUB CLUB, INCRated Power:65 HorsepowerOperator:CUB CLUB, INCOperating Certificate(s) Held:None	Airworthiness Certificate:	Normal	Serial Number:	5137
Inspection:Sender Sender S	Landing Gear Type:	Tricycle	Seats:	2
Airframe Total Time:6188 HrsEngine Manufacturer:CONTINENTALELT:Installed, activated, did not aid in locating accidentEngine Model/Series:A65-8Registered Owner:CUB CLUB, INCRated Power:65 HorsepowerOperator:CUB CLUB, INCOperating Certificate(s) Held:None		August 19, 1990 Annual	Certified Max Gross Wt.:	1500 lbs
ELT:Installed, activated, did not aid in locating accidentEngine Model/Series:A65-8Registered Owner:CUB CLUB, INCRated Power:65 HorsepowerOperator:CUB CLUB, INCOperating Certificate(s) Held:None	Time Since Last Inspection:	96 Hrs	Engines:	1 Reciprocating
Registered Owner:CUB CLUB, INCRated Power:65 HorsepowerOperator:CUB CLUB, INCOperating Certificate(s) Held:None	Airframe Total Time:	6188 Hrs	Engine Manufacturer:	CONTINENTAL
Operator: CUB CLUB, INC Operating Certificate(s) None Held:	ELT:		Engine Model/Series:	A65-8
Held:	Registered Owner:	CUB CLUB, INC	Rated Power:	65 Horsepower
Operator Does Business As: Operator Designator Code:	Operator:	CUB CLUB, INC		None
	Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 25000 ft AGL	Visibility	15 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	310°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	17°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	07:50 Local	Type of Airspace:	Airport advisory area

Airport Information

Airport:	WESTERLY STATE WST	Runway Surface Type:	Asphalt
Airport Elevation:	81 ft msl	Runway Surface Condition:	Dry
Runway Used:	32	IFR Approach:	None
Runway Length/Width:	4000 ft / 150 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	Wandel, Warren	
Additional Participating Persons:	WILLIAM M STEVENS; BEDFORD , MA	
Original Publish Date:	April 27, 1993	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=36981	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.