

Aviation Investigation Final Report

Location: DAYTONA BEACH, Florida Accident Number: ATL97LA028

Date & Time: December 26, 1996, 12:49 Local Registration: N737JC

Aircraft: Mooney M20F Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

Because the flight was taking longer than expected, the pilot elected to divert for fuel. While being vectored for an approach, the engine quit. During the ensuing forced landing, the airplane collided with trees and the ground. There was no evidence of a loss of fuel during the flight nor at the accident site, and the engine was operated following the accident. However, testing of the fuel injector servo revealed that its flow exceeded the maximum limit. The pilot stated he was using 11 gallons per hour for fuel usage planning. Using the power setting and altitude the pilot reported he used during the flight, the engine manufacturers operating manual indicated that the fuel usage would be between 11.3 and 13 gallons per hour (gph), depending on the mixture setting. Based on the elapsed time of the flight, the usable fuel supply in the airplane, and the excessive fuel servo flow, at 11.3 gph, about six gallons of fuel would have remained in the airplane. At 13 gph, more fuel than the usable capacity would have been needed. The fuel usage, therefore, exceeded the pilot's planned usage, discounting the servo's excessive flow rate.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's inadequate in-flight fuel consumption calculations, and the excessive flow of the fuel injector servo, that combined to result in fuel exhaustion.

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: DESCENT

Findings

1. (C) FUEL CONSUMPTION CALCULATIONS - INADEQUATE - PILOT IN COMMAND

2. (C) FUEL SYSTEM, INJECTOR - EXCESSIVE FLOW/OUTPUT

3. (C) FLUID, FUEL - EXHAUSTION

Occurrence #2: FORCED LANDING

Phase of Operation: EMERGENCY DESCENT/LANDING

Occurrence #3: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: EMERGENCY DESCENT/LANDING

Findings

4. OBJECT - TREE(S)

Page 2 of 6 ATL97LA028

Factual Information

On December 26, 1996, about 1248 eastern standard time, a Mooney M20F, N737JC, collided with trees and the ground about two miles from the approach end of runway 7L at Daytona Beach, Florida. The airplane was operated by the pilot under the provisions of Title 14 CFR Part 91, and visual flight rules. An instrument flight plan had been filed for the personal flight. There were no injuries to the private pilot, who was instrument rated, nor the passenger, and the airplane was substantially damaged. Origination of the flight was Elizabeth City, North Carolina, about 0822, on the same day.

According to air traffic personnel, the flight was originally destined for Melbourne, Florida. While the flight was in contact with Jacksonville Air Route Traffic Control Center, the destination was changed to Daytona Beach, Florida. The pilot reported critical fuel when about seven miles from Daytona Beach International Airport. Subsequently, about two miles from the airport, the pilot reported that the airplane would not reach the runway.

The FAA inspector who visited the accident site reported no evidence of siphoned fuel, no evidence of fuel on the ground, and no a fuel odor.

From the departure time until the pilot reported a loss of engine power, 4.5 hours elapsed. According to a record of telephone conversation between the FAA inspector and the airplane fueler, the fuel tanks were filled to their capacity of 64 usable gallons. The pilot reported that he used 11 gallons per hour to calculate the fuel usage, which was consistent with the owners manual for the 1967 airplane. At 11 gallons per hour and 4.5 hours elapsed flight time the total fuel usage would be 49.5 gallons. Fuel used for taxi, run-up, and takeoff was not listed in the owner's manual.

A post accident flow test of the fuel servo unit revealed in the servo exceeding the upper flow limit by 1 2/3 gallons per hour (see attached report) or 7.47 gallons for the 4.5 hour flight. Using the Lycoming Operator's Manual, the fuel flow at the pilot's described flight conditions of 4,000 feet mean sea level, 23 inches manifold pressure, and 2500 rpm, was 11.3 gallons per hour at best economy mixture setting, and 13.0 gallons per hour at best power mixture setting. Based on these figures the fuel expected to be used during the 4.5 hour flight would be as follows:

best economy: 4.5 hours X 11.3 gallons/hour = 50.85 + 7.47 gallons = 58.32 gallons best power:4.5 hours X 13 gallons /hour = 58.5 + 7.47 gallons = 65.97. Normally expected fuel for start, taxi, and run up is two to four gallons.

Page 3 of 6 ATL97LA028

Pilot Information

Certificate:	Private	Age:	64,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	April 16, 1996
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	1780 hours (Total, all aircraft), 24 hours (Total, this make and model), 1687 hours (Pilot In Command, all aircraft), 24 hours (Last 90 days, all aircraft), 13 hours (Last 30 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Mooney	Registration:	N737JC
Model/Series:	M20F M20F	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	670376
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	September 12, 1996 Annual	Certified Max Gross Wt.:	2740 lbs
Time Since Last Inspection:	24 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	6552 Hrs	Engine Manufacturer:	Lycoming
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	IO-360-A1A
Registered Owner:	TWIN AIR TRANSPORT CORPORATION	Rated Power:	200 Horsepower
Operator:	THEODORE R. COLEMAN	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 4 of 6 ATL97LA028

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	DAB ,35 ft msl	Distance from Accident Site:	3 Nautical Miles
Observation Time:	12:53 Local	Direction from Accident Site:	70°
Lowest Cloud Condition:	Scattered / 2300 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	5 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	24°C / 19°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	ELIZABETH CITY , NC (ECG)	Type of Flight Plan Filed:	IFR
Destination:	(DAB)	Type of Clearance:	IFR
Departure Time:	08:22 Local	Type of Airspace:	Class C

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	Localizer only
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	29.189174,-81.050682(est)

Page 5 of 6 ATL97LA028

Administrative Information

Investigator In Charge (IIC): Hicks, Preston **Additional Participating** S STRICKLAND; ORLANDO , FL Persons: JOHN MURPHY; ORLANDO , FL **Original Publish Date:** September 5, 1997 **Last Revision Date:** Investigation Class: Class Note: **Investigation Docket:** https://data.ntsb.gov/Docket?ProjectID=3814

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ATL97LA028