

Aviation Investigation Final Report

| Location: | CUMMING, Georg | ia | Accident Number: | MIA97LA106 |
|-------------------------|--------------------|--------------------|----------------------|-------------|
| Date & Time: | March 30, 1997, 0 | 9:00 Local | Registration: | N3201Z |
| Aircraft: | Piper | PA22-150 | Aircraft Damage: | Substantial |
| Defining Event: | | | Injuries: | 1 None |
| Flight Conducted Under: | Part 91: General a | viation - Personal | | |

Analysis

While in cruise flight the pilot noticed a decrease in engine RPM's. He switched fuel tanks and applied carburetor heat. He further stated that the only thing that helped was the 'in and out motion on the throttle.' The engine did not regain power so the pilot attempted a forced landing in a pasture, which resulted in impact with the ground. The engine was removed from the airplane and placed on a test stand and run with all the original parts that were on the engine at the time of the accident with the exception of the carburetor. The carburetor had sustained impact damage and the throttle valve was separated from the body of the carburetor. The engine test run did not reveal any discrepancies. The carburetor was disassembled and the gasket was found dry and in pieces. There was no fuel found in the bowl.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: a loss of engine power for an undermined reason, which resulted in a forced landing and subsequent impact with the ground.

Findings

Occurrence #1: LOSS OF ENGINE POWER Phase of Operation: CRUISE

Findings

1. 1 ENGINE - UNDETERMINED

Occurrence #2: FORCED LANDING Phase of Operation: EMERGENCY DESCENT/LANDING

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: EMERGENCY DESCENT/LANDING

Findings 2. TERRAIN CONDITION - GROUND

Factual Information

On March 30, 1997, about 0900 eastern standard time, a Piper PA-22-150, N3201Z, registered to a private owner, crashed during a forced landing near Cumming, Georgia. Visual meteorological conditions prevailed at the time and no flight plan was filed for the Title 14 CFR Part 91 local personal flight. The private-rated pilot was not injured. The airplane was substantially damaged. The fight had originated about 15 minutes before the accident.

The airplane was in cruise flight when the pilot noticed a "decrease in engine RPM's." The pilot switched fuel tanks and applied carburetor heat. He further stated that the only thing that helped was the "in and out motion on the throttle." The engine did not regain power so the pilot attempted a forced landing in a pasture, which resulted in impact with the ground.

The engine was removed from the airplane and examined at Lycoming Engine's facilities in Williamsport, Pennsylvania, July 2, 1997, under the supervision of the FAA. The engine was placed on a test stand and run with all the original parts that were on the engine at the time of the accident with the exception of the carburetor. The carburetor had impact damage and the throttle was separated from the body of the carburetor. The engine test run did not reveal any discrepancies.

The carburetor was shipped to the NTSB Southeast Regional office, Miami, Florida, were it was disassembled. The carburetor was received with all safety wires attached, and throttle valve which was laying separate from the body of the carburetor. The carburetor was disassembled and the gasket was found dry and in pieces. There was no fuel found in the bowl. The float retention valve pin was in place, and the needle valve operated.

The engine was released on July 11, 1997, and shipped from Lycoming's factory on the same day, under shipping order No. P597459. The carburetor was shipped on the same day from the NTSB Southeast Regional office, Miami, Florida.

Pilot Information

| Certificate: | Private | Age: | 60,Male |
|---------------------------|---|-----------------------------------|-------------------|
| Airplane Rating(s): | Single-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | None | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 3 Valid Medicalw/ waivers/lim | Last FAA Medical Exam: | November 24, 1995 |
| Occupational Pilot: | UNK | Last Flight Review or Equivalent: | |
| Flight Time: | 1201 hours (Total, all aircraft), 400 hours (Total, this make and model), 900 hours (Pilot In Command, all aircraft) | | |

Aircraft and Owner/Operator Information

| Aircraft Make: | Piper | Registration: | N3201Z |
|----------------------------------|---|-----------------------------------|-----------------|
| Model/Series: | PA22-150 PA22-150 | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 22-7141 |
| Landing Gear Type: | Tricycle | Seats: | 4 |
| Date/Type of Last Inspection: | Annual | Certified Max Gross Wt.: | 2000 lbs |
| Time Since Last Inspection: | 1 Hrs | Engines: | 1 Reciprocating |
| Airframe Total Time: | 1601 Hrs | Engine Manufacturer: | Lycoming |
| ELT: | Installed, activated, did not aid in locating accident | Engine Model/Series: | 0-320 |
| Registered Owner: | MILES R. DUNCAN | Rated Power: | 150 Horsepower |
| Operator: | | Operating Certificate(s) Held: | None |
| Operator Does Business As: | | Operator Designator Code: | |

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|----------------------------------|------------------------------|---|----------|
| Observation Facility, Elevation: | | Distance from Accident Site: | |
| Observation Time: | | Direction from Accident Site: | |
| Lowest Cloud Condition: | Clear | Visibility | 20 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 5 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 270° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 30 inches Hg | Temperature/Dew Point: | 20°C |
| Precipitation and Obscuration: | No Obscuration; No Precipita | ition | |
| Departure Point: | (84A) | Type of Flight Plan Filed: | None |
| Destination: | | Type of Clearance: | None |
| Departure Time: | 08:47 Local | Type of Airspace: | |

Airport Information

| Airport: | | Runway Surface Type: | |
|----------------------|---|---------------------------|----------------|
| Airport Elevation: | | Runway Surface Condition: | |
| Runway Used: | 0 | IFR Approach: | None |
| Runway Length/Width: | | VFR Approach/Landing: | Forced landing |

Wreckage and Impact Information

| Crew Injuries: | 1 None | Aircraft Damage: | Substantial |
|------------------------|--------|-------------------------|-------------|
| Passenger Injuries: | | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 1 None | Latitude, Longitude: | |

Administrative Information

| Investigator In Charge (IIC): | Yurman, Alan | | |
|--------------------------------------|--|--|--|
| Additional Participating Persons: | MARK MEOLA; ATLANTA , GA | | |
| Original Publish Date: | October 14, 1997 | | |
| Last Revision Date: | | | |
| Investigation Class: | <u>Class</u> | | |
| Note: | | | |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=38236 | | |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.