



# **Aviation Investigation Final Report**

Location: STUART, Florida Accident Number: MIA97LA131

Date & Time: April 9, 1997, 14:33 Local Registration: N2HS

Aircraft: Piper PA-34-200 Aircraft Damage: Substantial

**Defining Event:** 3 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

The pilot stated he was landing with a gusty quartering crosswind. He maintained a higher speed to compensate for the gusts, touched down, bounced and the nose gear collided with the runway. Review of weather conditions revealed no recorded record of turbulence, downdrafts, gusts, or windshear.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's failure to maintain directional control during a crosswind landing. Factors were the crosswind and his improper level off.

### **Findings**

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

**Findings** 

1. (F) WEATHER CONDITION - CROSSWIND

2. (F) LEVEL OFF - IMPROPER - PILOT IN COMMAND

-----

Occurrence #2: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - FLARE/TOUCHDOWN

#### Findings

3. (C) DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

------

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

4. TERRAIN CONDITION - RUNWAY

Page 2 of 6 MIA97LA131

#### **Factual Information**

On April 9, 1997, about 1433 eastern daylight time, a Piper PA-34, N2HS, registered to a private owner, operating as a 14 CFR Part 91 personal flight, landed hard at Witham Field, Stuart, Florida. Visual meteorological conditions prevailed and no flight plan was filed. The pilot and two passengers were not injured. The airplane sustained substantial damage. The flight originated from Rock Hill, South Carolina, about 2 hours 48 minutes before the accident.

The pilot stated he was landing with a gusting, quartering crosswind to runway 07. He maintained a higher approach speed to compensate for the gusts. The airplane touched down, bounced and collided with the runway on the nose gear

Review of weather information for the time period of the accident revealed no recorded record of turbulence, downdrafts, gusts, or windshear.

#### **Pilot Information**

Certificate:	Commercial	Age:	66,U
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land; Multi- engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	Glider; Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical-w/ waivers/lim	Last FAA Medical Exam:	April 27, 1995
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:		0 hours (Total, this make and model), st 90 days, all aircraft), 2 hours (Last 2	

Page 3 of 6 MIA97LA131

## **Aircraft and Owner/Operator Information**

Aircraft Make:	Piper	Registration:	N2HS
Model/Series:	PA-34-200 PA-34-200	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	34-8070022
Landing Gear Type:		Seats:	6
Date/Type of Last Inspection:	June 18, 1996 Annual	Certified Max Gross Wt.:	4570 lbs
Time Since Last Inspection:	72 Hrs	Engines:	2 Reciprocating
Airframe Total Time:	3236 Hrs	Engine Manufacturer:	Continental
ELT:	Installed, not activated	Engine Model/Series:	TSI0-360
Registered Owner:	HERBERT SPAUGH JR.	Rated Power:	200 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	MCO,96 ft msl	Distance from Accident Site:	120 Nautical Miles
Observation Time:	13:53 Local	Direction from Accident Site:	330°
<b>Lowest Cloud Condition:</b>	Scattered / 4900 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	40°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	26°C / 13°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	ROCK HILL , SC (29J)	Type of Flight Plan Filed:	None
Destination:	(SUA)	Type of Clearance:	None
Departure Time:	11:45 Local	Type of Airspace:	Class D

Page 4 of 6 MIA97LA131

## **Airport Information**

Airport:	STUART-WHITMAN FIELD SUA	Runway Surface Type:	Asphalt
Airport Elevation:	17 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	7	IFR Approach:	None
Runway Length/Width:	5000 ft / 200 ft	VFR Approach/Landing:	Traffic pattern

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	27.18946,-80.24057(est)

Page 5 of 6 MIA97LA131

#### **Administrative Information**

Investigator In Charge (IIC):	Martinez, Ana	
Additional Participating Persons:	GEORGE FRANCIONE; FORT LAUDERDALE, FL	
Original Publish Date:	September 5, 1997	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=38257	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 MIA97LA131