



# **Aviation Investigation Final Report**

Location: BURNSVILLE, North Carolina Accident Number: MIA97LA218

Date & Time: July 27, 1997, 14:30 Local Registration: N9396P

Aircraft: Piper PA-24-260 Aircraft Damage: Substantial

**Defining Event:** 2 Minor, 2 None

Flight Conducted Under: Part 91: General aviation - Personal

### **Analysis**

Before takeoff the pilot failed to verify that the main cabin door was closed and latched. After takeoff the door opened and he maneuvered the airplane to land in the opposite direction than for takeoff. He stated that he became distracted due to the perceived emergency and landed about 6 feet short of the runway on upsloping terrain. The left main landing gear then separated from the airplane which bounced onto then off the runway into a 25-foot deep ravine where the airplane came to rest upright.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The failure of the pilot to use the checklist to confirm that the main cabin door was closed and locked before takeoff. Also, failure of the pilot to attain the proper touchdown point during the precautionary landing. Contributing to the accident was the self induced pressure by the pilot.

### **Findings**

Occurrence #1: UNDERSHOOT

Phase of Operation: LANDING - FLARE/TOUCHDOWN

#### **Findings**

1. (C) CHECKLIST - NOT FOLLOWED - PILOT IN COMMAND

2. DOOR - OPEN

- 3. (C) PROPER TOUCHDOWN POINT NOT ATTAINED PILOT IN COMMAND 4. (F) SELF-INDUCED PRESSURE PILOT IN COMMAND

Page 2 of 6 MIA97LA218

#### **Factual Information**

On July 27, 1997, about 1430 eastern daylight time, a Piper PA-24-260, N9396P, coregistered to private individuals, landed short during a precautionary landing shortly after takeoff from the Mountain Air Airport, a private airstrip near Burnsville, North Carolina. Visual meteorological conditions prevailed at the time and no flight plan was filed for the 14 CFR Part 91 personal flight. The airplane was substantially damaged and the commercial-rated pilot and two passengers were not injured. The right front seat passenger sustained minor injuries. The flight originated about 2 minutes earlier.

The pilot stated that before takeoff he failed to check that the main cabin door was closed and latched. Shortly after takeoff his wife in the right front seat noted that the cabin door was ajar. He maneuvered the airplane to return for landing on the opposite direction used for departure. He stated that he became distracted by the perceived emergency and landed about 6 feet short on upsloping terrain. The left main landing gear separated and the airplane bounced onto the runway, veered off the left side of the runway into a 25-feet deep ravine and came to rest upright.

#### **Pilot Information**

Certificate:	Commercial	Age:	47,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	January 15, 1997
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	1190 hours (Total, all aircraft), 125 hours (Total, this make and model), 1025 hours (Pilot In Command, all aircraft), 29 hours (Last 90 days, all aircraft), 22 hours (Last 30 days, all aircraft)		

Page 3 of 6 MIA97LA218

## **Aircraft and Owner/Operator Information**

Aircraft Make:	Piper	Registration:	N9396P
Model/Series:	PA-24-260 PA-24-260	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	24-4899
Landing Gear Type:	Retractable - Tricycle	Seats:	4
Date/Type of Last Inspection:	February 10, 1997 Annual	Certified Max Gross Wt.:	3200 lbs
Time Since Last Inspection:	33 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	3187 Hrs	Engine Manufacturer:	Lycoming
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	IO-540-N1A5
Registered Owner:	KRISTAN R. MAYNARD	Rated Power:	260 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	AVL ,2165 ft msl	Distance from Accident Site:	27 Nautical Miles
Observation Time:	14:54 Local	Direction from Accident Site:	205°
<b>Lowest Cloud Condition:</b>	Clear	Visibility	6 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	7 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	10°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	28°C / 23°C
Precipitation and Obscuration:	N/A - None - Haze		
Departure Point:	(2NC0)	Type of Flight Plan Filed:	None
Destination:	INDIANAPOLIS , IN (UMP)	Type of Clearance:	None
Departure Time:	14:28 Local	Type of Airspace:	Class G

Page 4 of 6 MIA97LA218

## **Airport Information**

Airport:	MOUNTAIN AIR AIRPORT 2NC0	Runway Surface Type:	Asphalt
Airport Elevation:	4432 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	32	IFR Approach:	
Runway Length/Width:	2900 ft / 50 ft	VFR Approach/Landing:	Full stop;Precautionary landing

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 Minor, 1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 Minor, 2 None	Latitude, Longitude:	35.909988,-82.290367(est)

Page 5 of 6 MIA97LA218

#### **Administrative Information**

Investigator In Charge (IIC):	Monville, Timothy	
Additional Participating Persons:	WILLIAM D SEXTON; CHARLOTTE , NC	
Original Publish Date:	February 2, 1998	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=38316	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 MIA97LA218