



Aviation Investigation Final Report

| Location: | LAKE MURRAY, So | uth Carolina | Accident Number: | MIA98LA086 |
|-------------------------|---------------------|--------------------|------------------|-------------|
| Date & Time: | February 25, 1998, | 14:55 Local | Registration: | N3020P |
| Aircraft: | Lake | LA-4-200 | Aircraft Damage: | Substantial |
| Defining Event: | | | Injuries: | 3 Serious |
| Flight Conducted Under: | Part 91: General av | viation - Personal | | |
| | | | | |

Analysis

The amphibian airplane collided with a partially submerged object during a water landing that ripped and crushed the hull, below the water line, from the nose cone to the left side cockpit door. The airplane subsequently nosed over and submerged in the water..

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A collision with an unknown submerged.

Findings

Occurrence #1: ON GROUND/WATER COLLISION WITH OBJECT Phase of Operation: LANDING

Findings
1. (C) OBJECT - SUBMERGED OBJECT

Occurrence #2: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING

Findings 2. AIRCRAFT CONTROL - NOT POSSIBLE Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER Phase of Operation: LANDING - ROLL

Findings
3. TERRAIN CONDITION - WATER

Factual Information

On February 25, 1998, about 1455 eastern standard time, a Lake LA-4-200, N3020P, registered to and operated by Sea Flight, Inc., as a 14 CFR Part 91 personal flight, crashed while attempting a water landing on Lake Murray, South Carolina. Visual meteorological conditions prevailed, and no flight plan was filed. The aircraft sank and was substantially damaged. The private-rated pilot and two passengers were seriously injured. The flight originated from Columbia Metropolitan Airport about 27 minutes before the accident.

Following the accident, the pilot stated he thought that either the nose gear had inadvertently extended or that during initial water touchdown, the hull impacted a submerged object. Witnesses on the lake were mixed in their individual observations of whether the landing gear were up or down during the water landing. An eyewitness, the wife of a Lake amphibian owner and an ex-flight attendant, stated that she observed the airplane fly over her lakeside house and that all landing gear were up. The water surface conditions at the landing site were reported as smooth. Because of recent heavy rainfall, the lake level was higher, the water clarity was diminished due to mud run-off, and the lake contained more floating and partially submerged debris than normal. The pilot stated he made three low passes over the landing area prior to his water landing.

Examination of the submerged wreckage by salvage divers revealed the nose and left main gear fully retracted and totally in their respective wheel wells, while the right main gear was not fully retracted. The landing gear control handle was in the up position.

Subsequent examination of the salvaged amphibian by FAA personnel revealed the hull impacted an unknown submerged object of such mass and weight to crush and tear the left front hull from the nose cone to the cockpit. Examination of the landing gear hydraulic actuators, main gear uplocks, and right main gear door damage revealed the probable sequence of events to be impact with a submerged object early in the touchdown followed by a prying action by the water to partially extend the right main landing gear during the postimpact gyrations. (See enclosed FAA Inspector's statement)

Pilot Information

| Certificate: | Private | Age: | 65.Male |
|---------------------------|---|-----------------------------------|----------------|
| | | • | |
| Airplane Rating(s): | Single-engine land; Single-engine sea; Multi-engine land | Seat Occupied: | Left |
| Other Aircraft Rating(s): | None | Restraint Used: | |
| Instrument Rating(s): | Airplane | Second Pilot Present: | No |
| Instructor Rating(s): | None | Toxicology Performed: | No |
| Medical Certification: | Class 3 Valid Medical–w/ waivers/lim | Last FAA Medical Exam: | April 17, 1996 |
| Occupational Pilot: | No | Last Flight Review or Equivalent: | |
| Flight Time: | 12600 hours (Total, all aircraft), 4573 hours (Total, this make and model), 12461 hours (Pilot In Command, all aircraft), 9 hours (Last 90 days, all aircraft), 5 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft) | | |

Aircraft and Owner/Operator Information

| Aircraft Make: | Lake | Registration: | N3020P |
|----------------------------------|--|-----------------------------------|-----------------|
| Model/Series: | LA-4-200 LA-4-200 | Aircraft Category: | Airplane |
| Year of Manufacture: | | Amateur Built: | |
| Airworthiness Certificate: | Normal | Serial Number: | 962 |
| Landing Gear Type: | Retractable - Tricycle; Amphibian; Hull | Seats: | 4 |
| Date/Type of Last Inspection: | June 6, 1997 Annual | Certified Max Gross Wt.: | 2600 lbs |
| Time Since Last Inspection: | 60 Hrs | Engines: | 1 Reciprocating |
| Airframe Total Time: | 1442 Hrs | Engine Manufacturer: | Lycoming |
| ELT: | Installed | Engine Model/Series: | IO-360-A1B |
| Registered Owner: | SEA FLIGHT, INC. | Rated Power: | 200 Horsepower |
| Operator: | | Operating Certificate(s) Held: | None |
| Operator Does Business As: | | Operator Designator Code: | |

Meteorological Information and Flight Plan

| Conditions at Accident Site: | Visual (VMC) | Condition of Light: | Day |
|---|----------------------------------|---|-------------------|
| Observation Facility, Elevation: | CAE ,236 ft msl | Distance from Accident Site: | 18 Nautical Miles |
| Observation Time: | 14:56 Local | Direction from Accident Site: | 112° |
| Lowest Cloud Condition: | Clear | Visibility | 10 miles |
| Lowest Ceiling: | None | Visibility (RVR): | |
| Wind Speed/Gusts: | 7 knots / | Turbulence Type Forecast/Actual: | / |
| Wind Direction: | 310° | Turbulence Severity Forecast/Actual: | / |
| Altimeter Setting: | 29 inches Hg | Temperature/Dew Point: | 23°C |
| Precipitation and Obscuration: | No Obscuration; No Precipitation | | |
| Departure Point: | COLUMBIA , SC (CAE) | Type of Flight Plan Filed: | None |
| Destination: | | Type of Clearance: | VFR;VFLF |
| Departure Time: | 14:28 Local | Type of Airspace: | Class G |

Airport Information

| Airport: | | Runway Surface Type: | |
|----------------------|---|---------------------------|---------------------------|
| Airport Elevation: | | Runway Surface Condition: | Water-calm |
| Runway Used: | 0 | IFR Approach: | None |
| Runway Length/Width: | | VFR Approach/Landing: | Full stop;Traffic pattern |

Wreckage and Impact Information

| Crew Injuries: | 1 Serious | Aircraft Damage: | Substantial |
|------------------------|-----------|-------------------------|---------------------------|
| Passenger Injuries: | 2 Serious | Aircraft Fire: | None |
| Ground Injuries: | N/A | Aircraft Explosion: | None |
| Total Injuries: | 3 Serious | Latitude, Longitude: | 33.910449,-81.509223(est) |

Administrative Information

| Investigator In Charge (IIC): | Stone, Alan | | |
|--------------------------------------|--|--|--|
| Additional Participating Persons: | JOHN PIPKIN; COLUMBIA , SC | | |
| Original Publish Date: | February 11, 2000 | | |
| Last Revision Date: | | | |
| Investigation Class: | <u>Class</u> | | |
| Note: | | | |
| Investigation Docket: | https://data.ntsb.gov/Docket?ProjectID=38463 | | |

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.