



Aviation Investigation Final Report

Location: WEWAHITCHKA, Florida Accident Number: MIA98LA120

Date & Time: April 3, 1998, 09:00 Local Registration: N508DD

Aircraft: Bell 205 Aircraft Damage: Destroyed

Defining Event: 1 None

Flight Conducted Under: Part 133: Rotorcraft ext. load

Analysis

The pilot was about to start agricultural operations, and had turned on the fertilizer bucket, when he reported that the hydraulic gauges started to 'surge.' He said the helicopter, '...then took a violent turn to the left...the helicopter jerked for a third time and came back level.' He released the fertilizer bucket, and elected to make a forced landing. He stated, '...the control was going left to right, the collective was not reacting properly, so I spooled off the throttle and landed in the trees.' Examination of the helicopter's hydraulic system after the accident revealed that impact damage had destroyed the servos and the hydraulic fluid reservoir. No discrepancies were found with the hydraulic system.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's loss of control as a result of erratic flight control movement due to a surge in hydraulic pressure for undetermined reasons.

Findings

Occurrence #1: AIRFRAME/COMPONENT/SYSTEM FAILURE/MALFUNCTION

Phase of Operation: MANEUVERING

Findings

1. (C) HYDRAULIC SYSTEM - SURGE

2. REASON FOR OCCURRENCE UNDETERMINED

Occurrence #2: LOSS OF CONTROL - IN FLIGHT

Phase of Operation: MANEUVERING

Findings

3. ROTORCRAFT FLIGHT CONTROL

4. AIRCRAFT CONTROL - NOT POSSIBLE - PILOT IN COMMAND

Occurrence #3: FORCED LANDING

Phase of Operation: EMERGENCY DESCENT/LANDING

Occurrence #4: IN FLIGHT COLLISION WITH OBJECT Phase of Operation: EMERGENCY DESCENT/LANDING

Findings

5. OBJECT - TREE(S)

Page 2 of 6 MIA98LA120

Factual Information

On April 3, 1998, about 0830 central standard time, a Bell UH-1H (205) helicopter, N508DD, registered to Precision Air Services, operating as a Title 14 CFR Part 133, agricultural flight, impacted with trees during a forced landing near Wewahitchka, Florida. Visual meteorological conditions prevailed and no flight plan was filed. The helicopter was destroyed. The commercial-rated pilot was not injured. The flight had originated at 0800.

The pilot was about to start agricultural operations, and had turned on the fertilizer bucket, when he reported that the hydraulic gauges started to "surge." He said the helicopter, "...then took a violent turn to the left...the helicopter jerked for a third time and came back level." He released the fertilizer bucket, and elected to make a forced landing. He stated, "...the control was going left to right, the collective was not reacting properly, so I spooled off the throttle and landed in the trees."

Examination of the helicopter's hydraulic system after the accident revealed that impact damage had destroyed the servos and the hydraulic fluid reservoir. No discrepancies were found with the hydraulic system.

Pilot Information

Certificate:	Commercial	Age:	46,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	January 2, 1998
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	11000 hours (Total, all aircraft), 500 hours (Total, this make and model), 11000 hours (Pilot In Command, all aircraft), 200 hours (Last 90 days, all aircraft), 100 hours (Last 30 days, all aircraft)		

Page 3 of 6 MIA98LA120

Aircraft and Owner/Operator Information

Aircraft Make:	Bell	Registration:	N508DD
Model/Series:	205 205	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	67-17678
Landing Gear Type:	Skid	Seats:	2
Date/Type of Last Inspection:	100 hour	Certified Max Gross Wt.:	9500 lbs
Time Since Last Inspection:	15 Hrs	Engines:	1 Turbo shaft
Airframe Total Time:		Engine Manufacturer:	Lycoming
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	T53-L-13BA
Registered Owner:	PRESISION AIR SERVICE	Rated Power:	1300 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Weteorological illionilati	on and ingite i lan		
Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	130°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	22°C / 19°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	08:00 Local	Type of Airspace:	Class D

Page 4 of 6 MIA98LA120

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Destroyed
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	30.110288,-85.189392(est)

Page 5 of 6 MIA98LA120

Administrative Information

Investigator In Charge (IIC):	Yurman, Alan	
Additional Participating Persons:	RODGER HOLSTROM; BIRMINGHAM , AL	
Original Publish Date:	February 11, 2000	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=38487	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 MIA98LA120