

Aviation Investigation Final Report

Location:	FORT WALTON B	BCH, Florida	Accident Number:	MIA98LA154
Date & Time:	May 9, 1998, 15:0	00 Local	Registration:	N6714D
Aircraft:	Bell	47G-2	Aircraft Damage:	Substantial
Defining Event:			Injuries:	3 Minor
Flight Conducted Under:	Part 91: General	aviation		

Analysis

While in cruise flight at 500-600 feet the engine failed. A autorotation was performed and the helicopter touched down in 4-5 feet of water. After touchdown the waves rolled the helicopter to the right and the main rotor contacted the water and stopped. The pilot stated the helicopter contained about 20 gallons of fuel at the time of the accident. Examination of the engine and accessories showed no evidence of mechanical failure or malfunction. All fuel lines were found unobstructed.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The loss of engine power for undetermined reasons.

Findings

Occurrence #1: LOSS OF ENGINE POWER Phase of Operation: CRUISE

Findings
1. (C) REASON FOR OCCURRENCE UNDETERMINED

Occurrence #2: DITCHING Phase of Operation: DESCENT - EMERGENCY

Factual Information

On May 9, 1998, about 1500 central daylight time, a Bell 47G-2, N6714D, registered to Penguin-Air Helicopters, Inc., ditched in the Gulf of Mexico, near Fort Walton Beach, Florida, following loss of engine power, while on a Title 14 CFR Part 91 sightseeing flight. Visual meteorological conditions prevailed at the time and no flight plan was filed. The helicopter received substantial damage and the commercial-rated pilot and two passengers received minor injuries. The flight originated from Fort Walton Beach, Florida, a few minutes before the accident.

The pilot stated that he had refueled the helicopter and had about 20 gallons of fuel onboard at the time of the accident. He had completed giving three rides. While on the fourth ride, over the Gulf of Mexico near Fort Walton Beach, at an altitude of 500-600 feet, the engine failed. He entered autorotation and touched down in 4-5 feet of water. The waves caused the helicopter to roll over to the right and the main rotor blades contacted the water and stopped. He and the two passengers then exited the helicopter.

Examination of the engine by a mechanic, under the supervision of an FAA inspector, showed the engine assembly rotated and continuity of the crankshaft, valve train, and all accessory drives gears was confirmed. The magneto switch operated normally and each magneto rotated. The magnetos would not fire due to water damage. The carburetor was opened and all ports were found unobstructed. All airframe and engine fuel lines were unobstructed.

Certificate:	Commercial	Age:	45,Male
Airplane Rating(s):	None	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Helicopter	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	June 13, 1997
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	3900 hours (Total, all aircraft), 800 hours (Total, this make and model), 3000 hours (Pilot In Command, all aircraft), 45 hours (Last 90 days, all aircraft), 20 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Pilot Information

Aircraft and Owner/Operator Information

Aircraft Make:	Bell	Registration:	N6714D
Model/Series:	47G-2 47G-2	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	2199
Landing Gear Type:	Skid	Seats:	3
Date/Type of Last Inspection:	April 1, 1998 100 hour	Certified Max Gross Wt.:	2450 lbs
Time Since Last Inspection:	25 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	6227 Hrs	Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	VO-435-A1D
Registered Owner:	PENGUIN-AIR HELICOPTER, INC.	Rated Power:	260 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	DTS ,22 ft msl	Distance from Accident Site:	5 Nautical Miles
Observation Time:	14:53 Local	Direction from Accident Site:	90°
Lowest Cloud Condition:	Clear	Visibility	4 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	6 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	160°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	27°C / 22°C
Precipitation and Obscuration:	N/A - None - Haze		
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	14:55 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:	2 Minor	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 Minor	Latitude, Longitude:	30.419496,-86.610946(est)

Administrative Information

Investigator In Charge (IIC):	Kennedy, Jeffrey	
Additional Participating Persons:	GAIL LIEURANCE; BIRMINGHAM , AL RODGER L HOLMSTROM; BIRMINGHAM , AL	
Original Publish Date:	February 15, 2001	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=38515	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.