

Aviation Investigation Final Report

Location:	NORFOLK, Virginia		Accident Number:	NYC93LA144
Date & Time:	August 3, 1993, 16:3	32 Local	Registration:	N30JM
Aircraft:	BEECH	A55	Aircraft Damage:	Substantial
Defining Event:			Injuries:	3 None
Flight Conducted Under:	Part 91: General aviation - Personal			

Analysis

THE PILOT REPORTED THAT DURING THE LANDING THE WINDS PROVIDED TO HIM BY THE CONTROL TOWER WERE 'DOWN THE RUNWAY AT SEVENTEEN KNOTS.' HE USED FULL FLAPS DURING THE APPROACH TO RUNWAY 23. HE SAID THAT THE ATIS REPORTED WINDS FROM 270 DEGREES, GUSTING TO 22 KNOTS. DURING THE TOUCHDOWN, THE AIRPLANE STARTED TO DRIFT LEFT AND THE NOSE GEAR COLLAPSED. THE AIRPLANE DEPARTED THE RUNWAY AND COLLIDED WITH THE SOFT TERRAIN.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S IMPROPER COMPESNATION FOR WIND CONDITIONS AND FAILURE TO MAINTAIN FIRECTIONAL CONTROL. A FACTOR WAS ADVERSE WIND CONDITIONS.

Findings

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) WEATHER CONDITION - UNFAVORABLE WIND

2. (C) COMPENSATION FOR WIND CONDITIONS - IMPROPER - PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

Findings 3. TERRAIN CONDITION - SOFT

Occurrence #3: NOSE GEAR COLLAPSED Phase of Operation: LANDING

Findings 4. LANDING GEAR, NOSE GEAR - OVERLOAD

Factual Information

On Tuesday, August 3, 1993, at 1632 eastern daylight time, a Beech A55, N30JM, registered to Baron, Ltd., and piloted by Clarence H. Byler, sustained substantial damage during a landing at the Norfolk International Airport, Norfolk, Virginia. The pilot, the safety pilot and the passenger were not injured. Visual meteorological conditions prevailed, and no flight plan was filed. The flight was being conducted under 14 CFR 91.

The pilot was conducting a landing on runway 23. He stated that the wind was reported from the tower as "down the runway at seventeen knots." During the approach he elected to use full flaps. He stated that there was a spacing problem with a commercial airplane landing behind him, and he was asked to expedite his approach. After touchdown, the airplane began to swerve to the left and the nose gear collapsed. The airplane departed the left side of the runway and collided with the soft terrain.

The pilot stated that the Airport Terminal Information Service (ATIS) reported the winds from 270 degrees with gusts to 22 knots. The local weather sequence, recorded 13 minutes after the accident, reported the winds from 210 degrees at 15 knots, with gusts to 23 knots.

Mr. E. E. Roberts, Operations Safety Inspector for the Federal Aviation Administration, conducted an on-site examination of the wreckage and an interview with the pilot. In his report, Mr. Roberts stated:

The pilot reported that he experienced windshear as he was touching down which caused a sideload on the nose gear. The nose gear collapsed and the aircraft veered off the runway.

Pilot Information

Certificate:	Private	Age:	72,Male
Airplane Rating(s):	Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	September 15, 1992
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	3000 hours (Total, all aircraft), 300 hours (Total, this make and model), 3000 hours (Pilot In Command, all aircraft), 30 hours (Last 90 days, all aircraft), 15 hours (Last 30 days, all aircraft), 6 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	BEECH	Registration:	N30JM
Model/Series:	A55 A55	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal; Provisional (Special)	Serial Number:	TC-277
Landing Gear Type:	Retractable - Tricycle	Seats:	6
Date/Type of Last Inspection:	August 8, 1992 Annual	Certified Max Gross Wt.:	4880 lbs
Time Since Last Inspection:		Engines:	2 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	10-470-L
Registered Owner:	BARON, LTD.	Rated Power:	260 Horsepower
Operator:	CLARENCE H. BYLER	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	ORF ,27 ft msl	Distance from Accident Site:	
Observation Time:	16:45 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 2700 ft AGL	Visibility	5 miles
Lowest Ceiling:	Broken / 10000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	15 knots / 23 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	210°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	25°C / 22°C
Precipitation and Obscuration:	No Obscuration; No Precipit	ation	
Departure Point:	MACON, GA (MCN)	Type of Flight Plan Filed:	None
Destination:	(ORF)	Type of Clearance:	None
Departure Time:	00:00 Local	Type of Airspace:	Class D

Airport Information

Airport:	NORFOLK INTERNATIONAL ORF	Runway Surface Type:	Macadam
Airport Elevation:	27 ft msl	Runway Surface Condition:	Dry
Runway Used:	23	IFR Approach:	Visual
Runway Length/Width:	9000 ft / 150 ft	VFR Approach/Landing:	Full stop;Straight-in

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	36.910625,-76.329277(est)

Administrative Information

Investigator In Charge (IIC):	Leonard, Charles	
Additional Participating Persons:	E. E ROBERTS; RICHMOND , VA	
Original Publish Date:	September 26, 1994	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=38623	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.