

Aviation Investigation Final Report

Location:	NORWOOD, Massa	chusetts	Accident Number:	NYC94LA042
Date & Time:	December 19, 1993	3, 16:08 Local	Registration:	N8210H
Aircraft:	PIPER	PA-32-R-301T	Aircraft Damage:	Substantial
Defining Event:			Injuries:	4 None
Flight Conducted Under:	Part 91: General av	iation - Personal		

Analysis

THE PILOT RECEIVED AN ADVISORY FROM THE CONTROL TOWER INDICATING THE RUNWAY WAS COVERED WITH 2 INCHES OF WET SNOW. HE THEN PROCEEDED TO INITIATE A TAKEOFF. THE PILOT SAID THE AIRPLANE WAS NOT ACCELERATING AND ABORTED THE TAKEOFF. HE SAID HE DID NOT USE BRAKES TO AVOID SKIDDING AND THE AIRPLANE RAN OFF THE DEPARTURE END OF THE RUNWAY, AND INTO AN DITCH.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The pilot's delay in aborting the takeoff which resulted in a overrun of the runway. Factors were a snow covered runway, takeoff speed not attained, brakes not used, and a ditch.

Findings

Occurrence #1: OVERRUN Phase of Operation: TAKEOFF - ABORTED

Findings

- 1. (F) AIRPORT FACILITIES, RUNWAY/LANDING AREA CONDITION SNOW COVERED
- 2. (F) AIRSPEED NOT ATTAINED PILOT IN COMMAND
- 3. (C) ABORTED TAKEOFF DELAYED PILOT IN COMMAND
- 4. (F) BRAKES(NORMAL) NOT USED PILOT IN COMMAND

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER Phase of Operation: TAKEOFF - ABORTED

Findings 5. (F) TERRAIN CONDITION - DITCH

Factual Information

On December 19, 1993, at 1608 eastern standard time, a Piper PA-32-R-301T, N8210H, operated by Mr. Richard E. Fleming, of Princeton, New Jersey, overran the runway during an aborted takeoff at Norwood, Massachusetts. The airplane received substantial damage. The pilot and three passengers were not injured. Instrument meteorological conditions prevailed and the flight was operating on an instrument flight rules (IFR) flight plan under 14 CFR Part 91.

The pilot called the control tower to taxi for departure. At 1559, he was told, "...braking action was about an hour and half ago uh poor by a vehicle." The pilot then asked if he could back taxi down the runway for departure and that was approved.

At 1606, the pilot was given the following from the local controller, "...new field condition from the airport manager..., all surfaces covered two inches of wet snow, braking action reported poor by the vehicle." This was acknowledged by the pilot. He was then cleared for takeoff and the winds were reported as calm. At 1608, the pilot called the control tower and said, "Ahrr we're off the runway sir."

In a written statement, the pilot said:

...On take-off roll, the airplane accelerated initially, and there was never [an] indication of a failure to develop power. However, I sensed that were not achieving a lift-off and did not have flying speed. I cut the power but did not attempt to brake to avoid skidding. We ran straight ahead off the runway and into the wet field. There was a ditch which forced us to tip forward, striking the nose and propeller into the wet ground....

Pilot Information

Certificate:	Airline transport; Flight instructor	Age:	47,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	March 1, 1993
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	2120 hours (Total, all aircraft), 932 hours (Total, this make and model), 2050 hours (Pilot In Command, all aircraft), 19 hours (Last 90 days, all aircraft), 4 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N8210H
Model/Series:	PA-32-R-301T PA-32-R-30	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	32R-8339054
Landing Gear Type:	Retractable - Tricycle	Seats:	б
Date/Type of Last Inspection:	December 1, 1993 Annual	Certified Max Gross Wt.:	3600 lbs
Time Since Last Inspection:	4 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2250 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, not activated	Engine Model/Series:	TIO-540-S1AD
Registered Owner:	OQUOSSOC ASSOCIATES	Rated Power:	300 Horsepower
Operator:	RICHARD E. FLEMING	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Instrument (IMC)	Condition of Light:	Dav
conditions at Accident Site.	instrument (into)	condition of Light.	Day
Observation Facility, Elevation:	OWD ,50 ft msl	Distance from Accident Site:	
Observation Time:	15:45 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Unknown	Visibility	0.25 miles
Lowest Ceiling:	300 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	0°C
Precipitation and Obscuration:	N/A - None - Fog		
Departure Point:		Type of Flight Plan Filed:	IFR
Destination:	PRINCETON , NJ (39N)	Type of Clearance:	IFR
Departure Time:	16:06 Local	Type of Airspace:	Class D;Class E

Airport Information

Airport:	NORWOOD MEMORIAL OWD	Runway Surface Type:	Asphalt
Airport Elevation:	50 ft msl	Runway Surface Condition:	Snow
Runway Used:	35	IFR Approach:	None
Runway Length/Width:	4007 ft / 150 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	3 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	4 None	Latitude, Longitude:	

Administrative Information

Investigator In Charge (IIC):	Hancock, Robert		
Additional Participating Persons:	MERRILL CROSS; BEDFORD , MA		
Original Publish Date:	October 20, 1994		
Last Revision Date:			
Investigation Class:	<u>Class</u>		
Note:			
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=38722		

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available here.