



Aviation Investigation Final Report

Location: WEST PALM BEACH, Florida Accident Number: ATL97LA125

Date & Time: August 26, 1997, 00:30 Local Registration: N6216Q

Aircraft: Cessna 152 Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Instructional

Analysis

The commercial-rated, student pilot stated that they landed the airplane at Orlando Executive Airport to refuel, but found the FBO was closed. He was advised by his instructor (CFI) that he had sufficient fuel for the flight to Palm Beach. They flew to Melbourne International Airport to 'do a touch and go.' While en-route to Palm Beach, the engine lost power, and the CFI took control of the airplane. The CFI declared an emergency due to low fuel, and was vectored to North County Airport, but was unable to reach it. The CFI landed the airplane on a dirt road, and the airplane collided with a mailbox and trees.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: the flight instructor's (CFI's) inaccurate assessment of fuel available for the flight, and his improper in-flight planning/decision by continuing the training flight with minimal fuel, which resulted in fuel exhaustion and loss of engine power.

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: CRUISE - NORMAL

Findings

1. (C) FUEL CONSUMPTION CALCULATIONS - INACCURATE - PILOT IN COMMAND(CFI)

2. (C) IN-FLIGHT PLANNING/DECISION - IMPROPER - PILOT IN COMMAND(CFI)

3. (C) FLUID, FUEL - EXHAUSTION

Occurrence #2: FORCED LANDING

Phase of Operation: EMERGENCY DESCENT/LANDING

Occurrence #3: ON GROUND/WATER COLLISION WITH OBJECT

Phase of Operation: EMERGENCY LANDING

Findings

4. OBJECT - OTHER

5. OBJECT - TREE(S)

Page 2 of 6 ATL97LA125

Factual Information

On August 26, 1997, about 0030 eastern daylight time, a Cessna 152, N6216Q, force landed in a residential area and collided with terrain, 12 miles north-northwest of the Palm Beach International Airport, Florida. The airplane was operated by the commercial student pilot under the provisions of Title 14 CFR Part 91, and visual flight rules. Visual meteorological conditions existed, and no flight plan was filed for the local instructional flight. The instructor and student were not injured, and the airplane was substantially damaged. The student pilot stated that the engine had guit and they had to make a forced landing. The flight originated from Fort The student pilot stated that they landed the airplane Lauderdale Executive Airport. at Orlando Executive Airport to refuel, but found the FBO was closed. He was advised by his instructor that he had sufficient fuel for the flight to Palm Beach. They flew to Melbourne International Airport to "do a touch and go". While en-route to Palm Beach the engine guit and the instructor took control of the airplane and attempted restart procedures, but failed. The student pilot said, the instructor declared an emergency due to low fuel and was vectored to North County airport, but was unable to make it. The instructor landed the airplane on a dirt road and collided with a mailbox, and trees.

Pilot Information

T HOT IIII OTTHICKION			
Certificate:	Commercial; Flight instructor	Age:	25,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Right
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	Yes
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medical-w/ waivers/lim	Last FAA Medical Exam:	October 28, 1996
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	1250 hours (Total, all aircraft), 250 h all aircraft)	ours (Total, this make and model), 30	00 hours (Last 90 days,

Page 3 of 6 ATL97LA125

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N6216Q
Model/Series:	152 152	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Utility	Serial Number:	15285198
Landing Gear Type:	Tricycle	Seats:	2
Date/Type of Last Inspection:	Unknown	Certified Max Gross Wt.:	1675 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	14809 Hrs	Engine Manufacturer:	Lycoming
ELT:	Installed	Engine Model/Series:	0-235
Registered Owner:	EXECUTIVE PILOT SERVICE INC	Rated Power:	115 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

meteorological informati	3	_		
Conditions at Accident Site:	Visual (VMC)		Condition of Light:	Night/dark
Observation Facility, Elevation:			Distance from Accident Site:	:
Observation Time:			Direction from Accident Site	:
Lowest Cloud Condition:	Scattered / 150	0 ft AGL	Visibility	10 miles
Lowest Ceiling:	Unknown		Visibility (RVR):	
Wind Speed/Gusts:	/ None		Turbulence Type Forecast/Actual:	/
Wind Direction:	0°		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:			Temperature/Dew Point:	27°C
Precipitation and Obscuration:	No Obscuration	ı; No Precipi	tation	
Departure Point:	MELBOURNE	(MLB)	Type of Flight Plan Filed:	None
Destination:	PALM BEACH	(PBI)	Type of Clearance:	None
Departure Time:	00:00 Local		Type of Airspace:	Class G

Page 4 of 6 ATL97LA125

Airport Information

Airport:	NORTH COUNTY F45	Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	2 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	26.720767,-80.070106(est)

Page 5 of 6 ATL97LA125

Administrative Information

Investigator In Charge (IIC): Wilson, Butch Additional Participating BRUCE HILL; FORT LAUDERDALE, FL ANDREW SCHRADER: ATLANTA Persons: **Original Publish Date:** May 21, 1998 **Last Revision Date: Investigation Class:** Class Note: **Investigation Docket:** https://data.ntsb.gov/Docket?ProjectID=3893

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ATL97LA125