



Aviation Investigation Final Report

Location:	FARMINGDALE, New York	Accident Number:	NYC98LA108
Date & Time:	May 15, 1998, 12:58 Local	Registration:	N7SB
Aircraft:	Cessna 175B	Aircraft Damage:	Destroyed
Defining Event:		Injuries:	1 Minor, 1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

The pilot reported that he made a normal, flaps-up takeoff with full throttle. The point on the runway where he became airborne was about 2,800 feet from where the initial takeoff roll began. The pilot stated he climbed out at 90 to 100 mph, and 2,400 to 2,500 rpm. He said that the rpm dropped to 2,100, and then to 1,900. The pilot then performed a forced landing to a building roof top. According to the owner's manual, the calculated takeoff distance was less than 700 feet. Certification data revealed that at 90 to 100 mph, the geared engine should have produced about 2,900 to 3,000 rpm. A carburetor icing probability chart showed that for the ambient conditions, and with less than full power, moderate icing could result. A manufacturer's service instruction stated that 'the possibility of throttle icing at wide throttle openings is very remote, so remote in fact, that it can be disregarded.'

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: The engine's inability to provide full power, and the pilot's failure to use performance data. Factors in the accident were conditions conducive for carburetor icing at reduced power, and the unsuitable terrain during the forced landing.

Findings

Occurrence #1: LOSS OF ENGINE POWER
Phase of Operation: TAKEOFF - ROLL/RUN

Findings

1. (C) POWERPLANT - OUTPUT LOW
2. (C) PERFORMANCE DATA - NOT USED - PILOT IN COMMAND

Occurrence #2: LOSS OF ENGINE POWER

Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

3. (C) REASON FOR OCCURRENCE UNDETERMINED
4. WEATHER CONDITION - CARBURETOR ICING CONDITIONS

Occurrence #3: FORCED LANDING

Phase of Operation: CLIMB

Findings

5. (F) TERRAIN CONDITION - NONE SUITABLE

Factual Information

On May 15, 1998, at 1258 Eastern Daylight Time, a Cessna 175B, N7SB, was destroyed during a forced landing approximately 1 mile south of the Republic Airport, Farmingdale, New York. The certificated commercial pilot received minor injuries, and the passenger was not injured. Visual meteorological conditions prevailed at the time of the accident. No flight plan had been filed for the local flight conducted under 14 CFR Part 91.

The pilot stated that after takeoff, and passing through 150 feet, the airplane's engine rpm was 2,400 to 2,500 rpm, and then dropped to 2,100 rpm. After the rpm drop, the pilot applied carburetor heat, and "mags were cleared. Rpm further dropped to 1,900." The pilot felt he couldn't avoid a fence at the end of the airport, and there was not enough room to land straight ahead. The "decision to continue the climb was made when rpm increased back to 2,100." About 250 feet, the engine began losing power again.

The pilot stated he was "too low and too slow" to turn back to the field, and continued straight ahead. He cleared some trees, power lines, and a highway, and saw several buildings with flat roofs. Since he saw no other areas clear of obstructions, he decided to land on the largest building. At touchdown, the airplane struck an air conditioner and punctured the building's roof. It skidded off the roof into a tree, and went nose-down into a storage shed. A small fire started in the engine compartment, and was extinguished by the passenger. According to a Federal Aviation Administration (FAA) Inspector, post flight inspection revealed no water or debris during disassembly of the carburetor, and the airplane was turned over to a salvage facility.

The 1961 Cessna 175B Owner's Manual stated that normal takeoff and climb airspeeds were accomplished at full throttle. The owner's manual also stated that initial climb speed after takeoff was 84 mph, and normal climb airspeed thereafter was between 90 and 100 mph. The pilot said that he took off with full throttle and flaps up, and that he climbed between 90 and 100 mph. According to original certification data, and based on a McCauley 8464 fixed pitch propeller and full throttle, 90 mph should have resulted in a 2,990 rpm indication, and 100 mph should have resulted in a 3,070 rpm indication.

In the operational data section of the owner's manual, takeoff distance data was available for a standard day and 20 degrees flaps from a hard surface runway. There was no chart for a "flaps up" takeoff. However, according to a 1964 Cessna Aircraft Company comparative ground roll study, adding another 10% to the 20 degree flap takeoff distance would result in a reliable takeoff distance with the flaps up. The ambient temperature was 73 degrees Fahrenheit, and there was a note on the chart to increase takeoff distance by 10% for each 25 degrees Fahrenheit above standard temperature. Headwind at the time of takeoff was 10 knots, and the pilot said the airplane was about 200 pounds under maximum gross weight.

Utilizing the takeoff data chart with the above criteria, the airplane should have required less than a 700 foot ground run to take off with full power.

The pilot wrote that he began the takeoff roll at "the very beginning" of Runway 19, that the "ground run was normal, and initial liftoff occurred at approximately the intersection of Runway 14." According to airport diagrams, the intersection was about 2,800 feet from the beginning of Runway 19.

In the cruising section of the owner's manual, cruising rpm was stated as between 2,400 and 3,200 rpm. According to a carburetor icing probability chart in Tips on Winter Flying, FAA-P-8740-24, ambient conditions during the flight's timeframe would have produced "moderate icing" at cruising rpm. With reduced power, the degree of icing would have increased for the same ambient conditions.

Avco Lycoming published Service Instruction 1148B on May 4, 1973. Representatives from both Cessna and Teledyne-Continental stated that it was applicable to carbureted Continental engines, as well. The service instruction stated: "Take-offs and full throttle operation should be made with carburetor heat in the full cold position. The possibility of throttle icing at wide throttle openings is very remote, so remote in fact, that it can be disregarded."

Pilot Information

Certificate:	Commercial; Flight instructor	Age:	50, Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical-w/ waivers/lim	Last FAA Medical Exam:	October 2, 1997
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	1641 hours (Total, all aircraft), 600 hours (Total, this make and model), 1590 hours (Pilot In Command, all aircraft), 72 hours (Last 90 days, all aircraft), 44 hours (Last 30 days, all aircraft), 3 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N7SB
Model/Series:	175B 175B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	17556947
Landing Gear Type:	Tricycle	Seats:	4
Date/Type of Last Inspection:	December 18, 1997 Annual	Certified Max Gross Wt.:	2350 lbs
Time Since Last Inspection:	20 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2468 Hrs	Engine Manufacturer:	Continental
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	GO-300
Registered Owner:	FRITZ MARTELLY AND HENRY R REY	Rated Power:	175 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	FRG ,82 ft msl	Distance from Accident Site:	2 Nautical Miles
Observation Time:	12:45 Local	Direction from Accident Site:	10°
Lowest Cloud Condition:	Clear	Visibility	7 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	190°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	23°C / 12°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	FARMINGDALE , NY (FRG)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	12:50 Local	Type of Airspace:	Class D

Airport Information

Airport:	REPUBLIC FRG	Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Destroyed
Passenger Injuries:	1 None	Aircraft Fire:	On-ground
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor, 1 None	Latitude, Longitude:	40.729595,-73.440048(est)

Administrative Information

Investigator In Charge (IIC):	Cox, Paul
Additional Participating Persons:	RAY B MELCER; FARMINGDALE, NY
Original Publish Date:	February 15, 2001
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=39561

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).