

# **Aviation Investigation Final Report**

Location: BOISE, Idaho Accident Number: SEA83LA177

Date & Time: August 13, 1983, 18:34 Local Registration: N4772Q

Aircraft: CESSNA 185E Aircraft Damage: Substantial

**Defining Event:** 3 None

Flight Conducted Under: Part 135: Air taxi & commuter - Non-scheduled

### **Analysis**

THE ACFT LANDED IN A NEAR MAXIMUM VELOCITY CROSSWIND AND WHILE BRAKING TO CONTROL/CORRECT A SWERVE, THE RIGHT MAIN LANDING GEAR SEPARATED FROM THE ACFT. THE LANDING WAS ON RWY 28R AND THE WIND WAS FROM 200 DEGREES AT 10 TO 14 KTS ON FINAL AND 12 KTS WHEN THE PILOT WAS OVER THE THRESHOLD. THE ACFT TOUCHED DOWN ON THE LEFT WHEEL AND BOUNCED A LITTLE. ITTOUCHED DOWN AGAIN ON THE LEFT GEAR AND THE PILOT RAISED THE TAIL. THE RIGHT MAIN CAME DOWN WITH THE TAIL STILL IN THE AIR. AT ABOUT 40 MPH THE TAIL WAS LOWERED AND THE ACFT STARTED A LEFT TURN. THE PILOT CORRECTED WITH FULL RUDDER AND RIGHT BRAKING. THE PILOT DETECTED A SINKING ON THE RIGHT SIDE AND THEN THE RIGHT STRUT COLLAPSED. WHEN HE DEPLANED THE PILOT DISCOVERED THE RIGHT GEAR HAD SEPARATED. THE MAXIMUM DEMONSTRATED CROSSWIND VELOCITY FOR THIS AIRCRAFT (CESSNA 185) IS 15 KTS. METALLURGICAL TESTS WERE PERFORMED ON THE RIGHT WHEEL SPINDLE ATTACHING NUTS AND BOLTS WHICH SHOWED THAT THE REAR BOLTS FAILED AT THE INTERFACE OF SPINDLE AND STRUT DUE TO TENSILE OVERLOAD.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: LANDING - FLARE/TOUCHDOWN

#### **Findings**

- 1. (F) WEATHER CONDITION CROSSWIND
- 2. (C) FLARE MISJUDGED PILOT IN COMMAND
- 3. (C) GROUND LOOP/SWERVE PERFORMED PILOT IN COMMAND
- 4. (C) BRAKES(NORMAL) EXCESSIVE PILOT IN COMMAND

-----

Occurrence #2: MAIN GEAR COLLAPSED Phase of Operation: LANDING - ROLL

#### **Findings**

- 5. (F) LANDING GEAR, MAIN GEAR SEPARATION
- 6. (F) LANDING GEAR, MAIN GEAR STRUT FAILURE, TOTAL
- 7. (F) LANDING GEAR, MAIN GEAR OVERLOAD
- 8. (F) LANDING GEAR, MAIN GEAR STRUT OVERLOAD

Page 2 of 6 SEA83LA177

## **Factual Information**

### **Pilot Information**

Certificate:	Commercial	Age:	30,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):		Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical-w/ waivers/lim	Last FAA Medical Exam:	May 24, 1983
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	1164 hours (Total, all aircraft), 55 hours (Total, this make and model), 987 hours (Pilot In Command, all aircraft), 30 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Page 3 of 6 SEA83LA177

## **Aircraft and Owner/Operator Information**

Aircraft Make:	CESSNA	Registration:	N4772Q
Model/Series:	185E 185E	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	185-1239
Landing Gear Type:	Tailwheel	Seats:	6
Date/Type of Last Inspection:	100 hour	Certified Max Gross Wt.:	3300 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:		Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	0-470-R
Registered Owner:	MOUNTAIN BIRD, INCORPORATED	Rated Power:	230 Horsepower
Operator:	SALMON AIR TAXI	Operating Certificate(s) Held:	On-demand air taxi (135)
Operator Does Business As:		Operator Designator Code:	

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	BOI ,2858 ft msl	Distance from Accident Site:	
Observation Time:	18:50 Local	Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Scattered / 6000 ft AGL	Visibility	20 miles
Lowest Ceiling:	Broken / 14000 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	15 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	200°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	28°C / 9°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	MCCALL , ID (MYL)	Type of Flight Plan Filed:	Company VFR
Destination:	BOISE , ID (BOI)	Type of Clearance:	None
Departure Time:	17:45 Local	Type of Airspace:	Class D

Page 4 of 6 SEA83LA177

## **Airport Information**

Airport:	BOISE AIR TERMINAL BOI	Runway Surface Type:	Asphalt
Airport Elevation:	2858 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	28R	IFR Approach:	None
Runway Length/Width:	7400 ft / 150 ft	VFR Approach/Landing:	Full stop

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	

Page 5 of 6 SEA83LA177

#### **Administrative Information**

Investigator In Charge (IIC):	Carrera, Candace
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=39754

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 SEA83LA177