



Aviation Investigation Final Report

Location: WARM SPRINGS, Oregon Accident Number: SEA85FA137

Date & Time: June 13, 1985, 21:51 Local Registration: N4732

Aircraft: HILLER UH-12C Aircraft Damage: Substantial

Defining Event: 1 Serious

Flight Conducted Under: Part 91: General aviation - Ferry

Analysis

DURING A FLT FROM MADRAS, OR TO WALLA WALLA, WA, A LOSS OF ENG POWER OCCURRED DUE TO A FUEL FLOW PROBLEM & THE PLT MADE A SUCCESSFUL AUTOROTATION NEAR WARM SPRINGS, OR. A COMPANY MECHANIC WAS DISPATCHED TO THE HELICOPTER & HE REPAIRED A LOOSE FUEL LINE FITTING. LATE THAT EVENING, THE PLT STARTED & RAN THE ENG FOR ABOUT 10 MIN. HE THEN HOVERED FOR 4 TO 5 MIN BEFORE STARTING HIS DEPARTURE. THE PLT REPORTED THAT DURING DEPARTURE, THE ENG BEGAN LOSING RPM AT ABOUT 40 FT AGL. HE ATTEMPTED TO RESTORE POWER, BUT WAS UNABLE. SUBSEQUENTLY, THE HELICOPTER IMPACTED ON ITS SKID LANDING GEAR & TAIL SKID, THEN CAME TO REST ON ITS LEFT SIDE ABOUT 60 FT FROM THE IMPACT POINT. AN EXAM OF THE FUEL SYSTEM REVEALED THAT THE FUEL STRAINER, KOE/K2250B-2, WAS LOOSE AT BOTH ENGS OF THE GLASS & COULD BE TURNED WITH SLIGHT PRESSURE. THE BOLT AT THE BOTTOM OF THE LOWER PIECE WAS NOT SAFETY WIRED & WAS LOOSE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF ENGINE POWER
Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (C) FUEL SYSTEM, STRAINER - LOOSE

2. (C) MAINTENANCE - INADEQUATE - COMPANY MAINTENANCE PERSONNEL

3. (C) FLUID, FUEL - STARVATION

Occurrence #2: FORCED LANDING

Phase of Operation: DESCENT - UNCONTROLLED

Findings

4. AUTOROTATION - PERFORMED - PILOT IN COMMAND

Occurrence #3: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

5. (F) LIGHT CONDITION - NIGHT

Occurrence #4: ROLL OVER Phase of Operation: LANDING

Page 2 of 5 SEA85FA137

Factual Information

Pilot Information

Certificate:	Commercial	Age:	24,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	March 5, 1985
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	342 hours (Total, all aircraft), 3 hours (Total, this make and model), 230 hours (Pilot In Command, all aircraft), 53 hours (Last 90 days, all aircraft), 23 hours (Last 30 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	HILLER	Registration:	N4732
Model/Series:	UH-12C UH-12C	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Utility	Serial Number:	259
Landing Gear Type:	Skid	Seats:	1
Date/Type of Last Inspection:	August 10, 1984 Annual	Certified Max Gross Wt.:	2400 lbs
Time Since Last Inspection:	27 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	734 Hrs	Engine Manufacturer:	FRANKLIN
ELT:	Not installed	Engine Model/Series:	6V4-178-B335
Registered Owner:	AIRCRAFT COMMERCE, LTD.	Rated Power:	178 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 SEA85FA137

Meteorological Information and Flight Plan

Visual (VMC)	Condition of Light:	Dusk
	Distance from Accident Site:	
	Direction from Accident Site:	
Clear	Visibility	60 miles
None	Visibility (RVR):	
/	Turbulence Type Forecast/Actual:	/
0°	Turbulence Severity Forecast/Actual:	/
	Temperature/Dew Point:	10°C / -3°C
No Obscuration; No Precipita	ition	
	Type of Flight Plan Filed:	None
MADRAS , OR (S33)	Type of Clearance:	None
21:50 Local	Type of Airspace:	Class G
	Clear None / 0° No Obscuration; No Precipitation MADRAS , OR (S33)	Distance from Accident Site: Direction from Accident Site: Visibility None Visibility (RVR): Turbulence Type Forecast/Actual: Turbulence Severity Forecast/Actual: Temperature/Dew Point: No Obscuration; No Precipitation Type of Flight Plan Filed: MADRAS , OR (S33) Type of Clearance:

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	44.819206,-121.309921(est)

Page 4 of 5 SEA85FA137

Administrative Information

Investigator In Charge (IIC): Stripling, Wallace

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=40049

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 SEA85FA137