



# **Aviation Investigation Final Report**

Location: HOQUIAM, Washington Accident Number: SEA85LA151

Date & Time: June 25, 1985, 10:45 Local Registration: N4991D

Aircraft: BELL UH-1B Aircraft Damage: None

**Defining Event:** 1 Fatal, 1 None

Flight Conducted Under: Part 133: Rotorcraft ext. load

### **Analysis**

THE HELICOPTER WAS BEING USED DURING AN EXTERNAL LOAD OPERATION TO MOVE LARGE BLOCKS OF WOOD. HOWEVER, WHILE HOVERING, THE SLING BROKE. SUBSEQUENTLY, A BLOCK OF WOOD STRUCK A COMPANY EMPLOYEE ON THE HEAD WHILE HE WAS WORKING ON THE GROUND. THE EMPLOYEE WAS FATALLY INJURED.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

### **Findings**

Occurrence #1: MISCELLANEOUS/OTHER

Phase of Operation: HOVER

Findings

1. (C) PICKUP EQUIPMENT - FAILURE, TOTAL

## **Factual Information**

#### **Pilot Information**

Certificate:	Commercial	Age:	50,Male
Airplane Rating(s):	Single-engine land; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Helicopter	Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Unknown Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	January 4, 1985
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	13700 hours (Total, all aircraft), 2370 hours (Total, this make and model), 190 hours (Last 90 days, all aircraft), 2 hours (Last 24 hours, all aircraft)		

## **Aircraft and Owner/Operator Information**

Aircraft Make:	BELL	Registration:	N4991D
Model/Series:	UH-1B UH-1B	Aircraft Category:	Helicopter
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	61-765
Landing Gear Type:	Skid	Seats:	6
Date/Type of Last Inspection:	July 1, 1984 Annual	Certified Max Gross Wt.:	7200 lbs
Time Since Last Inspection:	55 Hrs	Engines:	1 Turbo shaft
Airframe Total Time:	1995 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	T53-11D
Registered Owner:	AIR LIFT HELICOPTER	Rated Power:	684 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 SEA85LA151

**Meteorological Information and Flight Plan** 

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
<b>Lowest Cloud Condition:</b>	Clear	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	18°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	10:30 Local	Type of Airspace:	Class G

**Airport Information** 

Airport:		Runway Surface Type:	
Airport Elevation:		<b>Runway Surface Condition:</b>	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	None
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	1 Fatal	Aircraft Explosion:	None
Total Injuries:	1 Fatal, 1 None	Latitude, Longitude:	47.110874,-123.959487(est)

Page 3 of 4 SEA85LA151

#### **Administrative Information**

Investigator In Charge (IIC): Carrera, Candace

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=40187

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 SEA85LA151