



Aviation Investigation Final Report

Location: YERINGTON, Nevada Accident Number: SEA85LA207

Date & Time: September 4, 1985, 14:40 Local Registration: N3635G

Aircraft: STOLT-ADAMS STARDUSTER SA101 Aircraft Damage: Substantial

Defining Event: Injuries: 1 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

WHILE ATTEMPTING TO LAND THE PLT ALLOWED THE ACFT TO BECOME TOO LOW ON SHORT FINAL. THE PLT DID NOT ADD PWR SOON ENOUGH AND AN UNDERSHOOT OCCURRED.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: UNDERSHOOT

Phase of Operation: APPROACH - VFR PATTERN - FINAL APPROACH

Findings

1. (C) IN-FLIGHT PLANNING/DECISION - DELAYED - PILOT IN COMMAND 2. (C) THROTTLE/POWER CONTROL - DELAYED - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Factual Information

Pilot Information

Certificate:	Private	Age:	53,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Center
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	August 27, 1985
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	1201 hours (Total, all aircraft), 101 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	STOLT-ADAMS	Registration:	N3635G
Model/Series:	STARDUSTER SA101 STARDUSTER	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	Yes
Airworthiness Certificate:	Experimental (Special)	Serial Number:	S-100
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	September 4, 1985 Continuous airworthiness	Certified Max Gross Wt.:	800 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	625 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	0-290
Registered Owner:	JERRY C. MARRACOLA	Rated Power:	130 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 2 of 4 SEA85LA207

Meteorological Information and Flight Plan

Conditions at Accident Site: Visual (VMC) Condition of Light: Day Observation Facility, Elevation: Distance from Accident Site: Observation Time: Direction from Accident Site: Lowest Cloud Condition: Clear Visibility 50 miles Lowest Ceiling: None Visibility (RVR): Wind Speed/Gusts: 5 knots / Turbulence Type Forecast/Actual: Wind Direction: 190° Turbulence Severity /
Observation Time: Lowest Cloud Condition: Clear Visibility 50 miles Lowest Ceiling: None Visibility (RVR): Turbulence Type Forecast/Actual:
Lowest Cloud Condition: Clear Visibility 50 miles Lowest Ceiling: None Visibility (RVR): Turbulence Type Forecast/Actual:
Lowest Ceiling: None Visibility (RVR): Wind Speed/Gusts: 5 knots / Turbulence Type / Forecast/Actual:
Wind Speed/Gusts: 5 knots / Turbulence Type / Forecast/Actual:
Forecast/Actual:
Wind Direction: 190° Turbulence Severity /
Forecast/Actual:
Altimeter Setting: Temperature/Dew Point: 24°C
Precipitation and Obscuration: No Obscuration; No Precipitation
Departure Point: Type of Flight Plan Filed: None
Destination: Type of Clearance: None
Departure Time: 14:15 Local Type of Airspace: Class G

Airport Information

Airport:	YERINGTON MUNICIPAL 043	Runway Surface Type:	Asphalt
Airport Elevation:	4378 ft msl	Runway Surface Condition:	Dry
Runway Used:	1	IFR Approach:	None
Runway Length/Width:	3921 ft / 75 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	38.870201,-119.139572(est)

Page 3 of 4 SEA85LA207

Administrative Information

Investigator In Charge (IIC): Carrera, Candace

Additional Participating Persons:

Original Publish Date:

Last Revision Date:

Investigation Class: Class

Note:

Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=40234

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 4 of 4 SEA85LA207