

Aviation Investigation Final Report

Location: NOATAK, Alaska Accident Number: ANC83FA095

Date & Time: June 11, 1983, 10:00 Local Registration: N731CN

Aircraft: CESSNA C-188 Aircraft Damage: Substantial

Defining Event: 1 None

Flight Conducted Under: Part 91: General aviation

Analysis

THE ACFT COLLIDED WITH THE RUNWAY AT THE MID-POINT IN A 30 DEGREE NOSE LOW ATTITUDE DURING TAKEOFF. ACCORDING TO THE PILOT THE TAKEOFF WAS STARTED AT THE NORTH END OF THE 5000 FOOT RUNWAY AND AFTER 500 FEET THE ACFT LIFTED OFF NORMALLY. THE PILOT THEN RELAXED THE BACK PRESSURE ON THE ELEVATOR TO ACCELERATE TO BEST CLIMB SPEED. THE PILOT FURTHER STATED THAT AT THE MID-POINT OF THE RUNWAY THE ACFT BEGAN TO PITCH DOWN GENTLY SO HE APPLIED SOME NOSE UP TRIM BUT THE ACFT CONTINUED TO PITCH DOWN AND THE PILOT NOTICED THAT THE CONTROL STICK WOULD NOT MOVE ANY FARTHER AFT THAN THE NEUTRAL POSITION. THE ACFT CONTINUED TO PITCH DOWN UNTIL IT IMPACTED THE RUNWAY. AN INSPECTION OF THE ACFT REVEALED AN UNUSUAL AMOUNT OF TOOLS & PLYWOOD IN THE TAIL SECTION. NO ITEMS WERE FOUND LODGED SO AS TO INTERFER WITH THE FLT CONTROLS. ALL THE FLT CONTROLS HAD CONTINUITY BUT THE ELEVATOR CABLES HAD AN UNUSUAL AMOUNT OF SLACK BUT NOT ENOUGH TO MAKE THE ACFT UNCONTROLLABLE.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: LOSS OF CONTROL - IN FLIGHT Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

1. (F) FLT CONTROL SYST, ELEVATOR CONTROL - BLOCKED (PARTIAL)
2. (C) PREFLIGHT PLANNING/PREPARATION - IMPROPER - PILOT IN COMMAND

Occurrence #2: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: TAKEOFF - INITIAL CLIMB

Page 2 of 6 ANC83FA095

Factual Information

Pilot Information

Certificate:	Airline transport	Age:	62,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land; Multi- engine sea	Seat Occupied:	Center
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane multi-engine; Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical–w/ waivers/lim	Last FAA Medical Exam:	May 18, 1983
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	19033 hours (Total, all aircraft), 5 hours (Total, this make and model), 19033 hours (Pilot In Command, all aircraft), 65 hours (Last 90 days, all aircraft), 4 hours (Last 24 hours, all aircraft)		

Page 3 of 6 ANC83FA095

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N731CN
Model/Series:	C-188 C-188	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	18802792T
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	February 5, 1983 Annual	Certified Max Gross Wt.:	3300 lbs
Time Since Last Inspection:	0 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1464 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	IO-520-D
Registered Owner:	NORTHWESTERN AVIATION	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	On-demand air taxi (135)
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)		Condition of Light:	Day
Observation Facility, Elevation:			Distance from Accident Site:	
Observation Time:			Direction from Accident Site:	
Lowest Cloud Condition:	Clear		Visibility	30 miles
Lowest Ceiling:	None		Visibility (RVR):	
Wind Speed/Gusts:	/		Turbulence Type Forecast/Actual:	/
Wind Direction:	0°		Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg		Temperature/Dew Point:	21°C
Precipitation and Obscuration:	No Obscuration	on; No Precipita	tion	
Departure Point:	KOTZEBUE	(OTZ)	Type of Flight Plan Filed:	VFR
Destination:			Type of Clearance:	None
Departure Time:	00:00 Local		Type of Airspace:	Class G

Page 4 of 6 ANC83FA095

Airport Information

Airport:	RED DOG	Runway Surface Type:	Dirt
Airport Elevation:	900 ft msl	Runway Surface Condition:	Dry
Runway Used:	21	IFR Approach:	None
Runway Length/Width:	5000 ft / 100 ft	VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	67.570564,-163.000854(est)

Page 5 of 6 ANC83FA095

Administrative Information

Investigator In Charge (IIC):	Kobelnyk, George
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=4029

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC83FA095