



Aviation Investigation Final Report

Location:	MERCER ISLAND, Washington	Accident Number:	SEA88LA092
Date & Time:	May 10, 1988, 14:00 Local	Registration:	N1701R
Aircraft:	CESSNA 185	Aircraft Damage:	Substantial
Defining Event:		Injuries:	1 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

THE PILOT STATED THAT THE AIRCRAFT STRUCK A LOG WHILE LANDING ON THE WATER. THE AIRCRAFT THEN NOSED OVER INVERTED AND SANK.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

Findings

Occurrence #1: ON GROUND/WATER COLLISION WITH OBJECT
Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (C) OBJECT - SUBMERGED OBJECT
 2. (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA - ENCOUNTERED - PILOT IN COMMAND
-

Occurrence #2: NOSE OVER
Phase of Operation: LANDING - FLARE/TOUCHDOWN

Factual Information

Pilot Information

Certificate:	Private	Age:	40, Male
Airplane Rating(s):	Single-engine land; Single-engine sea	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical--no waivers/lim.	Last FAA Medical Exam:	February 15, 1988
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1661 hours (Total, all aircraft), 136 hours (Total, this make and model), 1642 hours (Pilot In Command, all aircraft), 60 hours (Last 90 days, all aircraft), 8 hours (Last 24 hours, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	CESSNA	Registration:	N1701R
Model/Series:	185 185	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	18502324
Landing Gear Type:	Float	Seats:	6
Date/Type of Last Inspection:	May 2, 1988 Annual	Certified Max Gross Wt.:	3320 lbs
Time Since Last Inspection:		Engines:	1 Reciprocating
Airframe Total Time:	1600 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	IO-520-D
Registered Owner:	DON A. BUCKNER	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	25 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	21°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	SEATTLE , WA (BFI)	Type of Flight Plan Filed:	None
Destination:	LAKE WASHINGTON, WA	Type of Clearance:	None
Departure Time:	13:45 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	Water
Airport Elevation:	0 ft msl	Runway Surface Condition:	Water-calm
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	Full stop

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 None	Latitude, Longitude:	47.56097,-122.220634(est)

Administrative Information

Investigator In Charge (IIC):	Carrera, Candace
Additional Participating Persons:	MIKE KELLEY; SEATTLE , WA
Original Publish Date:	February 28, 1989
Last Revision Date:	
Investigation Class:	Class
Note:	
Investigation Docket:	https://data.nts.gov/Docket?ProjectID=40815

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).