



Aviation Investigation Final Report

Location: PORT TOWNSEND, Washington Accident Number: SEA89LA037

Date & Time: January 22, 1989, 13:00 Local Registration: N2582F

Aircraft: CHAMPION 7ECA Aircraft Damage: Substantial

Defining Event: 2 None

Flight Conducted Under: Part 91: General aviation - Personal

Analysis

THE PLT SIDE-SLIPPED THE AIRPLANE DURING THE LANDING APPROACH. A SINK RATE DEVELOPED WHICH THE PLT WAS UNABLE TO ARREST WITH POWER AND FLARE. THE AIRPLANE WAS LANDED HARD.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: IMPROPER APPROACH AND FLARE TECHNIQUE ON THE PART OF THE PILOT, RESULTING IN A HARD LANDING. CONTRIBUTING TO THE ACCIDENT WERE TALL TREES SURROUNDING THE AIRSTRIP.

Findings

Occurrence #1: HARD LANDING

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings

1. (F) TERRAIN CONDITION - HIGH OBSTRUCTION(S)

2. (C) AIRCRAFT HANDLING - NOT PERFORMED - PILOT IN COMMAND

3. (C) FLARE - IMPROPER - PILOT IN COMMAND

Occurrence #2: MAIN GEAR COLLAPSED

Phase of Operation: LANDING - FLARE/TOUCHDOWN

Findings 4. LANDING GEAR, MAIN GEAR - OVERLOAD

Page 2 of 5 SEA89LA037

Factual Information

Pilot Information

Certificate:	Private	Age:	40,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Unknown Unknown	Last FAA Medical Exam:	June 10, 1988
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	255 hours (Total, all aircraft), 128 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	CHAMPION	Registration:	N2582F
Model/Series:	7ECA 7ECA	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Aerobatic	Serial Number:	213
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	July 2, 1988 Annual	Certified Max Gross Wt.:	1650 lbs
Time Since Last Inspection:	24 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	2150 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Installed, activated, did not aid in locating accident	Engine Model/Series:	O-320-A1B
Registered Owner:	JAMES L. NODELL	Rated Power:	150 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 SEA89LA037

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PAE ,606 ft msl	Distance from Accident Site:	22 Nautical Miles
Observation Time:	12:45 Local	Direction from Accident Site:	90°
Lowest Cloud Condition:	Scattered / 600 ft AGL	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	4 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	260°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	3°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:		Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	12:50 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	Grass/turf
Airport Elevation:	400 ft msl	Runway Surface Condition:	Wet
Runway Used:	36	IFR Approach:	
Runway Length/Width:	4350 ft / 80 ft	VFR Approach/Landing:	Full stop;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	48.030605,-122.840065(est)

Page 4 of 5 SEA89LA037

Administrative Information

Investigator In Charge (IIC): Daily jr., H.

Additional Participating Persons: HAROLD HUTCHINS; SEATTLE , WA

Original Publish Date: September 28, 1990

Last Revision Date:
Investigation Class: Class

Note:
Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=40972

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 SEA89LA037