



Aviation Investigation Final Report

Location: BURNS, Oregon Accident Number: SEA90LA153

Date & Time: August 1, 1990, 14:00 Local Registration: N681M

Aircraft: PIPER PA-23-250 Aircraft Damage: Substantial

Defining Event: 1 Minor

Flight Conducted Under: Part 91: General aviation - Ferry

Analysis

THE ACFT, INACTIVE FOR 8 YEARS, WAS BEING FERRIED TO THE PILOTS FACILITIES FOR REBUILD. WHILE IN CRUISE FLT, THE RT ENG QUIT AND THE PROP WOULD NOT FEATHER. THE ACFT WOULD NOT MAINT ALT IN THAT CONFIGURATION AND THE PILOT BEGAN A FORCED LANDING, DURING WHICH THE LEFT ENG QUIT. THE ACFT IMPACTED SOFT TERRAIN, COLLAPSING THE LDG GEAR, AND DAMAGING THE LOWER FUSELAGE. THE LAST ANNUAL INSPECTION WAS IN 1982. THE FEERY PERMIT ISSUED FOR THE FLT EXPIRED 2 WEEKS BEFORE THE FLT. A FUEL TANK WAS CHANGED BEFORE THE FLT & THE PILOT APPLIED TAPE ON THE FILLER CAP. POST ACCIDENT EXAM OF THE ACFT FUEL SYSTEM REVEALED THE LEFT FUEL TANKS WERE EMPTY AND THE RT OUTBOARD TANK LINE WAS BLOCKED. THE RT OUTBOARD TANK WAS SELECTED WHEN THE RT ENG QUIT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: LOSS OF ENGINE POWER DUE TO A BLOCKED FUEL LINE AND THE OPERATION OF THE AIRCRAFT IN AN NON-AIRWORTHY CONDITION BY THE PIC.

Findings

Occurrence #1: LOSS OF ENGINE POWER(TOTAL) - NONMECHANICAL

Phase of Operation: CRUISE - NORMAL

Findings

1. 2 ENGINES

2. (C) FUEL SYSTEM, LINE - BLOCKED (PARTIAL)

3. (C) MAINTENANCE, INSPECTION - NOT PERFORMED - PILOT IN COMMAND

Occurrence #2: FORCED LANDING Phase of Operation: DESCENT

Findings

4. (C) PROPELLER SYSTEM/ACCESSORIES, FEATHERING SYSTEM - INOPERATIVE

Occurrence #3: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: DESCENT - EMERGENCY

Page 2 of 5 SEA90LA153

Factual Information

Pilot Information

Certificate:	Commercial	Age:	56,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	May 30, 1990
Occupational Pilot:	No	Last Flight Review or Equivalent:	
Flight Time:	3000 hours (Total, all aircraft), 4 hours (Total, this make and model)		

Aircraft and Owner/Operator Information

Aircraft Make:	PIPER	Registration:	N681M
Model/Series:	PA-23-250 PA-23-250	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	27-20
Landing Gear Type:	Retractable - Tricycle	Seats:	5
Date/Type of Last Inspection:	June 28, 1990 Unknown	Certified Max Gross Wt.:	4800 lbs
Time Since Last Inspection:	4 Hrs	Engines:	2 Reciprocating
Airframe Total Time:	4616 Hrs	Engine Manufacturer:	LYCOMING
ELT:	Not installed	Engine Model/Series:	O-540-A1B5
Registered Owner:	DORTHEA M. SMITH	Rated Power:	250 Horsepower
Operator:	ROBERT M. BRIGGS	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Page 3 of 5 SEA90LA153

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	BNO ,4141 ft msl	Distance from Accident Site:	9 Nautical Miles
Observation Time:	15:49 Local	Direction from Accident Site:	360°
Lowest Cloud Condition:	Clear	Visibility	40 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots / 17 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	300°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	30°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ition	
Departure Point:	HERMISTON , OR (S22)	Type of Flight Plan Filed:	None
Destination:	JACKSON , CA (070)	Type of Clearance:	None
Departure Time:	12:00 Local	Type of Airspace:	Class G

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:	0 ft msl	Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:	0 ft / 0 ft	VFR Approach/Landing:	Forced landing

Wreckage and Impact Information

Crew Injuries:	1 Minor	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Minor	Latitude, Longitude:	43.590663,-118.889244(est)

Page 4 of 5 SEA90LA153

Administrative Information

Investigator In Charge (IIC): Mangum, Prentiss

Additional Participating Persons: GORDON READ; HILLSBORO, OR

Original Publish Date: November 9, 1992

Last Revision Date: Investigation Class: Class

Note: Investigation Docket: https://data.ntsb.gov/Docket?ProjectID=41255

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 5 of 5 SEA90LA153