



# **Aviation Investigation Final Report**

Location: BARROW, Alaska Accident Number: ANC83LA158

Date & Time: September 1, 1983, 14:15 Local Registration: N5147G

Aircraft: de Havilland DHC-2, MK-1 Aircraft Damage: Substantial

**Defining Event:** 5 None

Flight Conducted Under: Part 135: Air taxi & commuter - Non-scheduled

## **Analysis**

THE ACFT COLLIDED WITH A DITCH DURING LANDING. THE SANDBAR USED FOR LANDING HAD A LIGHT COVERING OF SNOW AND A DITCH WASOBSCURED BY THE SNOW. DURING LANDING ROLLOUT THE ACFT COLLIDED WITH THE DITCH AND ONE OF THE MAIN LANDING GEAR COLLAPSED. NO MECHANICAL MALFUNCTIONS WERE INVOLVED IN THIS ACCIDENT.

## **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be:

#### **Findings**

Occurrence #1: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: LANDING - ROLL

#### **Findings**

1. (F) TERRAIN CONDITION - SNOW COVERED

- (C) UNSUITABLE TERRAIN OR TAKEOFF/LANDING/TAXI AREA NOT IDENTIFIED PILOT IN COMMAND
- 3. (C) INFORMATION INSUFFICIENT PILOT IN COMMAND
- 4. (F) TERRAIN CONDITION HIDDEN OBSTRUCTION(S)
- 5. (F) TERRAIN CONDITION DITCH

------

Occurrence #2: MAIN GEAR COLLAPSED Phase of Operation: LANDING - ROLL

Findings
6. (F) LANDING GEAR, NOSE GEAR ASSEMBLY - OVERLOAD

Page 2 of 6 ANC83LA158

# **Factual Information**

### **Pilot Information**

Certificate:	Airline transport	Age:	43,Male
Airplane Rating(s):	Single-engine land; Single-engine sea; Multi-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):		Restraint Used:	
Instrument Rating(s):	Airplane	Second Pilot Present:	No
Instructor Rating(s):	Airplane single-engine; Instrument airplane	Toxicology Performed:	No
Medical Certification:	Class 1 Valid Medical-no waivers/lim.	Last FAA Medical Exam:	July 19, 1983
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	5448 hours (Total, all aircraft), 38 hours (Total, this make and model), 5053 hours (Pilot In Command, all aircraft), 209 hours (Last 90 days, all aircraft), 8 hours (Last 24 hours, all aircraft)		

Page 3 of 6 ANC83LA158

## **Aircraft and Owner/Operator Information**

Aircraft Make:	de Havilland	Registration:	N5147G
Model/Series:	DHC-2, MK-1 DHC-2, MK-	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	373FM187L
Landing Gear Type:	Tailwheel	Seats:	5
Date/Type of Last Inspection:	September 27, 1982 100 hour	Certified Max Gross Wt.:	5100 lbs
Time Since Last Inspection:	79 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	7138 Hrs	Engine Manufacturer:	P&W
ELT:	Installed, not activated	Engine Model/Series:	R985-AN14B
Registered Owner:	CAPE SMYTHE AIR SERVICE, INC.	Rated Power:	
Operator:		Operating Certificate(s) Held:	On-demand air taxi (135)
Operator Does Business As:		Operator Designator Code:	

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Unknown	Visibility	10 miles
Lowest Ceiling:	Broken / 1500 ft AGL	Visibility (RVR):	
Wind Speed/Gusts:	8 knots / 15 knots	Turbulence Type Forecast/Actual:	/
Wind Direction:	270°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	-4°C
Precipitation and Obscuration:	N/A - Blowing - Snow		
Departure Point:	BARROW , AK (BRW )	Type of Flight Plan Filed:	VFR
Destination:		Type of Clearance:	None
Departure Time:	11:56 Local	Type of Airspace:	Class G

Page 4 of 6 ANC83LA158

## **Airport Information**

Airport:	UMIAT UMT	Runway Surface Type:	Gravel;Snow
Airport Elevation:	500 ft msl	<b>Runway Surface Condition:</b>	Snow
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	Full stop;Straight-in

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	4 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	5 None	Latitude, Longitude:	71.279472,-156.779556(est)

Page 5 of 6 ANC83LA158

#### **Administrative Information**

Investigator In Charge (IIC):	Mickle, Ronald
Additional Participating Persons:	
Original Publish Date:	
Last Revision Date:	
Investigation Class:	<u>Class</u>
Note:	
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=4161

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 ANC83LA158