

# **Aviation Investigation Final Report**

Location:	SIDNEY, Montana		Accident Number:	SEA94LA056
Date & Time:	January 22, 1994, 12:00	Local	<b>Registration:</b>	N95900
Aircraft:	TAYLORCRAFT	BC12-D	Aircraft Damage:	Substantial
Defining Event:			Injuries:	2 None
Flight Conducted Under:	Part 91: General aviation	- Personal		

### **Analysis**

THE PILOT REPORTED THAT AFTER LANDING ON RUNWAY 28, A GUST OF WIND LIFTED THE AIRPLANE AIRBORNE. THE AIRPLANE TOUCHED DOWN AGAIN AND VEERED TO THE LEFT. THE AIRPLANE TRAVELLED OFF THE EDGE OF THE RUNWAY AND COLLIDED WITH A SNOWBANK, COMING TO REST INVERTED.

### **Probable Cause and Findings**

The National Transportation Safety Board determines the probable cause(s) of this accident to be: THE PILOT'S INADEQUATE COMPENSATION FOR THE CROSSWIND RESULTING IN LOSS OF DIRECTIONAL CONTROL.

#### **Findings**

Occurrence #1: LOSS OF CONTROL - ON GROUND/WATER Phase of Operation: LANDING - ROLL

Findings

1. WEATHER CONDITION - CROSSWIND

2. (C) COMPENSATION FOR WIND CONDITIONS - INADEQUATE - PILOT IN COMMAND

3. DIRECTIONAL CONTROL - NOT MAINTAINED - PILOT IN COMMAND

-----

Occurrence #2: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER Phase of Operation: LANDING - ROLL

Findings 4. TERRAIN CONDITION - SNOWBANK

Occurrence #3: NOSE OVER Phase of Operation: LANDING - ROLL

### **Factual Information**

On January 22, 1994, at 1200 mountain standard time, a Taylorcraft BC12-D, N95900, collided with a snow bank and nosed over at the Sidney Airport, Sidney, Montana. Visual meteorological conditions prevailed at the time and no flight plan was filed. The airplane was substantially damaged and the private pilot and his passenger were not injured. The flight had originated from Culbertson, Montana, on January 22, 1994, at 1130, for the pleasure flight.

The pilot reported that after landing on runway 28, a gust of wind lifted the airplane into the air. The airplane touched down again and veered to the left. The airplane travelled off the side of the runway and collided with a snow bank, coming to rest inverted.

The accident was not reported until February 3, 1994.

#### **Pilot Information**

Certificate:	Private	Age:	48,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 3 Valid Medicalno waivers/lim.	Last FAA Medical Exam:	August 31, 1993
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	800 hours (Total, all aircraft), 200 hours (Total, this make and model)		

### Aircraft and Owner/Operator Information

Aircraft Make:	TAYLORCRAFT	Registration:	N95900
Model/Series:	BC12-D BC12-D	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Normal	Serial Number:	8200
Landing Gear Type:	Tailwheel	Seats:	2
Date/Type of Last Inspection:	May 30, 1984 Annual	Certified Max Gross Wt.:	1200 lbs
Time Since Last Inspection:	247 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1752 Hrs	Engine Manufacturer:	CONTINENTAL
ELT:	Installed, not activated	Engine Model/Series:	A-65-8F
Registered Owner:	LIFTO, PATRICK J.	Rated Power:	65 Horsepower
Operator:	LIFTO, PATRICK J.	Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

## Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:		Distance from Accident Site:	209
Observation Time:		Direction from Accident Site:	
Lowest Cloud Condition:	Clear	Visibility	30 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	10 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	190°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:		Temperature/Dew Point:	-4°C
Precipitation and Obscuration:			
Departure Point:	CULBERTSON , MT (S85)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	11:30 Local	Type of Airspace:	Class G

## **Airport Information**

Airport:	SIDNEY SDY	Runway Surface Type:	Asphalt
Airport Elevation:	1984 ft msl	<b>Runway Surface Condition:</b>	Dry
Runway Used:	28	IFR Approach:	None
Runway Length/Width:	4222 ft / 100 ft	VFR Approach/Landing:	Traffic pattern

## Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	1 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	2 None	Latitude, Longitude:	47.750083,-104.280769(est)

#### **Administrative Information**

Investigator In Charge (IIC):	Eckrote, Debra	
Additional Participating Persons:	LIEGH ASLAKSON; HELENA , MT	
Original Publish Date:	December 2, 1994	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=41872	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available <u>here</u>.