



# Aviation Investigation Final Report

<b>Location:</b>	ROBERTS, Idaho	<b>Accident Number:</b>	SEA95LA154
<b>Date &amp; Time:</b>	July 17, 1995, 08:15 Local	<b>Registration:</b>	N4326S
<b>Aircraft:</b>	AIR TRACTOR AT-301	<b>Aircraft Damage:</b>	Substantial
<b>Defining Event:</b>		<b>Injuries:</b>	1 None
<b>Flight Conducted Under:</b>	Part 91: General aviation - Positioning		

## Analysis

THE PILOT REPORTED THAT SHORTLY AFTER TAKEOFF, AT 40 FEET ABOVE GROUND LEVEL, THE ENGINE LOST POWER AND BEGAN BACKFIRING. THE PILOT MADE A FORCED LANDING IN A BARLEY FIELD WITH 3-FOOT-TALL CROPS, AND THE AIRPLANE CARTWHEELED. POSTACCIDENT EXAMINATION OF THE ENGINE REVEALED THAT THE EXHAUST VALVE ROCKER ARM HOUSING ON THE NUMBER 3 CYLINDER SEPARATED, DISABLING THE NUMBER 3 CYLINDER EXHAUST VALVE.

## Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: A LOSS OF ENGINE POWER DUE TO THE SEPARATION OF THE NUMBER 3 CYLINDER EXHAUST VALVE ROCKER ARM SHAFT FROM THE CYLINDER HEAD, WHICH DISABLED MOVEMENT OF THE EXHAUST VALVE. A FACTOR WAS THE LACK OF SUITABLE TERRAIN FOR THE FORCED LANDING.

## Findings

Occurrence #1: LOSS OF ENGINE POWER(PARTIAL) - MECH FAILURE/MALF  
Phase of Operation: TAKEOFF - INITIAL CLIMB

### Findings

1. (C) ENGINE ASSEMBLY,ROCKER ARM/TAPPET - SEPARATION
2. (C) ENGINE ASSEMBLY,VALVE,EXHAUST - DISABLED

-----

Occurrence #2: FORCED LANDING

Phase of Operation: EMERGENCY LANDING AFTER TAKEOFF

-----

Occurrence #3: ON GROUND/WATER ENCOUNTER WITH TERRAIN/WATER

Phase of Operation: EMERGENCY LANDING AFTER TAKEOFF

Findings

3. (F) TERRAIN CONDITION - NONE SUITABLE

4. TERRAIN CONDITION - CROP

## Factual Information

On July 17, 1995, at 0815 mountain daylight time, an Air Tractor 301, N4326S, owned by Lewis Flying Service, Inc., a 14 CFR 137 agricultural aircraft operator certificate holder, received substantial damage in a forced landing following a loss of engine power on takeoff from the pilot's private airstrip near Roberts, Idaho. The commercial pilot, a co-owner of the single-seat agricultural aircraft, was not injured. The flight was a 14 CFR 91 positioning flight to Rigby, Idaho. Visual meteorological conditions existed and no flight plan had been filed.

The pilot stated in his report on the accident: "During climb- out at approx[imately] 40 foot altitude engine lost power and [began] backfiring. All terrain (360 deg) was cultivated fields with near mature crops...Established glide into barley field - 3 foot tall crop...attempted soft-field landing. Wheels contacted barley; aircraft immediately pitched over and cartwheeled on left wing..."

A post-accident inspection of the Pratt & Whitney R-1340-AN1 radial engine revealed that the boss securing the exhaust valve rocker arm shaft to the number 3 cylinder head had separated from the cylinder head, allowing the entire rocker arm to move freely rather than pivot. This failure prevented the number 3 cylinder's exhaust valve from opening during engine operation. No other evidence of engine damage or malfunction was noted.

According to the accident report and copies of the aircraft and engine logs submitted by the airplane's owner, the engine had been operated 201.3 hours since the airplane's last inspection (an annual inspection conducted on April 7, 1995), and 233.8 hours since its last overhaul. The engine was installed on the airplane at zero time since overhaul on August 7, 1994 according to the engine log.

The FAA publication, "General Aviation Airworthiness Alerts" (AC 43-16), December 1995 issue, which the FAA distributes to FAA- certificated Inspection Authorization (IA) airframe and powerplant mechanics, contained an advisory for cylinder cracks on Pratt & Whitney model R-1340 engines. The advisory reported: "After receiving reports from three engine overhaul shops concerning cracks in the cylinder exhaust rocker shaft housing area, an investigation and interviews suggest this may be a systematic problem. Two repair stations stated they reject approximately 3 percent of the cylinders passing through their shops for this type defect. The defects in the exhaust rocker shaft housings range from slight cracking to complete separation of the housing above the rocker shaft....The Service Difficulty Reporting (SDR) data base revealed 42 similar reports, and 7 others which may have been related to this topic....the exact cause for cracking in this area has not been determined...Since the rocker shaft uses an 'O-ring' seal under each of the nuts, it is possible that when oil seepage is found, the nuts are tightened beyond the torque limits established by the manufacturer's maintenance manual....It is also possible that thermal expansion and contraction...may result in this type defect....It

would be wise to pay close attention to this area during scheduled inspections."

### Pilot Information

<b>Certificate:</b>	Commercial	<b>Age:</b>	50, Male
<b>Airplane Rating(s):</b>	Single-engine land	<b>Seat Occupied:</b>	Center
<b>Other Aircraft Rating(s):</b>	None	<b>Restraint Used:</b>	
<b>Instrument Rating(s):</b>	Airplane	<b>Second Pilot Present:</b>	No
<b>Instructor Rating(s):</b>	Airplane single-engine	<b>Toxicology Performed:</b>	No
<b>Medical Certification:</b>	Class 2 Valid Medical--w/ waivers/lim	<b>Last FAA Medical Exam:</b>	April 28, 1995
<b>Occupational Pilot:</b>	Yes	<b>Last Flight Review or Equivalent:</b>	
<b>Flight Time:</b>	8554 hours (Total, all aircraft), 3301 hours (Total, this make and model), 8433 hours (Pilot In Command, all aircraft), 220 hours (Last 90 days, all aircraft), 100 hours (Last 30 days, all aircraft), 8 hours (Last 24 hours, all aircraft)		

### Aircraft and Owner/Operator Information

<b>Aircraft Make:</b>	AIR TRACTOR	<b>Registration:</b>	N4326S
<b>Model/Series:</b>	AT-301 AT-301	<b>Aircraft Category:</b>	Airplane
<b>Year of Manufacture:</b>		<b>Amateur Built:</b>	
<b>Airworthiness Certificate:</b>	Restricted (Special)	<b>Serial Number:</b>	301-0006
<b>Landing Gear Type:</b>	Tailwheel	<b>Seats:</b>	1
<b>Date/Type of Last Inspection:</b>	April 7, 1995 Annual	<b>Certified Max Gross Wt.:</b>	5000 lbs
<b>Time Since Last Inspection:</b>	202 Hrs	<b>Engines:</b>	1 Reciprocating
<b>Airframe Total Time:</b>	7174 Hrs	<b>Engine Manufacturer:</b>	P&W
<b>ELT:</b>	Not installed	<b>Engine Model/Series:</b>	R-1340-AN1
<b>Registered Owner:</b>	LEWIS, ORLIN & JULIA	<b>Rated Power:</b>	600 Horsepower
<b>Operator:</b>		<b>Operating Certificate(s) Held:</b>	
<b>Operator Does Business As:</b>	LEWIS FLYING SERVICE	<b>Operator Designator Code:</b>	HNBG

## Meteorological Information and Flight Plan

<b>Conditions at Accident Site:</b>	Visual (VMC)	<b>Condition of Light:</b>	Day
<b>Observation Facility, Elevation:</b>	IDA ,4740 ft msl	<b>Distance from Accident Site:</b>	12 Nautical Miles
<b>Observation Time:</b>	07:45 Local	<b>Direction from Accident Site:</b>	160°
<b>Lowest Cloud Condition:</b>	Clear	<b>Visibility</b>	60 miles
<b>Lowest Ceiling:</b>	None	<b>Visibility (RVR):</b>	
<b>Wind Speed/Gusts:</b>	5 knots /	<b>Turbulence Type Forecast/Actual:</b>	/
<b>Wind Direction:</b>	350°	<b>Turbulence Severity Forecast/Actual:</b>	/
<b>Altimeter Setting:</b>	30 inches Hg	<b>Temperature/Dew Point:</b>	14°C / 9°C
<b>Precipitation and Obscuration:</b>	No Obscuration; No Precipitation		
<b>Departure Point:</b>		<b>Type of Flight Plan Filed:</b>	None
<b>Destination:</b>	RIGBY , ID (U56 )	<b>Type of Clearance:</b>	None
<b>Departure Time:</b>	00:00 Local	<b>Type of Airspace:</b>	Class G

## Airport Information

<b>Airport:</b>		<b>Runway Surface Type:</b>	
<b>Airport Elevation:</b>		<b>Runway Surface Condition:</b>	
<b>Runway Used:</b>	0	<b>IFR Approach:</b>	
<b>Runway Length/Width:</b>		<b>VFR Approach/Landing:</b>	Forced landing

## Wreckage and Impact Information

<b>Crew Injuries:</b>	1 None	<b>Aircraft Damage:</b>	Substantial
<b>Passenger Injuries:</b>		<b>Aircraft Fire:</b>	None
<b>Ground Injuries:</b>	N/A	<b>Aircraft Explosion:</b>	None
<b>Total Injuries:</b>	1 None	<b>Latitude, Longitude:</b>	43.730209,-112.260932(est)

## Administrative Information

<b>Investigator In Charge (IIC):</b>	Nesemeier, Gregg
<b>Additional Participating Persons:</b>	GEORGE D CAWTHRA; SALT LAKE CITY , UT
<b>Original Publish Date:</b>	February 8, 1996
<b>Last Revision Date:</b>	
<b>Investigation Class:</b>	<a href="#">Class</a>
<b>Note:</b>	
<b>Investigation Docket:</b>	<a href="https://data.nts.gov/Docket?ProjectID=42196">https://data.nts.gov/Docket?ProjectID=42196</a>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).