



Aviation Investigation Final Report

Location:	CORVALLIS, Oregon	Accident Number:	SEA95LA204
Date & Time:	September 4, 1995, 12:05 Local	Registration:	N8865K
Aircraft:	STINSON 108-1	Aircraft Damage:	Substantial
Defining Event:		Injuries:	3 None
Flight Conducted Under:	Part 91: General aviation - Personal		

Analysis

AFTER DEPARTING RUNWAY 17 THE PILOT REMAINED IN THE PATTERN FOR A TOUCH-AND-GO. UPON TOUCHDOWN AT 70 MPH, ON CENTERLINE, THE RIGHT MAIN LANDING GEAR COLLAPSED. POSTCRASH EXAMINATION REVEALED THAT THE FOUR RETAINING PINS WHICH HOLD THE RIGHT MAIN LANDING GEAR SHOCK STRUT RETAINER CAP HAD SHEARED ALLOWING THE STRUT TO SEPARATE FROM THE GEAR STRUT. NO PRE-EXISTING FATIGUE WAS OBSERVED ON THE PINS. THE AIRCRAFT HAD BEEN GROUND-LOOPED 14.3 HOURS PREVIOUS TO THIS ACCIDENT.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: SHEARING OF THE RIGHT MAIN LANDING GEAR SHOCK STRUT RETAINER CAP RETAINING PINS.

Findings

Occurrence #1: MAIN GEAR COLLAPSED
Phase of Operation: LANDING - ROLL

Findings

1. (C) LANDING GEAR,MAIN GEAR SHOCK ABSORBING STRUT - SEPARATION
2. (C) MISCELLANEOUS,DOWEL/PIN - SHEARED

Factual Information

On September 4, 1995, approximately 1205 hours Pacific daylight time, a Stinson 108-1, N8865K, sustained substantial damage when the right main landing gear collapsed during the landing roll on runway 17 at the Corvallis Municipal Airport, Corvallis, Oregon. The private pilot and two passengers were uninjured. Visual meteorological conditions existed and no flight had been filed. The flight, which was personal and local, was to have been operated under 14CFR91, and originated from Corvallis approximately 15 minutes earlier.

The pilot reported that he departed runway 17 at Corvallis and remained in the pattern with the intent of conducting a single touch-and-go landing on the same runway before departing the airport. He indicated that he flew a normal 70 mph approach and touched down on the "centerline on (the) 1000 foot square (runway fixed distance markings) (and) began (a) slight (10 degree) drift to l(eft)." He reported that the "plane responded poorly" and that the "plane lifted (the) left wing (or lowered the right wing) as (the) gear leg with (the) piston from (the) oleo lifted (the) right seat from (its) track" (refer to attached NTSB Form 6120.1/2).

The pilot also reported in a separate NASA ASRS report that inspection of the runway revealed "rubber marks from (the) wheel up the runway suggesting that the right tire was scuffing and perhaps turned inward from at or very near (the) touchdown" (refer to photograph 1).

Post crash examination revealed that the four retaining pins for the right main landing gear's shock strut retainer (cap) had sheared (refer to photograph 2). Gross examination of the pins revealed no evidence of fatigue.

The pilot reported to an FAA inspector that he had purchased the aircraft one week previous to the accident and that a total of 14.3 hours had been logged in the previous year since the time the aircraft had been previously ground looped.

Pilot Information

Certificate:	Private	Age:	62, Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Left
Other Aircraft Rating(s):	Glider	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	Yes
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medical-w/ waivers/lim	Last FAA Medical Exam:	October 17, 1994
Occupational Pilot:	UNK	Last Flight Review or Equivalent:	
Flight Time:	1212 hours (Total, all aircraft), 5 hours (Total, this make and model), 1045 hours (Pilot In Command, all aircraft), 46 hours (Last 90 days, all aircraft), 8 hours (Last 30 days, all aircraft)		

Aircraft and Owner/Operator Information

Aircraft Make:	STINSON	Registration:	N8865K
Model/Series:	108-1 108-1	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Utility	Serial Number:	108-1865
Landing Gear Type:	Tailwheel	Seats:	4
Date/Type of Last Inspection:	August 23, 1995 Annual	Certified Max Gross Wt.:	2230 lbs
Time Since Last Inspection:	5 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	1294 Hrs	Engine Manufacturer:	FRANKLIN
ELT:	Installed, not activated	Engine Model/Series:	6A4-165-BC
Registered Owner:	TAYLOR, WILLIAM, M.	Rated Power:	165 Horsepower
Operator:		Operating Certificate(s) Held:	None
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	CVO ,246 ft msl	Distance from Accident Site:	
Observation Time:	11:56 Local	Direction from Accident Site:	
Lowest Cloud Condition:	Scattered / 3100 ft AGL	Visibility	10 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	3 knots /	Turbulence Type Forecast/Actual:	/
Wind Direction:	100°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	30 inches Hg	Temperature/Dew Point:	22°C / 10°C
Precipitation and Obscuration:	No Obscuration; No Precipitation		
Departure Point:	(CVO)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	11:50 Local	Type of Airspace:	Class G

Airport Information

Airport:	CORVALLIS MUNICIPAL CVO	Runway Surface Type:	Asphalt
Airport Elevation:	246 ft msl	Runway Surface Condition:	Dry
Runway Used:	17	IFR Approach:	None
Runway Length/Width:	5065 ft / 150 ft	VFR Approach/Landing:	Touch and go;Traffic pattern

Wreckage and Impact Information

Crew Injuries:	1 None	Aircraft Damage:	Substantial
Passenger Injuries:	2 None	Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	3 None	Latitude, Longitude:	44.460475,-123.34011(est)

Administrative Information

Investigator In Charge (IIC): McCreary, Steven

Additional Participating Persons: LOU SANDERS; HILLSBORO , OR

Original Publish Date: February 14, 1996

Last Revision Date:

Investigation Class: [Class](#)

Note:

Investigation Docket: <https://data.nts.gov/Docket?ProjectID=42240>

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, “accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person” (Title 49 *Code of Federal Regulations* section 831.4). Assignment of fault or legal liability is not relevant to the NTSB’s statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 *United States Code* section 1154(b)). A factual report that may be admissible under 49 *United States Code* section 1154(b) is available [here](#).