





Aviation Investigation Final Report

Location: PULLMAN, Washington Accident Number: SEA96LA159

Date & Time: July 16, 1996, 06:45 Local Registration: N9336R

Aircraft: Cessna A188B Aircraft Damage: Substantial

Defining Event: 1 Serious

Flight Conducted Under: Part 137: Agricultural

Analysis

The pilot stated that he was spraying a field to the north and south with a light wind from the northwest and wind shear from different directions. He reported that as he was spraying south toward a small ridge, the airplane suddenly settled. The airplane collided with terrain, just below the top of a ridge, then it bounced and became airborne. The pilot tried to recover; however, the engine was no longer responding. The airplane then stalled and again collided with the terrain, flat on its belly. The pilot reported that there was no mechanical failure or malfunction with the airplane at the time of the accident.

Probable Cause and Findings

The National Transportation Safety Board determines the probable cause(s) of this accident to be: failure of the pilot to maintain terrain clearance during a swath run. Factors relating to the accident were: unfavorable (variable) wind conditions, low airspeed, and uneven terrain.

Findings

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER Phase of Operation: MANEUVERING - AERIAL APPLICATION

Findings

- 1. (F) WEATHER CONDITION UNFAVORABLE WIND
- 2. (F) WEATHER CONDITION VARIABLE WIND
- 3. (F) AIRSPEED LOW PILOT IN COMMAND

- 4. (F) TERRAIN CONDITION ROUGH/UNEVEN
 5. (C) CLEARANCE NOT MAINTAINED PILOT IN COMMAND

Page 2 of 6 SEA96LA159

Factual Information

On July 16, 1996, at 0645 Pacific daylight time, a Cessna A188B, N9336R, registered to and operated by the pilot as a 14 CFR Part 137 aerial application flight, collided with the terrain while maneuvering near Pullman, Washington. Visual meteorological conditions prevailed at the time and no flight plan was filed for the local flight. The airplane was substantially damaged and the commercial pilot, the sole occupant, was seriously injured. The flight had departed from Pullman approximately ten minutes prior to the accident.

In a written statement, the pilot reported that he was spraying an insecticide north and south over a pea field with a light wind from the northwest, and wind shear conditions from different directions. The pilot stated that he began a spray run to the south, toward a small ridge, when that the airplane suddenly settled to the ground and the airplane collided with the ridge just below the top. The airplane bounced and became airborne. The pilot tried to recover, however, the engine was no longer responding. The pilot stated that the airplane "stalled" and again collided with the terrain flat on its belly.

After the accident, the pilot reported that there were no mechanical failures or malfunctions with the airplane at the time of the accident.

Pilot Information

Certificate:	Commercial	Age:	56,Male
Airplane Rating(s):	Single-engine land	Seat Occupied:	Front
Other Aircraft Rating(s):	None	Restraint Used:	
Instrument Rating(s):	None	Second Pilot Present:	No
Instructor Rating(s):	None	Toxicology Performed:	No
Medical Certification:	Class 2 Valid Medicalw/ waivers/lim	Last FAA Medical Exam:	April 1, 1996
Occupational Pilot:	Yes	Last Flight Review or Equivalent:	
Flight Time:	2800 hours (Total, all aircraft), 800 hours (Total, this make and model), 2700 hours (Pilot In Command, all aircraft), 350 hours (Last 90 days, all aircraft), 105 hours (Last 30 days, all aircraft), 5 hours (Last 24 hours, all aircraft)		

Page 3 of 6 SEA96LA159

Aircraft and Owner/Operator Information

Aircraft Make:	Cessna	Registration:	N9336R
Model/Series:	A188B A188B	Aircraft Category:	Airplane
Year of Manufacture:		Amateur Built:	
Airworthiness Certificate:	Restricted (Special)	Serial Number:	18802243T
Landing Gear Type:	Tailwheel	Seats:	1
Date/Type of Last Inspection:	March 31, 1996 Annual	Certified Max Gross Wt.:	3300 lbs
Time Since Last Inspection:	400 Hrs	Engines:	1 Reciprocating
Airframe Total Time:	4400 Hrs	Engine Manufacturer:	Lycoming
ELT:	Not installed	Engine Model/Series:	IO-540-S1A5
Registered Owner:	SAGER, ARTHUR W.	Rated Power:	300 Horsepower
Operator:		Operating Certificate(s) Held:	
Operator Does Business As:		Operator Designator Code:	

Meteorological Information and Flight Plan

Conditions at Accident Site:	Visual (VMC)	Condition of Light:	Day
Observation Facility, Elevation:	PUW ,2551 ft msl	Distance from Accident Site:	7 Nautical Miles
Observation Time:	06:45 Local	Direction from Accident Site:	90°
Lowest Cloud Condition:	Clear	Visibility	20 miles
Lowest Ceiling:	None	Visibility (RVR):	
Wind Speed/Gusts:	/	Turbulence Type Forecast/Actual:	/
Wind Direction:	0°	Turbulence Severity Forecast/Actual:	/
Altimeter Setting:	29 inches Hg	Temperature/Dew Point:	18°C / 8°C
Precipitation and Obscuration:	No Obscuration; No Precipita	ation	
Departure Point:	PULLMAN, WA (PUW)	Type of Flight Plan Filed:	None
Destination:		Type of Clearance:	None
Departure Time:	06:35 Local	Type of Airspace:	Class G

Page 4 of 6 SEA96LA159

Airport Information

Airport:		Runway Surface Type:	
Airport Elevation:		Runway Surface Condition:	
Runway Used:	0	IFR Approach:	None
Runway Length/Width:		VFR Approach/Landing:	None

Wreckage and Impact Information

Crew Injuries:	1 Serious	Aircraft Damage:	Substantial
Passenger Injuries:		Aircraft Fire:	None
Ground Injuries:	N/A	Aircraft Explosion:	None
Total Injuries:	1 Serious	Latitude, Longitude:	46.66954,-117.959327(est)

Page 5 of 6 SEA96LA159

Administrative Information

Investigator In Charge (IIC):	Eckrote, Debra	
Additional Participating Persons:	LES EDMONDS; SPOKANE , WA	
Original Publish Date:	May 23, 1997	
Last Revision Date:		
Investigation Class:	<u>Class</u>	
Note:		
Investigation Docket:	https://data.ntsb.gov/Docket?ProjectID=42421	

The National Transportation Safety Board (NTSB) is an independent federal agency charged by Congress with investigating every civil aviation accident in the United States and significant events in other modes of transportation—railroad, transit, highway, marine, pipeline, and commercial space. We determine the probable causes of the accidents and events we investigate, and issue safety recommendations aimed at preventing future occurrences. In addition, we conduct transportation safety research studies and offer information and other assistance to family members and survivors for each accident or event we investigate. We also serve as the appellate authority for enforcement actions involving aviation and mariner certificates issued by the Federal Aviation Administration (FAA) and US Coast Guard, and we adjudicate appeals of civil penalty actions taken by the FAA.

The NTSB does not assign fault or blame for an accident or incident; rather, as specified by NTSB regulation, "accident/incident investigations are fact-finding proceedings with no formal issues and no adverse parties ... and are not conducted for the purpose of determining the rights or liabilities of any person" (Title 49 Code of Federal Regulations section 831.4). Assignment of fault or legal liability is not relevant to the NTSB's statutory mission to improve transportation safety by investigating accidents and incidents and issuing safety recommendations. In addition, statutory language prohibits the admission into evidence or use of any part of an NTSB report related to an accident in a civil action for damages resulting from a matter mentioned in the report (Title 49 United States Code section 1154(b)). A factual report that may be admissible under 49 United States Code section 1154(b) is available here.

Page 6 of 6 SEA96LA159